


1. Approving Civil Aviation Authority/Country		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number: WO151165	
4. Organization Name and Address: Transport Canada AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: T42644	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Battery Charger	4-254-04	1.00	C5541	REPAIRED
12. REMARKS UNIT CLEANED, REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 24-31-04, REVISION NUMBER 18, DATED AUG 12/2022. FOR MORE INFORMATION REFER TO MAINTENANCE REPORT.					
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12			
13b. Signature:		13c. Approved Organization Number		14c. Approval Organization Number 33-12	
13d. Name (Typed or Printed):		13e. Date		14d. Name (Typed or Printed) Hassan Boudemlij 14e. Date (dd/mm/yyyy) 30/Nov/2023	
Installer Responsibilities					
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

AJW. TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO151165
Date Printed: 11/30/2023
Customer RO: T42644
Page: 1

To:
A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: Battery Charger

P/N: 4-254-04

Qty: 1

Phone:

S/N: C5541

Mfg: ELDEC CORPORATION

Email:

CSO: N/A

CSR: N/A

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

Serial Out: C5541

P/N Out: 4-254-04



Symptoms:

CODE: REASON FOR REMOVAL
DETAILS: removed serviceable condition for test and recertification
ACFT: G-LSAO

Faults:

CODE: INITIAL TEST FAILURE
DETAILS: Initial test failed intermittent.

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION
DETAILS: Reason for removal is unknown (removed as is from AC: G-LSAO).

CODE: DISASSEMBLY / INSPECTION FINDINGS
DETAILS: During disassembly and inspection of the unit the following anomalies were found:
unit very dirty contaminated with dust and dirt from aircraft.
found crack soldering on terminal A5A1.

CODE: CLEANING
DETAILS: Cleaning is required due to contamination of dirt and dust.

CODE: REPAIR
DETAILS: Unit will be repaired in accordance with cmm 24-31-04.

Corrective Actions:

CODE: REPAIRED
DETAILS: UNIT CLEANED, REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 24-31-04.