




1. Approving Competent Authority/Country		2.		3. Form Tracking Number	
EASA		<b>AUTHORISED RELEASE CERTIFICATE</b> <b>EASA FORM 1</b>		ARC109234	
4. Organisation Name and Address		Oakenhurst Aircraft Services Ltd Claydons Lane Rayleigh, Essex SS6 7UP United Kingdom		5. Work Order/Contract/Invoice	
		Tel: +44 (0)1268741622 Email: sales@oakenhurst.com Web: www.oakenhurst.com		WP92596 / W52917	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	Headset	1046GT2102AY	1	571890	Repaired
12. Remarks					
Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 23-51-06 Rev 11, 14 October 2020.					
TSN: N/K, TSO: N/K, CSN: N/K, CSO: N/K, DoM: 01 Mar 2020					
13a. Certifies that the items identified above were manufactured in conformity to:		14a. <input checked="" type="checkbox"/> Part-145.A.50 Release to Service <input type="checkbox"/> Other regulation specified in block 12			
<input type="checkbox"/> Approved design data and are in condition for safe operation <input type="checkbox"/> Non-approved design data specified in block 12		14b. Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature	14c. Certificate/Approval Ref. No.		
			AVW 5	EASA.UK.145.00524	
13d. Name	13e. Date (dd mmm yyyy)	14d. Name	14e. Date (dd mmm yyyy)		
		Olivia Watkinson	12 Oct 2023		
<b>USER/INSTALLER RESPONSIBILITIES</b> This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1. Approving Competent Authority/Country		2.		<b>AUTHORISED RELEASE CERTIFICATE</b> <b>CAA FORM 1</b>		3. Form Tracking Number	
CAA / United Kingdom						ARC109235	
4. Organisation Name and Address				5. Work Order/Contract/Invoice			
<b>OAKENHURST</b>  AIRCRAFT SERVICES LTD Oakenhurst Aircraft Services Ltd Claydons Lane Rayleigh, Essex SS6 7UP United Kingdom				Tel: +44 (0)1268741622 Email: sales@oakenhurst.com Web: www.oakenhurst.com WP92596 / W52917			
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work		
1	Headset	1046GT2102AY	1	571890	Repaired		
12. Remarks The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under FAA certificate no. OSKY452Y. Work as stated in box 11 has been carried out in accordance with manufacturers manual No. 23-51-06 Rev 11, 14 October 2020.							
TSN: N/K, TSO: N/K, CSN: N/K, CSO: N/K, DoM: 01 Mar 2020							
13a. Certifies that the items identified above were manufactured in conformity to:				14a. <input checked="" type="checkbox"/> Part-145 A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12			
<input type="checkbox"/> Approved design data and are in condition for safe operation <input type="checkbox"/> Non-approved design data specified in block 12				Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature		14c. Certificate/Approval Ref. No.	
				 AVW 5		UK.145.00524	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name		14e. Date (dd mmm yyyy)	
				Olivia Watkinson		12 Oct 2023	
<b>USER/INSTALLER RESPONSIBILITIES</b> This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							



Oakenhurst Aircraft Services Ltd  
Claydons Lane  
Rayleigh, Essex  
SS6 7UP  
United Kingdom  
Tel: +44 (0)1268741622

CAA Part 145: UK.145.00524

EASA Part 145: EASA.UK.145.00524

## Completion Report

No: **WP92596**

Issue: **03**

Date: **12-Oct-23**

AJW Aviation  
The Headquarters  
Maydwell Avenue  
Slinfold  
West Sussex  
RH13 0AS  
United Kingdom

Attn: Summer Smythe

Tel: 0044 (0) 1403 798000 Fax:

E-Mail: summer.smythe@ajw-group.com

Your Ref: W52917	Our Ref: WP92596	Test Required: I.A.W. Manufacturers CMM	
Part No: 1046GT2102AY	Description: Headset	TSN: N/K	CSN: N/K
Serial No: 571890	Workscope: Audio Repair	TSO: N/K	CSO: N/K
DoM: 01-Mar-20	Overhauled:	Inspected:	
Removed From:	Serial No:	Reg No: AP-BOE	Position:

Technical Reference: LIB02520 - Issue No: N/A - Rev No: 11

### Inspection Findings:

Unit received for repair with a reported defect of 'boom mic broken'. Unit tested. Testing Passed. Unit disassembled for inspection. Inspection found the microphone arm has been damaged and worn earpads. Reported defect confirmed. Unit re-assembled. Upon approval unit requires replacement of U/S parts, cleaning, re-assembly, testing and final checks to be carried out.

History evaluation indicates that the unit was manufactured in March 2020 and is therefore within OEM warranty period. Unit has been assessed under OEM warranty terms and conditions but as the damage is customer induced warranty does not apply.

### Completion Summary:

Unit has been disassembled, replacement parts fitted, reassembled, cleaned and tested I.A.W CMM.

Signed:  Name: O WATKINSON Date: 12 OCT/2023

For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP