

AUTHORIZED RELEASE CERTIFICATE

FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

2.

1. Approving Civil Aviation
Authority/Country:

3. Form Tracking Number:

215909

CTID

1

FAA/UNITED STATES

4. Organization Name and Address:

BP Aero Services

4965 HANSON DR.

IRVING, TX 75038

USA

Ph: 469-208-0060, Fax: 972-252-2009

FAA Approval Holder: 442R874B

5. Work Order/Contract/Invoice
Number:

96082

Number of attached pages - 1

11. Status/Work:

OVERHAULED

10. Serial Number:

N/A

9. Quantity:

2

8. Part Number:

1318M23G03

6. Item 7. Description:
1 RING ASSY-ACTUATION CPRSR STTR STG 3

12. Remarks:

ATA: 72-32-11

E.S.N. 779338

Repair Order: ERO17579

Customer: AJ Walter Aviation Ltd

See Workscope Report : 96082

All work performed in accordance with CFM56-5B Manual ID: CFM1-TP-SM.9, Revision #: 79, Revision Date: 4/15/2023

Also meets the inspection criteria of:
CFM56-5C Manual ID: CFM1-TP-SM.8, Revision #: 56, Revision Date: 4/15/2022
CFM56-5A Manual ID: CFM1-TP-SM.7, Revision #: 69, Revision Date: 2/15/2023
CFM56-3 Manual ID: CFM1-TP-SM.5, Revision #: 80, Revision Date: 12/15/2022
CFM56-7B Manual ID: CFM1-TP-SM.10, Revision #: 63, Revision Date: 6/15/2022

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to Service under EASA Part 145

Approval Number: EASA 145 6427

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.☐ Non-approved design data specified in Block 1214a. ☒ 14 CFR 43.9 Return to Service☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No.:



14c. Approval/Certificate No.:

442R874B

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

Douglas Cler

14e. Date (dd/mm/yyyy):

11-Jul-2023

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1 国家 Country P.R. CHINA	2 中国民用航空总局 CAAC ☐ 符合性 Conformity	☒ 适航性 Airworthiness	3 证书编号 Certificate Ref. No. 90812			
批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG						
4 单位 BP Aero Services FAA Repair Station # 442R874B 4965 HANSON DR. IRVING, TX 75038 USA Tel: 972-252-2800, Fax: 972-252-2009	5 工作单/合同单/发票 Work Order / Contract / Invoice 96082 Number of attached pages - 1					
6 序号 Item	7 内容 Description	8 件号 Part No.	9 适用性 Eligibility	10 数量 Qty	11 系列号/批号 Serial/Batch No.	12 产品状态 Status/Work
1	RING ASSY-ACTUATION CPRSR STTR STG 3	1318M23G03	CFM56-5B	2	N/A	OVERHAULED
13 备注 Remarks ATA: 72-32-11 E.S.N. 779338 Repair Order: ERO17579 Customer: AJ Walter Aviation Ltd See Workslope Report : 96082 All work performed in accordance with CFM56-5B Manual ID: CFMI-TP-SM.9, Revision #: 79, Revision Date: 4/15/2023 Also meets the inspection criteria of: CFM56-5C Manual ID: CFMI-TP-SM.8, Revision #: 56, Revision Date: 4/15/2022 CFM56-5A Manual ID: CFMI-TP-SM.7, Revision #: 69, Revision Date: 2/15/2023 CFM56-3 Manual ID: CFMI-TP-SM.5, Revision #: 80, Revision Date: 12/15/2022 CFM56-7B Manual ID: CFMI-TP-SM.10, Revision #: 63, Revision Date: 6/15/2022						
14 新产品 New Parts 兹声明上述产品除第13项的其他规定以外, 按照上述国家适航条例进行制造、检查, 并且该产 品(出口产品)符合经批准的型号设计数据和进口国提出的专用要求。 Certifies that the part(s) identified above, except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		15 使用过的产品 Used Parts 兹声明上述产品除第13项的其他规定以外, 已按照上述国家适航条例和进口国通知的特殊要求 进行了工作。该产品出于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)				
16 批准人签名 Signature 		19 中国民航总局授权 Issued by or on behalf of the CAAC F00100709				
17 批准人姓名(打印的) Name (Printed) Douglas Cler		18 批准日期 Date Jul/11/2023				

AAC-038(12/94)

*参阅产品目录详细查找适用性
Cross-check eligibility for more details with parts catalogue

To: AJ Walter Aviation Ltd THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM		Ship To: Repairs Group THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM	
Ref #: ERO17579	Phone #: +44 1403 711 777	Fax #: +44 1403 710 936	Email: stockmarket@ajw-aviation.com
Code: 12	Site: AWAL	PN: 1318M23G03	Descr: RING ASSY-ACTUATION CPRSR S
Qty: 2	Station:	Make:	Model: Mfg: CFMI
CMM/ESM: CFMI-TP-SM.9 CFM56-5B CFMI-TP-SM.8 CFM56-5C CFMI-TP-SM.7 CFM56-5A CFMI-TP-SM.5 CFM56-3CFMI-TP-SM.10 CFM56-7B			
ESN 779338			
TSN	CSN	Complies With	
Entry Date: 6/27/2023	Need Date: 7/10/2023	Compl. Date: 7/11/2023 11:37:52 AM	Warranty: No

Serial Numbers:

Inspection Findings:

Visual / Dimensional Findings

Damaged/worn hardware

Corrective Actions:

Overhauled - 8130/CAAC Issued

Repair Performed:

72-32-11 - Replacement of hardware.

Task Description	Status	Seq
RECEIVING INSPECTION	Complete	0
CFM56-5B-ESM-TASK-72-32-11-030 - DISASSEMBLY	Complete	50
CFM56-5B-ESM-TASK-72-32-11-100-001 - CLEANING	Complete	100
CFM56-5B-ESM-TASK-72-32-11-200-001 - INSPECTION	Complete	200
CFM56-ESM-72-32-11-440-000- HARDWARE REPLACEMENT	Complete	301
PHASE II FINAL INSPECTION	Complete	399
FINAL CLEANING AND CONDITIONING	Complete	800000
FINAL INSPECTION	Complete	900000



DEC