

1. Approving National Aviation  
Authority/Country:  
**FAA/United States**

2.

**AUTHORIZED RELEASE CERTIFICATE**  
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

**205983**

4. Organization Name and Address:



615 West Knox Road  
Tempe, AZ 85284  
480-831-1268 FAX 480-831-1314

Z6AR209Y

5. Work Order/Contract/Invoice Number:

**W0077422**

6. Item:

7. Description:

**FLAP FAIRING PANEL  
ASSY**

8. Part Number:

**113T1740-156**

9. Eligibility: \*

**N/A**

10. Quantity:

**1**

11. Serial/Batch Number:

**53699**

12. Status/Work:

**REPAIRED**

13. Remarks:

**REPAIRED UNIT IAW BOEING DWC 113T1740, REV "C" DATED JUN 09/96.**

"AIR TRANSPORT COMPONENTS CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CARRIED OUT IN ACCORDANCE WITH PART-145 AND IN RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA APPROVAL CERTIFICATE NO: EASA.145.5116."

14. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation  
☐ Non-approved design data specified in Block 13

15. Authorized Signature:

16. Approval/Authorization No:

17. Name (Typed or Printed):

18. Date (m/d/y):

19. ☒ 14 CFR 43.9 Return to Service  
Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

20. Authorized Signature:

21. Approval/Certificate No:

22. Name (Typed or Printed):

**DAMIAN JOSHUA ALLEN**

23. Date (m/d/y):

**OCT/08/2013**

**User/Installer Responsibilities**

It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.



615 W. Knox Road  
Tempe, AZ 85284  
Ph: 480-831-1268

FAA Repair Station #  
Z6AR209Y  
Fx: 480-831-1314

---

COMPONENT TEARDOWN/CONDITION REPORT

---

Customer 10109    AJ WALTER AVIATION LTD.    WORK ORDER# W0077422  
Nomenclature FLAP FAIRING PANEL A    MFG    CUST-PO# 205983  
Part Number 113T1740-156    S/N 53699    A/C

Reason For Removal/Customer Instructions    Modifications/S.B/A.D Compliance  
REPAIR AS REQUIRED IAW MFG SPECS.  
DUAL RELEASE REQUIRED.

Visual Inspection Prior To Teardown:  
UNIT DIRTY. PAINT CHIPPED / WORN.

Preliminary Test Results:  
NOT REQUIRED.

Teardown And Inspection Findings:  
EPOXY WORN, REFINISH REQUIRED.

Corrective Action Taken:  
REPAIRED UNIT IAW BOEING DWG 113T1740, REV "C" DATED JUN 09/96.

Final Disposition: REPAIRED

TECH GH    GARY HANNAH    INSPECTOR JA    DAMIAN JOSHUA ALLEN    DATE OCT/08/2013

For further info contact Roy Hyde at 480-831-1268    FAX 480-831-1314

ATC009