

ANSETT A/C  
SPARES SVC

WP

1. APPROVING NATIONAL AVIATION AUTHORITY/COUNTRY: <b>FAA / UNITED STATES</b>		<b>AUTHORIZED RELEASE CERTIFICATE</b> FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: <b>13-5475</b>	
4. Organization: <b>CONSOLIDATED AIRCRAFT SUPPLY CO. INC. (631) 981-7700 800-422-6300</b> <b>55 RAYNOR AVENUE, RONKONKOMA, NEW YORK 11779 FAX: (631) 981-7706</b>						5. Work Order/Contract/Invoice Number: <b>A50008286</b>	
6. Item: <b>1</b>						7. Description: <b>HYDRAULIC FUSE</b>	
8. Part Number: <b>60B00238-12</b>						9. Eligibility: <b>N/A</b>	
10. Quantity: <b>1</b>						11. Serial/Batch Number: <b>2102382</b>	
12. Status/Work: <b>INSPECTED</b>							
13. Remarks: 1. THIS UNIT <del>OVERVIEWED/REPAIRED</del> FUNCTIONALLY TESTED IN ACCORDANCE WITH MANUFACTURER'S CURRENT MANUAL. 2. DETAILS OF THE WORK ARE CONTAINED ON ATTACHED WORK ORDER. 3. CERTIFIES THAT THE WORK SPECIFIED EXCEPT AS OTHERWISE SPECIFIED WAS CARRIED OUT IN ACCORDANCE WITH EASA 145 AND WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA ACCEPTANCE CERTIFICATE NUMBER EASA 145.4346. <b>IN ACCORDANCE WITH CIRCULAR SEAC 00mm 32-32-01 REV 8 DATED SEP/18/2008</b>							
14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 13.				19. <input checked="" type="checkbox"/> 14 CFR 43.9 Return To Service <input type="checkbox"/> Other Regulation Specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, Part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature: <i>[Signature]</i>		16. Approval/Authorization No: <i>[Signature]</i>		20. Authorized Signature: <i>[Signature]</i>		21. Approval/Certificate No: <b>GIIR167K</b>	
17. Name (typed or printed): <i>[Signature]</i>		18. Date: <i>[Signature]</i>		22. Name (typed or printed): <b>FAA TARM</b>		23. Date (dd/mm/yyyy): <b>06/10/2013</b>	
<b>User/Installer Responsibilities</b>							
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.</p> <p>Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.</p> <p>Statements in Block 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>							
FAA Form 8130-3 (6-01)		*Installer must cross-check eligibility with applicable technical data.				NSN: 0052-00-012-9005	

CONSOLIDATED AIRCRAFT SUPPLY CO., INC.  
55 RAYNOR AVE., RONKONKOMA, NY 11779

FAA REPAIR STATION #G11R167K  
DATE OCT/10/2013 JOB# 13-5475

## COMPONENT TEARDOWN REPORT (Q.C. 261)

Revision Date 10/07/11

NOMENCLATURE: HYDRAULIC FUSE	WORK PERFORMED: FUNCTIONALLY TESTED
PART NUMBER: VI-4360-2 (60B00238-12)	CUSTOMER: ANSETT A/C SPARES SVC.
SERIAL NUMBER: 2102382	CUSTOMER P.O.#: A50008286
AMEND./MOD. PLATE STATUS: N/A	MANUFACTURER: CIRCLE SEAL
REQUESTED/REQUIRED MODIFICATION: YES NO <b>X</b>	REVISED PART #: N/A REVISED SERIAL #: N/A

AIRWORTHINESS DIRECTIVES - FAA AD: YES (COMPLETE BLOCK 6) NO **X** EASA AD: YES (COMPLETE BLOCK 6) NO **X**

1) RECEIVING REMARKS: (CUSTOMER INSTRUCTIONS, AIRCRAFT REMOVAL INFO, T.S.O. T.S.N.)  
TEST AND RECERTIFY

2) TEARDOWN REMARKS:  
N/A

3) REPAIR ACTION TAKEN:  
INSPECTED AND FUNCTIONALLY TESTED.  
PASSED ALL THE MANUFACTURES SPEC'S.

4) INSPECTION REMARKS: (EXPLAIN P/N OR S/N CHANGES)  
FUNCTIONALLY TESTED

N.D.T. REQ'D.: YES **X** NO

ALL WORK DONE IN ACCORDANCE WITH: CIRCLE SEAL CMM 32-32-01 REV "8" DATED SEP/18/2008



5) SERVICE BULLETINS COMPLIED WITH:  
NONE

6) A.D. COMPLIED WITH THIS VISIT: A.D.# NONE A.D. PREVIOUSLY COMPLIED WITH: A.D.# N/A  
COMMENTS: NONE

TECHNICIAN'S SIGNATURE  WILLIAM K PRITCHARD SR

Internet/Worldwide Web Address  
HTTP://WWW.CONSOLAC.COM

591478

## PACK LIST

Internet/Worldwide Web Address  
HTTP://WWW.CONSOLAC.COM

JOB NO.

135475

### Consolidated Aircraft Supply Co., Inc.

Air Agency Certificate Number G1R167K  
55 RAYNOR AVENUE, RONKONKOMA, NEW YORK 11779  
PHONE (631) 981-7700 • FAX (631) 981-7708  
E-Mail CONSOL1291@AOL.COM

A129

**B**  
**I**  
**L**  
**L**  
**T**  
**O**  
ANSETT A/C SPARES SVC.  
12675 ENCINITAS AVENUE  
SYLMAR, CA 91342

### Consolidated Aircraft Supply Co., Inc.

Air Agency Certificate Number G1R167K  
55 RAYNOR AVENUE, RONKONKOMA, NEW YORK 11779  
PHONE (631) 981-7700 • FAX (631) 981-7708  
E-Mail CONSOL1291@AOL.COM

PHONE#: 818-362-1100

**S**  
**H**  
**I**  
**P**  
**T**  
**O**  
ANSETT A/C SPARES SVC.  
12675 ENCINITAS AVENUE  
SYLMAR, CA 91342

CUST. PURCHASE ORDER NO.		SHIP VIA		TERMS	DATE SHIPPED
A50008286		FEDX P1 PRIOR 122579433		NET 30 DAYS	10/11/13
QUANTITY			PART NUMBER / SERIAL NUMBER	DESCRIPTION	
ORDERED	SHIPPED	BACK ORDERED			
1	1		60B00238-12 2102382	** FUNCTIONALLY TESTED **  PASSED FUNCTIONAL TEST  HYD. FUSE	

### REPAIR & REPLACEMENT WARRANTY

CONSOLIDATED WARRANTS THAT, UPON SHIPMENT, ALL PARTS REPLACED IN THE REPAIRED OR OVERHAULED ARTICLE, WILL BE FREE FROM DEFECTS IN MATERIAL AND WORKMANSHIP. THE LIABILITY OF CONSOLIDATED IS LIMITED TO THE REPLACEMENT OR REPAIR OF ANY ARTICLE OR ARTICLES WHICH ARE FOUND BY CONSOLIDATED NOT TO COMPLY WITH THIS WARRANTY AND WITH RESPECT TO WHICH NOTICE OF ANY ASSERTED NON-COMPLIANCE IS GIVEN TO CONSOLIDATED IN WRITING WITHIN 90 DAYS AFTER THE SAME IS DISCOVERED. IF THE ARTICLES SO CLAIMED TO BE DEFECTIVE ARE RETURNED TO CONSOLIDATED, AND AFTER INSPECTION ARE FOUND TO BE NOT IN COMPLIANCE WITH THIS WARRANTY, THEY WILL BE REPAIRED TO THE EXTENT FOUND BY CONSOLIDATED TO BE NECESSARY OR, AT THE OPTION OF CONSOLIDATED, REPLACED AND RETURNED TO BUYER WITHOUT CHARGE.

CONSOLIDATED SHALL HAVE NO RESPONSIBILITY IF SUCH ARTICLES HAVE BEEN IMPROPERLY STORED, INSTALLED, OPERATED OR MAINTAINED OR IF BUYER HAS PERMITTED UNAUTHORIZED MODIFICATIONS, ADJUSTMENTS, AND/OR REPAIRS TO THE ARTICLES OR THE FAILURE OF THE USER TO USE THE PRODUCT IN ACCORDANCE WITH ITS INTENDED MANNER OF USE AND WITHIN APPLICABLE TOLERANCES SPECIFIED BY THE MANUFACTURER.

THE FOREGOING SHALL BE CONSOLIDATED'S SOLE AND EXCLUSIVE LIABILITY, AND BUYERS' SOLE AND EXCLUSIVE REMEDY FOR ANY ACTION, WHETHER BASED ON CONTRACT OR TORT LAW, INCLUDING NEGLIGENCE.

CONSOLIDATED SHALL NOT BE LIABLE FOR SPECIAL INCIDENTAL, OR CONSEQUENTIAL DAMAGES UNDER ANY CIRCUMSTANCES, INCLUDING, BUT NOT LIMITED TO, DAMAGE OR LOSS RESULTING FROM INABILITY TO USE THE EQUIPMENT, INCREASED OPERATING COSTS LOSS OF PRODUCTION, LOSS OF ANTICIPATED PROFITS OR OTHER SPECIAL INCIDENTAL OR CONSEQUENTIAL DAMAGES, WHETHER SIMILAR OR DISSIMILAR OR ANY NATURE ARISING FROM ANY CAUSE WHATSOEVER WHETHER BASED ON CONTRACT OR TORT LAW INCLUDING NEGLIGENCE.

CONSOLIDATED'S MAXIMUM LIABILITY ARISING FROM ANY CAUSE WHATSOEVER SHALL NOT EXCEED THE UNIT PRICE OF THE ARTICLES SPECIFIED IN THE REPAIR/OVERHAUL CONTRACT.

THIS WARRANTY CONSTITUTES THE SOLE LIABILITY OF CONSOLIDATED AND SHALL EXPIRE 6 MONTHS OR 200 (TWO HUNDRED) FLIGHT HOURS AFTER THE REPAIR OR OVERHAUL IS MADE, WHICHEVER COMES FIRST. THE USE OF THE PARTS DELIVERED BY CONSOLIDATED CONSTITUTES ACCEPTANCE OF THE WARRANTY AS THE SOLE OBLIGATION OF CONSOLIDATED TO THE CUSTOMER.



TO WHOM IT MAY CONCERN

Document No. AN/AASS APA001

**MATERIAL CERTIFICATION**

**Asset Purchase Agreement of Ansett Australia Limited Aircraft Spare Parts**

**Reference Number: AN/AASS APA001**

From: Ansett Australia Limited (subject to Deed of Company Arrangement) ("Ansett")

Level 24, 333 Collins Street

Melbourne VIC 300 Australia

To: Ansett Aircraft Spares & Services ("AASS")

12675 Encinitas Avenue

Sylmar, CA 91342-3634

USA

The undersigned hereby certifies that to the best of the knowledge of the Deed Administrators and their staff, the Aircraft Spares purchased ref. # AN/AASS APA001 Lot 959 under contract "Asset Purchase Agreement" dated on or about 21 March 2011:

1. Were purchased by AASS in a serviceable or unserviceable condition on an "as is where is" basis.
2. Were originally obtained by Ansett from the Original Equipment Manufacturer (OEM), one of its authorized licensees, Ansett recognized sources (under the Ansett certification systems as existed at the time) or were obtained from the stock of Ansett.
3. Were not obtained from any U.S. Government Military source.

To the best of the knowledge of the Deed Administrators and their staff, the material(s) shipped under this certification have not been subjected to extreme stress or heat (as in major engine failure, accident or fire).

By: Mark Korda

Name:

A handwritten signature in dark ink, appearing to read 'M. Korda'.

Title: Deed Administrator

PN	DESCRIPTION	SERIAL NUMBER	QTY	CONDITION	RELEASE No.
60B00238-12	FUSE	2102382	1	SV	6
60B40042-7	SENSOR-POS. PITCH/YAW	B58905W50	1	AR	15
60B40042-7	SENSOR-POS. PITCH/YAW	15720	1	SV	10
60B40052-12	CABLE /ASSY		3	NE	#1220
60B40059-4	"LIGHT AY/		1	NE	S45961
60B50059-618	HOSE /OXY,CREW SYSTEM.		4	NE	DC8242
60B50062-17	"CONNECTR/		1	NE	BN4182
60B50062-20	"CONNECTR/		1	NE	CE6377
60B50062-20	"CONNECTR/		2	NE	CF6014
60B50071-24	"LATCH /		1	NE	CZ0151
60B50087-34	OXYGEN BOTTLE - PORTABLE	2	1	AR	2
60B50087-93	OXYGEN CYLINDER-CREW	366123	1	AR	37
60B80033-1	SEAL /		1	NE	A92721
60B80033-2	SEAL /		1	NE	A91008
60B90021-1	BEARING /		2	NE	CU6479
60B90021-1	BEARING /		8	NE	DG6379
60B90021-1	BEARING /		3	NE	DG6889
60B90135-58	HOSE /		1	NE	#L3521
60B90135-58	HOSE /		1	NE	#L3522
60B90135-58	HOSE /		1	NE	#K5548
60B90135-61	"HOSE AY /		1	NE	#L3796
60B90135-61	"HOSE AY /		1	NE	#L4147
60B92401-4	VALVE /CHECK		1	NE	D60471
60B92409-8	"FITTING /ASSY.FLEX.FUEL CONNECTR		1	NE	BX8353
60B97215-2	"BLOCK /		1	NE	CD1180
610-0007-001	GASKET /		4	NE	#F6555
610-0007-001	GASKET /		10	NE	#G9396
61000-100-015-0	"SPRING /		5	NE	CG4903
61000-100-015-0	"SPRING /		36	NE	CZ4517
61000-100-015-0	"SPRING /		1	NE	CX8752
610-0012-001	GASKET /		2	NE	CU2556
61000-500-002-0	BUSHING /STANDARD (9158-SERIES)		9	NE	CS5194
61000-500-002-0	BUSHING /STANDARD (9158-SERIES)		10	NE	CZ4700
61000-500-100-0	"BUSHING /1ST CLASS SEAT ASSY.		45	NE	CZ2560
61000-500-100-0	"BUSHING /1ST CLASS SEAT ASSY.		4	NE	CZ2560
61000-551-025-0	"CLIP /RETAINING		20	NE	CS1560
61000-600-019-0	"SCREW /		29	NE	T01355
61000-603-110-1	"MISC /ESXUTCH		3	NE	E47328
61000-603-110-1	"MISC /ESXUTCH		4	NE	E47328
61000-603-110-2	"ESCUTCHN/		1	NE	BW7186
61000-603-110-2	"ESCUTCHN/		2	NE	BX3241
61000-603-400-0	"BUMPER /		11	NE	BL9022
61000-603-410-0	"BUMPER /		6	NE	61000-603-410-0
61000-603-410-0	"BUMPER /		10	NE	BL3773
61000-603-410-0	"BUMPER /		10	NE	BR2742
61000-624A740-0	FAIRING /		8	NE	DC9951
61000-624A740-0	FAIRING /		2	NE	CZ6870
61000-703-630-1	"ESCUTION/L/H,9199 SERIES SEAT.		5	NE	DF0790
61000-703-630-2	"ESCUTION/R/H,9199 SERIES SEAT.		21	NE	DF6904
61000-703-630-2	"ESCUTION/R/H,9199 SERIES SEAT.		5	NE	DH0185
61000-703A620-0	FAIRING /NHA 770420-110-0000		5	NE	K60304
61000-703A620-0	FAIRING /NHA 770420-110-0000		7	NE	E77186
61000-704A620-0	"FAIRING /UNDER		6	NE	CU0722
61000-704A620-0	"FAIRING /UNDER		4	NE	CU4732
61000-704A620-0	"FAIRING /UNDER		1	NE	CU0755
61000-708-600-1	ARMREST /		2	NE	DH0187
610-0074-018	RING /O RING		2	NE	#F6556
610-0074-040	O RING /		5	NE	#F6815
610-0077-001	FITTING /		2	NE	E05451
61000-800-010-1	"BEARING /BEARING L/H		6	NE	DF5194
61000-800-010-2	"BEARING /BEARING - R/H		6	NE	DG6239
61000-800-010-2	"BEARING /BEARING - R/H		6	NE	DF5192

## PART OR MATERIAL CERTIFICATION FORM

ATA SPECIFICATION 106

2. Seller's Name:

**ANSETT AIRCRAFT SPARES & SERVICES**

3. Reference #

**A30128187**

4. Organization:

**Ansett Aircraft Spares & Services - US**

Address:

12675 Encinitas Avenue  
SYLMAR, CA 91342, UNITED STATES  
Ph: (818) 362-1100, Fax: (818) 362-1088

Phone#:

(818) 362-1100

Fax#:

(818) 362-1088

SITA/Wire Code: LAXASXH

Status:

New/Surplus Parts Supplier  
New Parts Distributor

5A. Seller's Contract #: A10145692

5B. Buyer's PO #:

281636

6. Item	7. Description	8. Manufacturer & Part Number	9. App Code	10. Qty	11. Serial/Batch #	12. Status
1	FUSE	60B00238-12 BRUNSWICK	767-200	1	SN: 2102382	SV

13A. Remarks:

CONSOLIDATED 8130-3 STRN#13-5475

To the best of our knowledge, the material(s) shipped against this certification was (were) not obtained from any U.S. Government or military source and have not been subjected to extreme stress or heat (as in major engine failure, accident or fire).

13B. Traceable To:

ANSETT AUSTRALIA

13C. Last Certified Agency:

CONSOLIDATED AIRCRAFT

14. New Parts/Material Verification

THE FOLLOWING SIGNATURE ATTESTS THAT THE PART(S) OR MATERIAL(S) IDENTIFIED ABOVE WAS (WERE) MANUFACTURED BY A FAA PRODUCTION APPROVAL HOLDER (PAH), OR TO AN INDUSTRY COMMERCIAL STANDARD.

18. Surplus, Used, Repaired or Overhaul Parts Verification:

THE FOLLOWING SIGNATURE ATTESTS THAT THE DOCUMENTATION SPECIFIED ABOVE OR ATTACHED IS ACCURATE WITH REGARD TO THE ITEM(S) DESCRIBED.

15. Signature

19. Signature

16. Name

17. Date 10/14/2013

20. Name

JOSE AGUIRRE  
QUALITY CONTROL

21. Date 10/14/2013