

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2.		AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 08188418	
4. Organization Name and Address: The Boeing Company 1901 Oakesdale Ave SW, M/C 34-02 Renton, WA 98057-2623 P.C. #700				5. Work Order/Contract/Invoice Number: CF5198		11. Status/Work:			
6. Item:		7. Description:		8. Part Number:		9. Quantity:		10. Serial Number:	
0001		SUP KIT		GMS45L		015T1778-14		1 EA	
0002		SUPL KIT		HOF08W		015U1808-3		1 EA	
0003		KIT		OMW46P		015U1924-2		1 EA	
0004		SB KIT		UNB31K		005W3155-1		1 EA	
								N/A	
								NEW	
								NEW	
								NEW	
								NEW	
12. Remarks: TRX AUB				PAGE 1 OF 1		OVERBOX NO: CF5198			
EXPORT AIRWORTHINESS APPROVAL THIS ARTICLE(S) MEETS THE SPECIAL REQUIREMENTS OF UNITED KINGDOM									
13a. Certifies the items identified above were manufactured in conformity to: ☒ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.				14a. ☐ 14-CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
13b. Authorized Signature: 				13c. Approval/Authorization No.: ODA-300064-NM		14b. Authorized Signature:		14c. Approval/Certificate No.:	
13d. Name (Typed or Printed): MARK A. LEWIS				13e. Date (dd/mm/yyyy): 17 AUG 2015		14d. Name (Typed or Printed):		14e. Date (dd/mm/yyyy):	
User/Installer Responsibilities									
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.									

Boeing Packing Slip

Date: 05-JUL-15 01:04 PM

Ship From:
SDC Receiving Address
Boeing Spares Kitting
2201 South 142nd Street
22-01 Door W10
Sea-Tac, WA 98168-3713, United States

324126

Ship To:
Customer Services Division
SSA108
2201 South 142nd Street
Sea-Tac, WA 98168, United States

S/O: 211787
SIS:
Cust Code:
W/O: M79605113



Delivery Name: 324126



Way Bill:

Line	Item No.	Description	Qty Shipped	Qty B/O	UOM	Lot Number
015T1778-14						
1.1	015T1778-14	SUPPLEMENTAL KIT, BOOST PUMP OVERRIDE/	13.00	0.00	EA	438374



Total Qty: 13.00

TEAM CONTRIBUTORS
STDS PICKER
HIGHBAY PICKER N/A
FLOOR PICKER 2092669
PACKER 129646

Boeing Packing Slip

S/O: 211787 /1.1

324126

Total Overboxes: 0

Qty: 1

Kit Lot: 438374

Item: 015T1778-14

Kit Description: SUPPLEMENTAL KIT, BOOST PUMP (

W/O: M79605113

Engrg Rev:

Ref	Section Level	Item No.	Description	Per Ay Qty	Reqd Qty	Issued Qty	UM	Ctry Mfg B	Sched	Lot Number	Engrg Rev/ Box
+ 0		015T1778-14	SUPPLEMENTAL KIT, BOOST PUMP OVERR		1	1	EA			438374	PDM/B
1		289T1136-10201	SLEEVE	49	49	49	EA				
1		324484	TERMINAL	1	1	1	EA				
1		P204541	CONTACT, SOCKET	3	3	3	EA				

129646

Cross-Reference: P-204541

Ref.
Section
1