

1. Approving Civil Aviation
Authority/Country:

2.

AUTHORIZED RELEASE CERTIFICATE

3. Form Tracking Number:

318673

FAA/UNITED STATES

FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

4. Organization Name and Address:

AirCo Services, LLC

2995 Lone Oak Circle

Suite# 10

Eagan, MN 55121

Ph: 316-945-9820, Fax: 651-393-3310

FAA Approval Holder: T12R188L



5. Work Order/Contract/Invoice
Number:

X1035

6. Item 7. Description:

1

RUDDER TRIM IND

8. Part Number:

10166N01ND00

9. Quantity:

1.00

10. Serial Number:

07085137BA

11. Status/Work:

REPAIRED

12. Remarks:

REFERENCE WORK ORDER REPORT FOR WORK PERFORMED. ALL WORK PERFORMED I/AAW, Manual ID: 27-21-03, Revision #: 2, Revision Date: 3/1/2001

MODS INSTALLED: NONE

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: EASA.145.4100.

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

T12R188L

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

Adam Holstine

14e. Date (dd/mm/yyyy):

28-Nov-2023

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

**AirCo Services, LLC**

2995 Lone Oak Circle

Suite# 10

Eagan, MN 55121

FAA REPAIR STATION #TI2R188L

Tear Down/Inspection

Work Order #: X1035

PN: 10166N01N00

Desc: RUDDER TRIM IND

SN: 07085137BA

To:

ATTN: REBECCA WILDERS
A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WE RH13 OSH
UNITED KINGDOM

Ship To:

A J WALTER AVIATION LTD
B AND H WORLDWIDE INC DORAL
1523 NW 82ND AVENUE
DORAL, FL 33126
UNITED STATES

Date Printed	Cust No.	Terms	Customer Contact			Cust PO
11/28/2023	01489	N30	REBECCA WILDERS			R418421
F.O.B.	Ship Via		Manual:	Revision:	Rev Date:	Location:
	FEDX P1	651244579	27-21-03	2	3/1/2001	F4
ASSIGNED TECHNICIANS			ASSIGNED INSPECTOR			
Timothy Wood			Adam Holstine			

Action Requested

REPAIR

Please advise cost to Repair IAW mfg specs.

Faults:

REPAIR

Unit dirty, faceplate scuffed, J1 missing. Unit requires cleaning, painting, replacement of J1, and testing IAW mfg specs.

Action Taken:

REPAIR

Cleaned, painted, and replaced J1. Functionally tested unit in accordance with CMM 27-21-03, Rev 2, 3/1/2001. Tagged, Repaired, and certified airworthy in accordance with mfg specs.

PN	Description	Qty Needed	CD	Disposition
MS24264R12B12P	CONNECTOR	1	NE	Consumable

By:

Date:

11/28/2023



2995 Lone Oak Circle
Suite 10
Eagan, MN 55121
316-945-9820 Phone
www.aircoservices-ict.com
FAA REPAIR STATION # TI2R188L

Packing Slip

SO #: 3843
Date Printed: 11/28/2023
Time: 7:19:44 AM
of Items: 1
Page: 1

To:

A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WE RH13 OSH
UNITED KINGDOM
ATTN: REBECCA WILDERS

Ship To:

B AND H WORLDWIDE INC DORAL
1523 NW 82ND AVENUE
DORAL, FL 33126
UNITED STATES

Date Open: 11/28/2023

Ship Via: FEDX P1

Customer PO#: R418421

Customer #: 01489

Ship Via Acc: 651244579

Buyer:

Thank you for your order!

Item	Part Number/Description	Delivery	To Ship	BackOrd	CD
1	10166N01N00 RUDDER TRIM IND Serial #: 07085137BA		1.00	EA 0.00	RP

These commodities are subject to the Export Administration Regulations (EAR) and/or International Traffic in Arms Regulations (ITAR). If you are exporting, or re-exporting these products, It is your responsibility to obtain a validated export license for this material from the Department of Commerce or the Department of State if so required under the applicable U.S. Government Export Control Regulations. The above material shall not be shipped to any country that has an embargo placed on it by the U.S. Government or any entity on the U.S. Debarred list. By accepting the item(s) on this invoice you agree to our terms and conditions of sale. If these commodities, technology or software are being

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our Service Guide. Written claims must be filed within strict time limits, see current FedEx Service Guide.

After printing this label:

CONSIGNEE COPY - PLEASE PLACE IN FRONT OF POUCH

1. Fold the printed page along the horizontal line.
2. Place label in shipping pouch and affix it to your shipment.

ORIGIN ID: MICA (651) 994-1600
ADAM HOLSTINE
AIRCO SERVICES, LLC
2995 LONE OAK CIRCLE
SUITE 10
EAGAN, MN 551211431
UNITED STATES US

SHIP DATE: 28NOV23
ACTWGT: 3.50 LB MAN
CAD: 0810607/CAFE3755
DIMS: 18x12x8 IN
BILL RECIPIENT

TO LAURA SALADO

B & H WORLDWIDE, INC.
1523 NW 82ND AVENUE

DORAL FL 33126

(140) 379-8000

PO: R418421



J233923061201ur

TRK#
0201

6456 5141 3640

WED - 29 NOV 12:00P
PRIORITY OVERNIGHT

NGCTYA

33126
FL-US MIA



585C17/D12/AED7