

1. Approving Civil Aviation Authority / Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: RD 7025755	
4. Organization Name and Address: LIEBHERR-AEROSPACE SALINE, INC 1465 Woodland Drive Saline MI 48176 USA			5. Work Order/Contract/Invoice Number: L3RR193H RD 7025755				
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:		
1	REHEATER	755C0000-01	1	81210-51824	OVERHAULED		
12. Remarks							
TSN: 0 CSN: 0 Amendment: A Refer to: Shop Finding Report RD 7025755 Approved data: CMM 21-54-17 Rev 2 dated 08 NOV 2019 Comments: Return to service: Work specified accomplished IAW 14CFR Part 43.13(a)(b) and/or (c)/AC 43.18 if local fabricated parts were used. Remark: RECORE Limited life parts must be accompanied by maintenance history including total time / total cycle / time since new.							
13a Certifies that the items identified above were manufactured in conformity to:		14a. ☒ 14 CFR 43.9 Return to Service		Other regulation specified in Block 12			
☐ Approved design data and in condition for safe operation ☐ Non-approved design data specified in Block 12		Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
13b. Authorized Signature:		14b. Authorized Signature: LSL 18		14c. Approval/Certificate No.:		L3RR193H	
13d. Name (Typed or Printed):		14d. Name (Typed or Printed): Thomas Weber		14e. Date (dd/mm/yyyy):		18/Apr/2022	
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

1 国家 Country 中国/REPUBLIC OF CHINA		2 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness 批准放行证书/适航批准标签		3 证书编号 Certificate Ref. N°. 2022-06600		
4 单位 Organization: LIEBHERR-AEROSPACE SALINE, INC 1465 Woodland Drive Saline MI 48176 USA		AUTHORIZED RELEASE CERTIFICATE / AIRWORTHINESS APPROVAL TAG				
5 工作单/合同单/货单 Work Order/Contract/Invoice RD 7025755						
6 序号 Item	7 内容 Description	8 件号 Part N°.	9 适用性 Eligibility	10 数量 Qty	11 系列号/批号 Serial/Batch N°.	12 产品状态 Status/Work
1	REHEATER	755C0000-01 Amdt A	Not Known	1	81210-51824	OVERHAULED
13 备注 Remarks Approved data: CMM 21-54-17 Rev 2 dated 08 NOV 2019 Investigation Report 7025755 Remark: RECORE TSN: TSO: 0 CSN: CSO: 0 Modification: SB 755-21-02 Rev 0 dated 19 DEC 2016						
14 新产品 New Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例进行制造/检查, 并且该产品(出口产品)符合经批准的型号设计资料/和进口国提出的专用要求。 Certifies that the Part(s) identified above except as otherwise specified in block 13 was(were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		15 使用过的产品 Used Parts 兹声明上述产品除第13项的其它规定以外, 已按照上述国家适航条例和进口国通知的特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)				
16 批准人签名 Signature 		18 批准日期 Date 18/Apr/2022		19 中国民航总局授权 Issued by or on behalf of the CAAC F00100650		
17 批准人姓名 (打印的) Name(Printed) Thomas Weber						

SHOP FINDING REPORT

LIEBHERR REPAIR DOSSIER: 7025755
RECEPTION DATE: 05 APR 2022
CUSTOMER PURCHASE ORDER: RAV2200144
OPERATOR: UNKNOWN
AIRCRAFT TYPE: Unknown aircraft
AIRCRAFT REG. NUMBER: N/A
AIRCRAFT SERIAL NUMBER: N/A
ADD. CUSTOMER DOCUMENTS: N/A

CONTACT: Alyssa Fountain
EMAIL: N/A
DATE: 18 APR 2022

RECEIVED UNIT

CUSTOMER REFERENCE: 755C0000-01
PART NUMBER: 755C0000-01
AMENDMENT: -
SERIAL NUMBER: 81210-51824
DESCRIPTION: REHEATER
MANUFACTURING CODE: F1958
MANUFACTURING DATE: 07/06

DELIVERED UNIT

CUSTOMER REFERENCE: 755C0000-01
PART NUMBER: 755C0000-01
AMENDMENT: A
SERIAL NUMBER: 81210-51824
DESCRIPTION: REHEATER

TIMES & CYCLES

TSN	TSO	TSI	CSN	CSO	CSI
N/A	0.00	N/A	N/A	0	N/A

INSTALLATION DATE: N/A
LIFE LIMITED PARTS EXISTING: No
LOG CARD EXISTING: No

REMOVAL DATE: N/A
NON INCIDENT STATEM.: No

MAINTENANCE DOSSIER: /755D0000-01 / VERSION 13 (23 MAR 2022)
APPROVED DATA & MAINTENANCE DOCUMENTS: CMM 21-54-17 / REVISION 2 / 08 NOV 2019
 SB 755-21-02 / REVISION 0 / 19 DEC 2016


TYPE OF CERTIFICATE: EASA, FAA, CAAC

WORK REQUESTED: REPAIR
WORK PERFORMED: Recore

Annex: FINDINGS AND ANALYSIS PICTURES

Visual inspection - Cold outlet header damaged - Large dent.

IMG_6381.JPG



IMG_6382.JPG

REASON FOR RETURN:

QUOTE TO RECORE

FINDINGS AND ANALYSIS:

Findings from Analysis:

- Recoring - Customer request recore.
- Visual inspection - Cold outlet header damaged - Large dent.
- Slight material imperfections and deformations on flanges and header surfaces may be present

WORK PERFORMED:

- Repair of the cold outlet header
- Recoring
- Unit was inspected and all remaining imperfections are deemed to be of a cosmetic nature only, not affecting fit, form or function
IAW LTS SPM 20-00-01

LIFE LIMITED PARTS RECEIVED:

N/A

LIFE LIMITED PARTS DELIVERED:

N/A


SHOP FINDING REPORT APPROVED:

VALIDATION DATE:

15 APR 2022

VALIDATED BY:

Wes Brakhage (electronic signature)



IMG_6383.JPG

