

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 121306363	
4. Organization Name and Address: Precision Aero Technology 3333 East Spring Street Long Beach, CA 90806-6826				5. Work Order, Contract, or Invoice Number: 121306363 Cust Ref: T13172	
6. Item: 1		7. Description: FLT DECK ACCESS LT CONT		8. Part Number: 233U4205-1	
9. Eligibility:		10. Quantity:		11. Serial/Batch Number:	
N/A		1		D00112	
12. Status/Work:		INSPECTED			
13. Remarks: 31-12-03 Rev:1 8/13/2009 A GENERAL DESCRIPTION OF THE WORK PERFORMED IS IN THE ATTACHED WORK ORDER DOCUMENT, UNDER THE PART DESCRIPTION LISTED IN BLOCKS 6,7,8,10 AND 11 AS APPLICABLE. A COMPLETE DESCRIPTION OF WORK PERFORMED IS ON FILE AT THE ABOVE REFERENCED ORGANIZATION UNDER THE WORK ORDER AND SYSTEM TRACKING REFERENCE NUMBER INDICATED IN BLOCKS 3 AND 5. NOTICE: An Airworthiness Directive may apply to the article(s) described hereon. The installer is responsible for ensuring complete compliance with any applicable Airworthiness Directives. Precision Aero Technology certifies that the work specified in block 12 and 13 was performed in accordance with EASA part 145 and with respect to that work, the aircraft component is considered ready for release to service under EASA part 145 Approval Number EASA.145.4052.					
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in Block 13.					
15. Authorized Signature:		16. Approved Authorization No:		19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
17. Name (Typed or Printed):		18. Date (m/d/y):		20. Authorized Signature: <i>Ernesto Fontanilla</i> 21. Approval/Certificate Number: DQ3R458L	
ERNESTO FONTANILLA		Jul/24/2013			
User/Installer Responsibilities It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

NSN: 0052-00-012-9005

*Installer must cross check eligibility with applicable technical data.

Precision Aero Technology

3333 East Spring Street
Long Beach, CA 90806-6826

Phone: 562-595-6055

FAX: 562-595-1815

FAA # DQ3R458L

ARINC: LGBGHXD

Work Order

DATE RECEIVED WORK ORDER NO.

06/24/2013

121306363


DATE COMPLETED CUSTOMER ORD NO.

07/24/2013

T13172

ROUTINE

B I L L T O	A1414 AJ WALTER AVIATION LTD THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST UNITED KINGDOM	RH13 OSH	S H I P T O	A1414T B&H WORLDWIDE INC 8000 NW 25TH STREET SUITE 300 DORAL USA	FL 33122
Action Requested		Unit Number	Description		Serial Number
REPAIR AS NECESSARY		233U4205-1	FLT DECK ACCESS LT CONT		D00112
Aircraft Number		Customer Part No.			Manual No.
F-GITB					31-12-03
Aircraft Position		Last Repair Station	T S O		Manual Date/Loc
					08/13/2009 AL-1759
REASON FOR REMOVAL			SPECIAL INSTRUCTIONS		
PLEASE INSPECT AND REPAIR AS NECESSARY.			TIME & MATERIAL		
Service Performed Detailed Service Report					
Incoming Inspection:					
UNIT RECEIVED IN FAIR CONDITION.					
Shop Evaluation:					
PRELIMINARY INSPECTION SHOWS NO OBVIOUS PROBLEM.					
Work Accomplished:					
INSPECTED UNIT. CLEANED FRONT PANEL, CONNECTOR AND SWITCH ASSEMBLY. PERFORMED FUNCTIONAL TEST AND VERIFIED TO MEET THE TECHNICAL SPECIFICATIONS. THE ABOVE MENTIONED WORK WAS PERFORMED I.A.W. C.M.M. 31-12-03.					

Service Performed	Warranty	Removal Reason Confirmed
I INSPECTED	☐ Accepted ☐ Denied ☒ N/A	☐ Yes ☐ No ☒ N/A
TECHNICIAN	INSPECTOR	8130 REFERENCE
LAURENTIU GEORGESCU	ERNESTO FONTANILLA 	69834