


1. Approving Civil Aviation Authority / Country: <div style="text-align: center;">FAA/United States</div>		2. AUTHORIZED RELEASE CERTIFICATE <div style="text-align: center;">FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG</div>			3. Form Tracking Number: <div style="text-align: center;">RD 7025753</div>	
4. Organization Name and Address: LIEBHERR-AEROSPACE SALINE, INC 1465 Woodland Drive Saline MI 48176 USA		5. Work Order/Contract/Invoice Number: <div style="text-align: center;">RD 7025753</div>				
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	REHEATER	755C0000-01	1	81210-57991	OVERHAULED	
12. Remarks TSN: TSO: 0 Dual Release: Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work, the aircraft component is considered ready for release to service under EASA Part-145 Approval Number EASA.145.5439. CSN: CSO: 0 Amendment: A Modification: SB 755-21-02 Rev 0 dated 19 DEC 2016 Refer to: Shop Finding Report RD 7025753 Approved data: CMM 21-54-17 Rev 2 dated 08 NOV 2019 Comments: Return to service: Work specified accomplished IAW 14CFR Part 43.13(a)(b) and/or (c)/AC 43.18 if local fabricated parts were used. Remark: RECORE						
Limited life parts must be accompanied by maintenance history including total time / total cycle / time since new.						
13a. Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and in condition for safe operation <input type="checkbox"/> Non-approved design data specified in Block 12		14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.				
13b. Authorized Signature: 	13c. Approval/Authorization No.: <div style="text-align: center;">L3RR193H</div>	14b. Authorized Signature: 		14c. Approval/Certificate No.: <div style="text-align: center;">L3RR193H</div>		
13d. Name (Typed or Printed): <div style="text-align: center;">Thomas Jimenez</div>	13e. Date (dd/mm/yyyy): <div style="text-align: center;">21/Apr/2022</div>	14d. Name (Typed or Printed): <div style="text-align: center;">Thomas Jimenez</div>		14e. Date (dd/mm/yyyy): <div style="text-align: center;">21/Apr/2022</div>		

User/Installer Responsibilities
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1 国家 Country		2 中国民用航空总局 CAAC		<input type="checkbox"/> 符合性 Conformity <input checked="" type="checkbox"/> 适航性 Airworthiness		3 证书编号 Certificate Ref. N°	
中国/REPUBLIC OF CHINA		AUTHORIZED RELEASE CERTIFICATE / AIRWORTHINESS APPROVAL TAG				2022-06653	
4 单位 Organization:				5 工作单/合同单/货单 Work Order/Contract/Invoice			
LIEBHERR-AEROSPACE SALINE, INC 1465 Woodland Drive Saline MI 48176 USA				RD 7025753			
6 序号 Item	7 内容 Description	8 件号 Part N°	9 适用性 Eligibility	10 数量 Qty	11 系列号/批号 Serial/Batch N°	12 产品状态 Status/Work	
1	REHEATER	755C0000-01 Amdt A	Not Known	1	81210-57991	OVERHAULED	
13 备注 Remarks							
TSN: TSO: 0 CSN: CSO: 0 Approved data: CMM 21-54-17 Rev 2 dated 08 NOV 2019 Investigation Report 7025753 Modification: SB 755-21-02 Rev 0 dated 19 DEC 2016 Remark: RECORE							
14 新产品 New Parts				15 使用过的产品 Used Parts			
兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例进行制造/检查，并且该产品（出口产品）符合经批准的型号设计资料。和进口国提出的专用要求。 Certifies that the Part(s) identified above except as otherwise specified in block 13 was(were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.				兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例和进口国通知的特殊要求进行工作，该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)			
16 批准人签名 Signature		15-18 批准日期 Date		19 中国民航总局授权 Issued by or on behalf of the CAAC			
 21/Apr/2022				F00100650			
17 批准人姓名（打印的） Name(Printed) Thomas Jimenez							

批准放行证书/适航批准标签
AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG
使用者/安装者职责
USER/INSTALLER RESPONSIBILITIES

- (1) 必须明确：本文件并不批准零件/组件/部件可以装到有关产品上。
- (2) 当使用者/安装者使用的是所在国适航当局的条例，而不是本表第1项中所指国家适航当局的条例时，使用者/安装者必须保证所在国的适航当局能接受所指国家适航当局批准出口的零件/组件/部件。
- (3) 表中第14项、第15项的陈述，并不说明本表是安装批准。在所有情况下，航空器使用前，航空器使用者/安装者应把按本国适航条例颁发的安装批准放入维修记录中。

- (1) It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.
- (2) Where the user/installer works in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1 it is essential that the user/installer ensure that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.
- (3) Statements 14 and 15 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.



Liebherr-Aerospace Saline * 1465 Woodland Drive * Saline, MI 48176

SHOP FINDING REPORT

LIEBHERR REPAIR DOSSIER:	7025753	CONTACT:	Alyssa Fountain
RECEPTION DATE:	04 APR 2022	EMAIL:	N/A
CUSTOMER PURCHASE ORDER:	RAV2200143	DATE:	21 APR 2022
OPERATOR:	UNKNOWN		
AIRCRAFT TYPE:	Unknown aircraft		
AIRCRAFT REG. NUMBER:	N/A		
AIRCRAFT SERIAL NUMBER:	N/A		
ADD. CUSTOMER DOCUMENTS:	N/A		

RECEIVED UNIT

CUSTOMER REFERENCE:	755C0000-01
PART NUMBER:	755C0000-01
AMENDMENT:	-
SERIAL NUMBER:	81210-57991
DESCRIPTION:	REHEATER
MANUFACTURING CODE:	F1958
MANUFACTURING DATE:	062013

DELIVERED UNIT

CUSTOMER REFERENCE:	755C0000-01
PART NUMBER:	755C0000-01
AMENDMENT:	A
SERIAL NUMBER:	81210-57991
DESCRIPTION:	REHEATER

TIMES & CYCLES

TSN	TSO	TSI	CSN	CSO	CSI
N/A	0.00	N/A	N/A	0	N/A

INSTALLATION DATE:	N/A	REMOVAL DATE:	N/A
LIFE LIMITED PARTS EXISTING:	No	NON INCIDENT STATEM.:	No
LOG CARD EXISTING:	No		

MAINTENANCE DOSSIER:	/755D0000-01 / VERSION 13 (23 MAR 2022)
APPROVED DATA & MAINTENANCE DOCUMENTS:	CMM 21-54-17 / REVISION 2 / 08 NOV 2019 SB 755-21-02 / REVISION 0 / 19 DEC 2016

TYPE OF CERTIFICATE:	CAAC, EASA, FAA	WORK REQUESTED:	REPAIR
		WORK PERFORMED:	Recore

LIEBHERR

Liebherr-Aerospace Saline * 1465 Woodland Drive * Saline, MI 48176

REASON FOR RETURN:

QUOTE TO RECORE

FINDINGS AND ANALYSIS:

Findings from Analysis:

- Recoring - Customer request recore.
- Slight material imperfections and deformations on flanges and header surfaces may be present

WORK PERFORMED:

- Recoring
- Unit was inspected and all remaining imperfections are deemed to be of a cosmetic nature only, not affecting fit, form or function
IAW LTS SPM 20-00-01

LIFE LIMITED PARTS RECEIVED:

N/A

LIFE LIMITED PARTS DELIVERED:

N/A

SHOP FINDING REPORT APPROVED:

VALIDATION DATE: 20 APR 2022
VALIDATED BY: Skyler Root (electronic signature)

Bill To:

Ship To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Carrier: AVIA VAN

W/O/SO No: WAV2204523

Airway bill:

Customer PO: T37168

Ship Date:

Order Date: 22/03/2022

Part No.	Description	Cond	Qty	Serial Number	Cert No.
----------	-------------	------	-----	---------------	----------

755C0000-01

Reheater

OH

1

81210-57991

RD 7025753

We hereby certify that the parts in this shipment conform with applicable specifications and that documentation and/or data is on file and available for examination.

Signed:

[Signature]

Date:

- 4 MAY 2022

For and on behalf of Avia Technique Ltd.

Reference: SK-GF-006

Issue: Initial