



1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 64580-1	
4. Organization Name and Address: SOUTHERN AEROPARTS 4157 SOUTHWEST BLVD TULSA, OK. 74107 US		Repair Station No.: QAKR523K				5. Work Order, Contract or Invoice Number: Work Order No.: SEL101450 Customer RO.: R337747	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:		
1	POWER DRIVE UNIT	192AD1R218B	1.00	8965	REPAIRED		
12. REMARKS IN ACCORDANCE WITH CMM: 25-55-04 REV: 6 DATE: 31-MAR-2015 DER REPAIR: SAIRS 1019 DER REPAIR REV: A DATE: 15-JUL-2002							
NO APPLICABLE AND/OR ADDITIONAL AD'S OR SB'S NOTED ON THIS UNIT AT THIS TIME. Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number 145.5539							
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a ☒ 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14b. Authorized Signature: 			14c. Approval/Certificate No: QAKR523K
13b. Authorized Signature:		13c. Approval Authorization No:		14d. Name (Typed or Printed): SAMANTHA TALLY			
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 02/Oct/2018			
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 64580-1	
4. Organization Name and Address: SOUTHERN AEROPARTS 4157 SOUTHWEST BLVD TULSA, OK. 74107 US				5. Work Order, Contract or Invoice Number: Work Order No.: SEL101450 Customer RO.: R337747	
Repair Station No.: QAKR523K		8. Part Number: 192AD1R218B		9. Quantity: 1.00	10. Serial Number: 8965
6. Item	7. Description:	11. Status/Work: REPAIRED			
1	POWER DRIVE UNIT				
12. REMARKS IN ACCORDANCE WITH CMM: 25-55-04 REV: 6 DATE: 31-MAR-2015 DER REPAIR: SAIRS 1019 DER REPAIR REV: A DATE: 15-JUL-2002 NO APPLICABLE AND/OR ADDITIONAL A/D'S OR S/B'S NOTED ON THIS UNIT AT THIS TIME. Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number 145.5539					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a ☒ 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		☒ Other regulation specified in Block 12	
13b. Authorized Signature:		14b. Authorized Signature: 		14c. Approval/Certificate No: QAKR523K	
13d. Name (Typed or Printed):		14d. Name (Typed or Printed): SAMANTHA TALLY		14e. Date (dd/mm/yyyy): 02/Oct/2018	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Southern Aeroparts
4157 Southwest Blvd
Tulsa, OK. 74107
US

Tear Down/Inspection

Work Order #: SEL101450

Date Printed: 02-Oct-18

Page: 1 of 1

To:

AJ WALTER AVIATION LTD***
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
WEST SUSSEX RH13 0AS
UNITED KINGDOM

Ship To:

AJ WALTER AVIATION LTD***
LOGISTICS CENTRE
THE BUSINESS PARK
MAYDWELL AVENUE
SLINFOLD, RH13 UNITED KINGDOM

Cust.PO Ref.: R337747

Cust.Phone: 441403711777

Cust.Email: projectsgroup@ajw-aviation.com

Cust.Code: 310222

Cust.Fax: 1-441403710936

Station: SAI

IN. PN: 192AD1R218B

Descr: POWER DRIVE UNIT

Qty: 1

OUT PN: 192AD1R218B

Serial Numbers: 8965

Symptoms:

See PO

Faults:

Verified P/N and S/N. Unit was tested IAW 25-55-04 Rev (6) 3/31/2015. Requesting parts for repair rollers, strap, cotter pins, 4 o-rings and hardware. SAIRS 1019, REV A, 7/15/2002.

Corrective Actions:

Verified P/N and S/N. Unit was tested IAW 25-55-04 Rev (6) 3/31/2015. Requested parts replaced and rollers were repaired, strap, cotter pins, 4 o-rings and hardware were replaced.

Repaired IAW CMM 25-55-04 Rev 4 Dated 3/31/2015 and SAIRS 1019 Rev A Dated 7/15/2002.

CMM: 25-55-04 Rev: 6 Date: 31-Mar-2015