

1. Approving Competent Authority/Country

2.

AUTHORISED RELEASE CERTIFICATE

3. Form Tracking Number
20230013092509Y02
347406777

EASA

EASA FORM 1

4. Organisation Name and Address:

HONEYWELL UK LIMITED, 1/a HONEYWELL AEROSPACE BASINGSTOKE,
EDISON RD BASINGSTOKE HAMPSHIRE RG21 6QD
TEL: +44(0)1256 722200 FAX: +44(0)1256 722201

5. Work Order/Contract/Invoice
T41368

347382391
Page 1 of 1

6. Item	7. Description	8. Part No	9. Qty	10. Serial No.	11. Status/Work
001	COMPUTER, DIGITAL-DISPLAY UNIT	4091900-942	1	40034642	REPAIRED

12. Remarks

WORK PERFORMED AS DETAILED IN SERVICE REPORT
THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH:
CMM 31-61-82 Rev 8, JUL/21/2022
SB 4091900-31-0005 Rev 1, JAN/26/2016

THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER
GENERATED SIGNATURE PROCEDURE
MODS: B,C,D,F.


PRINTED FROM ELECTRONIC FILE

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ approved design data and are in condition for safe operation
☐ non-approved design data specified in block 12

14a. ☒ Part-145, A.50 Release to Service ☐ Other regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service

13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature 	14c. Certificate/Approval Ref. No EASA.UK.145.00879
13d. Name	13e. Date (dd mmm yyyy)	14d. Name Andrew Hunt	14e. Date (dd mmm yyyy) 29 JUN 2023

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulation of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.





1. Approving Competent Authority/Country CAA UK		2.		AUTHORISED RELEASE CERTIFICATE			3. Form Tracking Number 20230013092510Y32 347406777	
4. Organisation Name and Address: HONEYWELL UK LIMITED, 14a HONEYWELL AEROSPACE BASINGSTOKE, EDISON RD BASINGSTOKE HAMPSHIRE RG21 6QD TEL: +44(0)1256 722200 FAX: +44(0)1256 722201				CAA FORM 1			5. Work Order/Contract/Invoice T41368 347382391 Page 1 of 1	
6. Item 001	7. Description COMPUTER, DIGITAL-DISPLAY UNIT	8. Part No 4091900-942	9. Qty 1	10. Serial No. 40034642	11. Status/Work REPAIRED			
12. Remarks WORK PERFORMED AS DETAILED IN SERVICE REPORT THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: CMM 31-61-82 Rev 8, JUL/21/2022 SB 4091900-31-0005 Rev 1, JAN/26/2016 THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER GENERATED SIGNATURE PROCEDURE MODS: B,C,D,F. THE WORK IDENTIFIED IN BLOCK 11 AND DESCRIBED HEREIN HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH 14 CFR PART 43 AND IN RESPECT TO THAT WORK, THE ITEMS ARE APPROVED FOR RETURN TO SERVICE UNDER CERTIFICATE NO. XYWY939L								
13a. Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in condition for safe operation <input type="checkbox"/> non-approved design data specified in block 12			14a. <input checked="" type="checkbox"/> Part-145, A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature 		14c. Certificate/Approval Ref. No UK.145.00879		
13d. Name		13e. Date (dd mmm yyyy)		14d. Name Andrew Hunt Electronic signature on file		14e. Date (dd mmm yyyy) 29 JUN 2023		

USER/INSTALLER RESPONSIBILITIES
This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulation of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5017586088		347406777	FAA: XYWY939L	EASA: UK.145.00879
PO: T41368	CUSTOMER PART NUMBER:		CONTRACT NUMBER: 440082821	
DATE REJECTED: 01 JUN 2023	DATE RECEIVED: 05 JUN 2023		DATE COMPLETED: 29 JUN 2023	
A/C TYPE: BOEING B737-800	A/C TAIL NUMBER: LY-BJB		A/C SERIAL NUMBER: 29919	
PACKING STATUS: No	SEALS INTACT: Intact		PHYSICAL DAMAGE: No	
REASON FOR REMOVAL: PLEASE QUOTE TO TEST AND RECERTIFY. PLEASE QUOTE TO REPAIR IF IT FAILS TEST. REMOVED IN SERVICEABLE CONDITION FROM A/C REGN: OM-G EX OM-GEX RE REG TO LY-BJB				
PART NUMBER	AS RECEIVED:	AS RELEASED:		
	4091900-942	4091900-942		
DESCRIPTION:	COMPUTER, DIGITAL-DISPLAY UNIT		COMPUTER, DIGITAL-DISPLAY UNIT	
SERIAL NUMBER	40034642		40034642	
UID(MFR/SPL PNO SER/UCN)	58960 40034642		58960 40034642	
HW MOD STATUS:	C,D,F.		B,C,D,F.	
SW MOD STATUS:				
SOFTWARE LOAD:				
REASON FOR REMOVAL CONFIRMED: Failure Not Related to Rejection			ESTIMATE SUPPLIED: Yes	
PRIMARY SHOP FINDING: Fault Found But Uncorrelated Removal			WARRANTY: Warranty Denied	
TYPE OF SERVICE: REPAIRED			TECHNICIAN: Jordan Martyn	
MAINTENANCE STATEMENT: PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.				
SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____				
SIGNATURE OF AUTHORIZED PERSON: _____				
Complied With CMM/Eng Documentation: 31-61-82/Rev 8/Rev Date 21 JUL 2022; Service Bulletins: 4091900-31-0005/Rev 1/Rev Date 26 JAN 2016; Customer Manuals/Documentation:				
SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.				

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5017586088		FAA: XYWY939L	EASA: UK.145.00879
PO: T41368	CUSTOMER PART NUMBER:	CONTRACT NUMBER: 440082821	

Previously Complied With
CMM/Eng Documentation:
Service Bulletins:
Customer Manuals/Documentation:

Evaluation Findings
UNIT FAILED INCOMING EVAL.
DISPLAY OPTICS FAILED.
MOD B (4091900-31-0005) IS REQUIRED.
UNIT TO BE STRIPPED, CLEANED AND INSPECTED.
UNIT TO BE FINAL TESTED TO SPEC.

Work performed / Comments to Customer
NOTE SMALL SCRATCH TO DISPLAY GLASS NON DETRIMENTAL TO UNIT.
NEW BACKLIGHT ASSY AND A4 FITTED INCORPORATING MOD B IAW S.B.
UNIT CLEANED AND PREPARED FOR FINAL TEST.
PRETEST COMPLETED.
FINAL TESTED TO SPEC.
OUTGOING ETI 55421.7 HOURS.

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	Primary Failure	SB
Replace		62001127-1001	CMY230356366	4091894-1002	89937595	1		4091900-31-0005

REPLACE DUE TO FAILING ATEC TEST

Replace		62001128-902	86292108	4091896-902	86088508	1		4091900-31-0005
---------	--	--------------	----------	-------------	----------	---	--	-----------------

REPLACED DUE TO FAILING ATEC TESTING.

MEASUREMENT DESCRIPTION	MEAS. VALUE (DECIMAL)	MEAS. VALUE (HH:MM)
Time Since Repair		0:00
Cycles Since Repair		

RTS TECHNICIAN



DATE 29/6/23