Statements in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance reco the national regulations by the user/installer before the aircraft may be flown.	Where the user/installer performs work in accordance with the national regulations of an airworthiness authority d block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/p specified in block 1.	It is important to understand that the existence of this docume		13d. Name(Typed or Printed): 13e.	13b. Authorized Signature:	Non-approved design data specified in blo	13a. Certifies the items identified above were manufactured in conformity to:		12. Remarks:Certifies that the work specified Part 145 and in respect to that work the commendate Part 145 approval Number: "EASA.145.502 including work instructions used, personnel, time and/or cycles in service (if reported Part 18 PO #980645112/PO W52398 . LAST OPERAT Repaired IAW CMP:73-11-04 Issue: 2 Dated:202 TSN-693.42 H, TSR:0 H, TSO-UNK, CSN-426.00		6. Item: /. Description: VALVE - ASSY FUEL, SUPPLY, COMBUSTOR		Approving Civil Aviation Authority/Country: FAA/United States 2. AUTHO
n all cases, aircraft maintenance reco	Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.	User/Installer Kesponsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.	MARY CRAGER	Date(dd/mmm/yyyy): 14d. Name(Typed or Printed):	May Cry	and described in Blo Federal Regulations, return to service.	14a. X 14 CFR 4		brk specified in block 11/12 was carried out in accordance wit work the component is considered ready for release to servi "EASA.145.5027". See attached repair report for maintenance ed, personnel performing the work, dates of completion, parts (if reported), and customer purchase order number. 1. LAST OPERATOR: AJW STOCK . 2. Dated:2022-03-18, Details on WO: H444751 E: 2 Dated:2022-03-18, Details on WO: H444751			O Book Number.	HORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG
rds must contain an installation certification issued in accordance with NSN: 0052-00-012-9005	ifferent than the airworthiness authority of the country specified in ropeller(s)/article(s) from the airworthiness authority of the country	ft engine/propeller/article.	18/AUG/2023			ck 12 was accomplished in accordance with Title 14, Code of part 43 and in respect to that work, the items are approved for	3.9 Return to Service $ imes imes o$ Other regulation specified in Block 12	TAMESTO STORES OF THE STORES O	service under snance records, parts replaced	1	3WWAF00926 REPA	Number: Inv 5947691 Po 980645112/Po W52398 So 3877370 In Secial Number: 11 Status/Work:	3. Form Tracking Number: 3537179-1

AAC-038 (12/94)	17. NAME (Printed) Name (Printed) MARY CRAGER	4651	16. 批准人签名 Signature	Certifies that the Part(s) identified above block 13, was (were) manufactured/inspected regulations of the stated country and/or in with the approved design data and with the the importing country.	兹声明上述产品除第13项的其它规定以外,已按照国家适航条例进行制造/检查,并且该产品(出口产品)符合经批准的型号设计资料和进口国提出的专用要求	14. 新产品 New Parts	1 VALVE - ASSY FUEL, COMBUSTOR	7.	WOODWARD, INC. 5001 N 2ND ST LOVES PARK, IL USA	4. 单位 Organization	P.R. CHINA	ntry 2.
		08-18-2023	18. 批准日期 Date	Certifies that the Part(s) identified above except as otherwise specified in the block 13, was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.	7、己按照国家适航条例进行制 经批准的型号设计资料和进口国提出的			8. 件号 Part No.	61111-5808		Authorized Release	中国民用航空总局 caac 口符合性 conf 批准放行证书/适航批准标签
*参阅产品目录详细查找适用性 * Cross-check eligibili	F00100102	WEST OF STREET	19. 中国民航总局授权 Issued by or on be		兹声明上述产品除第13项的其它规定外,已按照上述国家适航条例和 进口国通知的特殊要求进行了工作,该产品处于安全可用状态可以批准放 行使用。	15. 使用过的产品 Used Parts	×	9. 适用性 10. 数量 Eliqibility* Oty			Authorized Release Certificate/Airworthiness	Conformity 区适航性 Airworthiness标签
*参阅产品目录详细查找适用性 * Cross-check eligibility for more details with parts catalogue.			behalf of the CAAC	Certifies that the work specified above except as otherwise specified in the block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)	5外,已按照上述国家适航条例和 该产品处于安全可用状态可以批准放		RE	11. 系列号/批号 12. 产品状态 Serial/Batch No Status/Work	Inv. # 5947691	5. 工作单/合同单/货单 Work Order/Contract/Invoice		3. 证书编号 Certific

REPAIR REPORT

SHEET 1 OF 2

UNIT SERIAL NO : 3WWAF00926

WOODWARD, INC.

UNIT ITEM NO : 1023247-2
RECVD ITEM NO : 1023247-2
SALES ORDER NO : 3877370

TIME SINCE REPORTED: NEW 693.42 F.A.A. TAG NO: 3537178-1, 3537179-1

CUSTOMER : HAMILTON SUNDST - A1724629

WORK ORDER NO : H444751

CUSTOMER ORDER NO: 980645112/PO W52398

CYCLES SINCE: NEW 426.00 OVERHAUL N/R

OVERHAUL N/R

REASON CODES

REPAIR N/R

STOCK CODES

N = NEW F = NEWDC = DEPT CHRG

004-REPLACED AT DISASSEMBL 020 - INOPERATIVE/FAILED TES

006-MISSING FROM FIELD

007 - DAMAGED IN FIELD

NE = EXCH/NEW

R = REPAIR RE = EXCHANGE

RK = NOT PICKED

ZZ = NOT PICKED

WORK SCOPE: REPAIR

DESCRIPTION OF REPAIR OR GENERAL REMARKS:

DISASSEMBLED BY : D. PATTON	29-JUN-2023
FINAL TESTED BY : D. PATTON	29-JUN-2023
AS RECV TESTED BY : D. PATTON	29-JUN-2023
VISUAL AS RECV BY : D. PATTON	28-JUN-2023
ASSEMBLED BY : D. PATTON	29-JUN-2023
HCC BY : M. Holcomb	29-JUN-2023
OVERHAULED [] REPAIRED [X] INSPECTED [] TESTED [1
IN ACCORDANCE WITH CMP: 73-11-04 ISSUE: 2 REV DATE: 2	022-03-18
SB'S INCORPORATED: None Required	
PCW: None Required	
AD's / CN's INCORPORATED: None Required	
HONORING WARRANTY ON REMOVAL REASON. REP/CID ON FITTING	;s

1. Approving Civil Aviation 2.			3. 1	3. Form Tracking Number:	er:
Authority/Country: FAA/United States	AUTHORIZED RELIFACE FAA Form 8130-3, AIRWOF	RELEASE CERTIFICATE AIRWORTHINESS APPROVAL TAG		3537179-1	
4. Organization Name and Address: WOODWARD, INC. 5001 N 2ND ST			5. V	5. Work Order/Contract/Invoice Number:	Invoice
LOVES PARK, IL 61111-5808 USA UU2R227L			Inv	5947691 980645112/PO	W52398
6. Item: 7. Description:	8. Par	8. Part Number: 9.			11. Status/Work:
VALVE - ÄSSY FUEL, SUPPLY, C	COMBUSTOR 1023247-2		3WW	3WWAF00926	REPATRED
12. Remarks: Certifies that the work specified Part 145 and in respect to that work the con EASA Part 145 Approval Number: "EASA.145.502 including work instructions used, personnel time and/or cycles in service (if reported)	in bapone 27". perf	out for eport of c	rdance wit to service intenance on, parts	The EASA records, replaced	
HS PO #980645112/PO W52398 Repaired IAW CMP:73-11-04 Issue: TSN-693.42 H, TSR:0 H, TSO- UNK	LAST OPERATOR: AJW STOCK 2 Dated:2022-03-18 , Detail CSN-426.00 C, CSR:0 C, CS	ils on WO: H444751 SO- UNK ,			
		Co	Copy		
3a. Certifies the items identified above were manufactured in conformity to	ctured in conformity to:	14a. X 14 CFR 43.9 Return to Service	Service X	Other regulation specified in Block 12	ed in Block 12
Approved design data and are in a condition for safe operation. Non-approved design data specified in block 12.	condition for safe operation. d in block 12.	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved fo return to service.	ecified in Block 12, complished in accor l in respect to that w	otherwise specified in Block 12, the work identified in Block 11 ck 12 was accomplished in accordance with Title 14, Code of part 43 and in respect to that work, the items are approved for	k 11 of d for
3b. Authorized Signature:	13c. Approval/Authorization No:	14b. Authorized Signature:	4651372	14c.	Approval/Certificate No: CRS# UU2R227L
3d. Name(Typed or Printed):	13e. Date(dd/mmm/yyyy):	or		14e.	Date(dd/mmm/yyyy):
	User/Install	User/Installer Responsibilities		18/A	18/AUG/2023
It is important to understand that the existence of this document alone does not automatically constitute authority to Where the user/installer performs work in accordance with the national regulations of an airworthiness authority did block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/pr	It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.	ly constitute authority to install th rworthiness authority different th epts aircraft engine(s)/propeller(s)	install the aircraft engine/propeller/article. fferent than the airworthiness authority of to opeller(s)/article(s) from the airworthiness.	o install the aircraft engine/propeller/article. Ifferent than the airworthiness authority of the country specified in t	
specified in block 1.				E All WOLUIIIIESS AULIOLIC	try specified in ty of the country

FAA Form 8130-3(02-14)

NSN: 0052-00-012-9005

WOODWARD, INC. 5001 N 2ND ST LOVES PARK, IL 61111-5808 8. 件号 USA 7. 内容 Description Description 1 VALVE - ASSY FUEL, SUPPLY, 102324 COMBUSTOR Remarks See attached repair report f applicable at time of work), time or cycles in service if HS PO #980645112/PO W52398 LAST OPPLY time or cycles in service if HS PO #980645112/PO W52398 LAST OPPLY Repaired IAW CWE:73-11-04 Issue: 2 Dated: TSN-693.42 H, TSR:0 H, TSO- UNK , CSN-426 Wash Law Cwe:73-11-04 Issue: 2 Dated: TSN-693.42 H, TSR:0 H, TSO- UNK , CSN-426 Wew Parts Wew Parts Wew Parts Wew Parts Were manufactured inspected in accordance regulations of the stated country and/or in the case of not block is, was (were manufactured inspected in accordance regulations of the stated country and/or in the case of not block is, was (were manufactured inspected in accordance regulations of the stated country and/or in the case of not block is, was (were manufactured inspected in accordance regulations of the stated country and/or in the case of not block is, was (were manufactured inspected in accordance regulations of the stated country and/or in the case of not block is, was (were manufactured inspected in accordance regulations of the stated country and/or in the case of not block is, was (were manufactured inspected in accordance regulations of the stated country and/or in the case of not block is, was (were manufactured inspected in accordance regulations of the stated country and/or in the case of not block is, was (were manufactured inspected in accordance regulations of the stated country and/or in the case of not block is, was (were manufactured in accordance regulations of the stated country and/or in the case of not block is a state of the stated country and/or in the case of not block is a state of the stated country and or in the case of not block is a state of the stated country and or in the case of not block is a state of the stated country and or in the case of not block is a state of the stated is a state of the stated is a state of th		woodward.		CHINA	Country	国家
61111-5808 61111-5808 ached repair reble at time of cycles in serv O W52398 LAN L1-04 Issue: 2 14, TSO- UNK , Cit ified above except red/inspected in accord and with the notifit of the cand with the cand with the notifit of the cand with the cand with the cand with the can	INC.			Author	批准放行	2. 中国民用航空总局
personnel reported, RATOR: AJW 2022-03-18 .00 C, CSR: H #			30	Authorized Release Certificate/Airworthiness	批准放行证书/适航批准标签	CAAC 符合性 c
正自由性 Eligibil OT KNOWN (in forming wo parts rep ctails on the iness			PTOVAT TAY	Certificate/	終	Conformity 区 适航性
Inv. # I				Airworthines		他 Airworthiness
Inv. # 5947691 10. 数量	5. 工作甲/合同甲/货甲 Work Order/Contract/Invoice		л	3537178-1	Certificate Ref No	3.



WOODWARD

PHONE: 815-877-7441 LOVES PARK, IL 61111 US FAX: 1-815-639-6048 N. SECOND S

CERTIFICATE OF CONFORMANCE

PO #	COC DATE	COC		
: 980645112/PO W5239	: 18-AUG-2023	:5947691	18-AUG-2023	1 4 2

A1724629 Tim Earlywine ACCOUNT 980645112/PO W52398 FREIGHT		
Earlywine 645112/PO W52398	2462	_
	1	

CUSTOMER

DATE CHANGED CHANGE # DATE ENTERED SALES ORDER #

: 18-AUG-2023

: 58

26-JUN-2023 3877370

CUSTOMER

CONTACT ORDER #

CONTRACT # PURCHASE ORDER

IPR SUSPEN. # PAYMENT TERMS

60 DAYS NET

SHIP TO: Sales Order -3877370 CoC - 5947691 DESTINATION

BTW/VAT #

RECIPIENT

124277507

FCA ROCKFORD

FEDEX INTERNATIONAL

PRIORITY

: 01

PLANT : 01

MAYDWELL AVENUE THE HEADQUARTERS A J WALTER AVIATION ATTN:

SLINFOLD RH13 OAS

WINDSOR LOCKS CT 06096-1010

ONE HAMILTON ROAD MAIL STOP 1-1-B45 ATTN: MELODY MONACCHIO HAMILTON SUNDSTRAND -CUSTOMER SOLD TO:

CARE PROGRAM

ATTN: BILL TO:

MAIL STOP 542-23 ACCOUNTS PAYABLE PHOENIX AZ 85082 PO BOX 61930 HAMILTON SUNDSTRAND

FAA FORM 8130-3 REQUIRED - INCLUDE EASA PART 145 RELEASE TO SERVICE STATEMENT IN BLOCK 12: NOTE CMM #, REVISION AND DATES. ALSO REF HS PO #980645112/PO W52398 ALSO INCLUDE IN BLOCK 12: ALL TIME AND CYCLE INFO, IF LISTED ALSO INCLUDE IN BLOCK 12 OF 8130 LAST OPERATOR: AJW STOCK CAAC REQUIRED - INCLUDE ALL INFO IN BLOCK 12 OF 8130 ON CAAC

UNITED KINGDOM

COUNTRY OF ORIGIN: USA

LAST SHIPPED 08-AUG-2022
REMOVAL REASON: RFR-MEL ENG 2 FADEC MAINTENANCE
BENCH TEST & REPAIR AS REQUIRED
PROGRAM NAME: NEO - AJ WALTER ENG2A-0281-FLOW DV VLV SOL ELEC FAIL

"THESE ITEMS ARE CONTROLLED BY THE U.S. GOVERNMENT AND AUTHORIZED FOR EXPORT ONLY TO THE COUNTRY OF ULTIMATE DESINATION FOR USE BY THE ULTIMATE CONSIGNEE OR END-USER(S) HEREIN IDENTIFIED. THEY MAY NOT BE RESOLD, TRANSFERRED, OR OTHERWISE DISPOSED OF TO ANY OTHER COUNTRY OR TO ANY PERSON OTHER THAN THE AUTHORIZED ULTIMATE CONSIGNEE OR END-USER(S), EITHER IN THEIR ORIGINAL FORM OR AFTER BEING INCORPORATED INTO OTHER ITEMS, WITHOUT FIRST OBTAINING APPROVAL FROM THE U.S. GOVERNMENT OR AS OTHERWISE AUTHORIZED BY U.S. LAW AND REGULATIONS."

IF UNIT WAS REPAIRED, PLEASE RESET TSR/CSR TO TSN-693.42 H, TSR- UNK, TSO- UNK, CSN-426.00 Investigate per Investigation 1189542. 00 CSR-UNK, CSO-

P.O.

PART NUMBER

ITEM DESCRIPTION

REQUESTED DUE DATE DATE

UNK

ALO



SALES ORDER # : 3877370 CHANGE # DATE ENTERED : 58 : 26-JUN-2023

WOODWARD, INC.
5001 N. SECOND ST
PHONE: 815-877-7441 LOVES PARK, IL 61111 US FAX: 1-815-639-6048

CERTIFICATE OF CONFORMANCE



18-AUG-202

PLANT: 01 B/U: 26 : 980645112/PO W52398 : 18-AUG-2023 :5947691 SHIP PLANT : 01

P.O. LINE FFX/NUMBER

ORDER TYPE

DATE CHANGED

: 18-AUG-2023

: REP

CUSTOMER PART NUMBER

ITEM DESCRIPTION

REQUESTED DUE DATE DATE

YTO

00010 1023247-2

SERIAL NUMBER(S): 3WWAF00926

ASSY FUEL, SUPPLY, COMBUSTOR 28-AUG-2023 28-AUG-2023

VALVE -

HSN Code: 8481.80.9015 NO ECCN: 9A991.d

applicable chemical, physical, and functional are in a condition for safe operation. The maintained in accordance with all applicable ACCOMPLISHED IN ACCORDANCE WITH FAA APPROVED REPAIR STATION at Woodward Inc. requirements are on file and subject to review specifications and approved type design data, and to certify that the parts herein described were the requirements of your purchase order, this is CERTIFICATION STATEMENT "E": In accordance with MANUAL 1-QCI-01000 FOR REPAIR STATION NO. UU2R227L (ROCKFORD FACILITY) WOODWARD INC. ON AIRCRAFT PRODUCTS ARE "ALL MAINTENANCE, INSPECTION, AND REPAIRS PERFORMED BY

WOODWARD, INC. REPRESENTATIVE

SIGNATURED Hel Cumb

PRINTED NAME / Holums

08/18/2023

May Oran 08/18/2013 INSPECTOR Mary Crager

UNLESS OTHERWISE AUTHORIZED BY THE UNITED STATES GOVERNMENT. UNITED STATES LAW PROHIBITS DISPOSITION OF THESE COMMODITIES TO: CUBA, DEMOCRATIC P.R. OF KOREA, IRAN, ISLAMIC REPUBLIC OF, LIBYAN ARAB JAMAHIRIYA, RUSSIA, SUDAN, SYRIAN ARAB REPUBLIC

3. Form Tracking Number: 3537179-1	>= >	PO 980645112/PO W52398 SO 3877370 10. Serial Number: 11. Status/Work: 3wwaf00926 REPAIRED	with EASA Vice under ce records, ts replaced		Other regulation specified in Block 12 12, the work identified in Block 11 cordance with Title 14, Code of	it work, the items are approved for	
THORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		Part Number: 9. Quantity:	rdance to ser intenan		Certifies that unless otherwise specified in Block 12, the work identified in Block 11 was accomplished in accordance with Title 14, Code of	return to service. 14b. Authorized Signature:	1
AUTHORIZED REL FAA Form 8130-3, AIRWOI		COMBUSTOR 1023247-2	specified in book the componer ASA.145.5027". Personnel perfor reported), an AST OPERATOR: Proposed CSN-426.00 C, C		tion.	13c. Approval/Authorization No:	13e. Date(dd/mmm/yyyy):
FAA/United States 6. Organization Name and Address:	500 LOV USA	O. 10m: 7. Description: 1 VALVE - ASSY FUEL, SUPPLY, COM	Part 145 and in respect to that work specified in block 11/12 was carried out in acconstant 145 and in respect to that work the component is considered ready for release including work instructions used, personnel performing the work, dates of completing. Hs PO #980645112/PO W52398 . LAST OPERATOR: AJW STOCK . Repaired IAW CMP:73-11-04 Issue: 2 Dated:2022-03-18, Details on WO: H444751 TSN-693.42 H, TSR:0 H, TSO-UNK, CSN-426.00 C, CSR:0 C, CSO-UNK,	Certifies the items identified above were manufactured in conformity to-	Approved design data and are in a condition for safe operation. Non-approved design data specified in block 12.	Authorized Signature:	L. Name(Typed or Printed): 13e. Date(dd/mmm/yyyy): 14d. Name(Typed or Printed): MADV CDAGTE

Statements in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with

FAA Form 8130-3 (02-14)

NSN: 0052-00-012-9005 Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country

NSN: 0052-00-012-9005

WOODWARD, INC.

REPAIR REPORT

SHEET 1 OF 2

UNIT SERIAL NO : 3WWAF00926 UNIT ITEM NO

CUSTOMER WORK ORDER NO

: HAMILTON SUNDST - A1724629

: 1023247-2 RECVD ITEM NO : 1023247-2

: H444751

CYCLES SINCE : NEW OVERHAUL N/R REPAIR N/R

TIME SINCE REPORTED: NEW __693.42 F.A.A. TAG NO: 3537178-1, 3537179-1

SALES ORDER NO : 3877370

REPAIR N/R

STOCK CODES

N = NEW F = NEW

004-REPLACED AT DISASSEMBL 006-MISSING FROM FIELD

REASON CODES

007 - DAMAGED IN FIELD

NE = EXCH/NEW R = REPAIR

DC = DEPT CHRG

020 - INOPERATIVE/FAILED TES

RE = EXCHANGE RK = NOT PICKED ZZ = NOT PICKED

DESCRIPTION OF REPAIR OR GENERAL REMARKS:

DISASSEMBLED BY : D. PATTON	
FINAL TESTED BY : D. PATTON	29-JUN-2023
AS RECV TESTED BY : D. PATTON	29-JUN-2023
VISUAL AS RECV BY : D. PATTON	29-JUN-2023
ASSEMBLED BY : D. PATTON	28-JUN-2023
HCC BY : M. Holcomb	29-JUN-2023
OVERHAULED [] REPAIRED [X] INSPECTED [] TESTED []	29-JUN-2023
IN ACCORDANCE WITH CMP: 73-11-04 ISSUE: 2 REV DATE: 2022-03-18	
SB'S INCORPORATED: None Required	

PCW: None Required

AD's / CN's INCORPORATED: None Required

HONORING WARRANTY ON REMOVAL REASON. REP/CID ON FITTINGS

WORK SCOPE: REPAIR