

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: W40088	
4. Organization Name and Address: PRECISION AERO TECHNOLOGY 3333 EAST SPRING STREET SUITE 300 LONG BEACH, CA 90806 UNITED STATES		FAA Certificate : DQ3R458L		5. Work Order/Contract/Invoice Number: 8211091	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	AURAL WARNING BOX	65-54499-23	1 EA	D00719	REPAIRED
12. Remarks: Referencing manual No. 31-26-01 Revision: 029 Revision Date: JAN 14 2010 Full details of work carried out are in the work order number found in Block 5.					

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA 145.4052".


13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.
☐ Non-approved design data specified in Block 12.

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

14b. Authorized Signature: 

14c. Approval/Certificate No.: **DQ3R458L**

14d. Name (Typed or Printed): **Richard Bermudez**
 14e. Date (dd/mm/yyyy): **31/Aug/2017**

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



PRECISION AERO TECHNOLOGY

3333 EAST SPRING STREET
SUITE 300
562-595-6055

LONG BEACH CA 90806
UNITED STATES
562-595-8416

www.pat-pag.com

WORK ORDER REPORT

Page: 1 of 1

Close	:		Incoterms : Account No. [A14148]	
Abnormal/PH	:		AJ WALTER AVIATION LTD	
Normal	:		THE HEADQUARTERS	
Technician	:	LAURENTIU GEORGESCU	MAYDWELL AVENUE	
Inspector	:	RICHARD BERMUDEZ	SLINFOLD, WEST SUSSEX RH13 0AS	
Aircraft Number	:		UNITED KINGDOM	
A/C Position	:		Tel. : 1-403-711777	
TSN	:		Fax : -1-403-710936	
TSO	:			
TSR	:			
For Customer	:	AJ WALTER AVIATION LTD		
S.O. No.	:	8212468	Line No. : 1	
Cust P.O.	:	W40088	P/N : 65-54499-23	Note :
Our Ref	:	LINDA	Desc : AURAL WARNING BOX	Trace To :
Stock	:		S/N : D00719	Tag Date :
Shop	:	DIVISION 1	MFG :	Manual : 31-26-01
Warr Claim	:	Yes	Qty : 1	Revision : 029 / Jan-14-2010
Completed P/N	:	65-54499-23	S/N As : D00719	Into Bin Loc :
Company	:	1	Division : 08	Department :
Order Date	:	Aug-16-2017	Received Date : Aug-16-2017	Due Date : Aug-23-2017
				Print Date : Aug-31-2017

WORK ORDER No. 8211091

Reported By Customer

PLEASE CONSIDER FOR WARRANTY DEFECT FIRE BELL WEAK

Preliminary Insp.

RECEIVED UNIT IN FAIR CONDITIONS WITH PAT WARRANTY SEAL INTACT. PRELIMINARY INSPECTION SHOWS NO FAILURE.

Corrective Action

DISASSEMBLED AND INSPECTED UNIT: NO PROBLEM FOUND. HOWEVER, PRECAUTIONARY REMOVED BELL ASSEMBLY, CLEANED AND LUBRICATED MOBILE PIN, CLEANED AND TENSIONED ELECTRICAL SPRING CONTACT AND CALIBRATED BELL OUTPUT SOUND. REASSEMBLED UNIT, RAN FUNCTIONAL TEST PROCEDURE AND VERIFIED TO MEET THE TECHNICAL SPECIFICATIONS. THE ABOVE MENTIONED WORK WAS PERFORMED I.A.W. C.M.M. 31-26-01.

A/D's and S/B's

SERVICE BULLETINS INSTALLED : NONE.

Authorized Signature

Copyright (c) PENTAGON 2000 Software, Inc.

Rev 2 (2000.2.12.07) Ver 1.00.03 Build 03