



Oakenhurst Aircraft Services Ltd  
Claydons Lane  
Rayleigh, Essex  
SS6 7UP  
United Kingdom  
Tel: +44 (0)1268741622

EASA Part 145: UK.145.00524

FAR 145: O5KY452Y

## Workshop Report

No: **IR12144**

Issue: **01**

Date: **06-May-15**

AJW Aviation  
The Headquarters  
Maydwell Avenue  
Slinfold  
West Sussex  
RH13 0AS  
United Kingdom

Attn: Mr Dan Macdonald

Tel: 0044 (0) 1403 798000 Fax:

E-Mail: dan.macdonald@ajw-aviation.com

Your Ref: R263135

Our Ref No: WP12146

Test Required: N/A

Part No: 45-0339-11

Description: Aircraft Controllable Search Light

TSN: N/A

CSN: N/A

Serial No: 0049

Workscope: Electrical Repair

TSO: N/A

CSO: N/A

Removed From:

Serial No:

Reg No:

Position:

### Inspection Findings:

Unit received in average condition. Reported defect of does not extend or retract is confirmed. Fault traced to u/s motor assembly. Unit requires replacement motor assembly and testing to full manufacturers specification. Unit repaired and tested to specification. Unit conforms with maintenance data criteria.

Signed: 

Name: S. LABDON

Date: 13/08/15

For and on the behalf of Oakenhurst Aircraft Services Ltd

Registered address:- Claydons Lane, Rayleigh, Essex, SS6 7UP

1. Approving Competent Authority/Country  
CAA / United Kingdom

2.

# AUTHORISED RELEASE CERTIFICATE EASA FORM 1

3. Form Tracking Number  
ARC13367

4. Organisation Name and Address



Oakenhurst Aircraft Services Ltd  
Claydons Lane  
Rayleigh, Essex  
SS6 7UP  
United Kingdom  
Tel: +44 (0)1268741622  
Fax:  
Email: sales@oakenhurst.com  
Web: www.oakenhurst.com

5. Work Order/Contract/Invoice

WP12146 / R263135

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	Aircraft Controllable Search Light	45-0339-11	1	0049	Repaired

## 12. Remarks

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. O5KY452Y.  
TCCA Certificate No: 807-10  
IN ACCORDANCE WITH MANUFACTURERS MANUAL No: 33-42-23 Revision 1, Dated: 15th October 2006.

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in condition for safe operation  
☐ Non-approved design data specified in block 12

14a. ☒ Part-145 A.50 Release to Service ☒ Other regulation specified in block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature

14b. Authorised Signature

26

14c. Certificate/Approval Ref. No.  
UK.145.00524

13d. Name

14d. Name

Mr Stephen Labdon

AVW 26

14e. Date (dd mmm yyyy)  
06 Aug 2015

## USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).  
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.  
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.