

1. Approving Competent Authority/Country CAA/UNITED KINGDOM		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number. 246740	
4. Organisation Name and Address. MUIRHEAD AEROSPACE LIMITED T/A MUIRHEAD AVIONICS 3 Square One Heathrow Southall Lane Southall, Middlesex, UB2 5NH, UK Ph: +44(0) 20 8571 3422, Fax: +44 (0) 20 8571 2336		5. Work Order/Contract/Invoice Work Order No: IA20758 Customer Order No: T33873		6. Item 1 D.C. VOLTMEETER	
7. Description D.C. VOLTMEETER		8. Part No. 206PN01		9. Qty. 1	
10. Serial No. 2181		11. Status/Work Repaired		12. Remarks MODS OBSERVED ON IDENT PLATE:C Manual ID: 24-30-02 (ECE 216), Revision #: 6, Revision Date: 15/05/2011 14 CFR 43.9 Return to Service The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. H9EY443N Date(m/d/y): Dec/24/2020 Signed: 	
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation. ☐ non-approved design data specified in block 12		14a. ☒ Part-145 A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		14b. Authorised Signature  14c. Certificate/Approval Ref No. UK.145.00592	
13b. Authorised Signature: 		13c. Approval/Authorisation No.		14d. Name JD PEARCE	
13d. Name		13e. Date (dd mmm yyyy)		14e. Date (dd mmm yyyy) 24 Dec 2020	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Muirhead Aerospace Limited

Contact Name: Customer Services

Telephone:

Fax:

Tear Down/Inspection

Work Order #: IA20758

Date Printed: 24-Dec-20

Work Type: Inspected/Tested

Page: 1

To:

AJ WALTER (AVIATION) LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX RH13 0AS
UK

Ship To:

AJ WALTER (AVIATION) LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX, RH13 0AS UK

Cust.PO Ref.: T33873

Cust.Phone: 01403 711777

Cust.Email:

Cust.Code: 200382

Cust.Fax: 01403 712135

Station: SOUTH

Part No. In: 206PN01

Description: D.C. VOLTMETER

Qty: 1

Part No. Out: 206PN01

Serial No: 2181

Previous WO No:

Documentation: 24-30-02 (ECE 216)

Location: ECE 216

ATA No: 24-30-02

Rev. & Date: 6 15-May-2011

Symptoms:

Repair report REPORTED DEFECT:-

No defect reported

VISUAL INSPECTION:-

LCD shows signs of leakage

FUNCTIONAL TEST RESULTS:-

Unit fails functional testing phase

FINDINGS / CORRECTIVE ACTIONS:-

Unit hasn't been subjected to customer induced damage

LCD shows signs of leakage & segment Inop (Photo's taken)

Replaced LCD Display to address observed defect

Unit visually inspected, assembled and tested satisfactory to full spec

MODS EMBODIED:-

Nil

MOD PLATE STATUS:-

C

Inspection Signature:

Stamp:

Inspect. Print Name:

YUSUF ABDUCAHI