



61995495

3. Form Tracking Number

21994902 00000001

AUTHORISED RELEASE CERTIFICATE EASA FORM 1

 **Lufthansa Technik**

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

4. Organisation Name and Address:

9. Qty. 10. Serial No.

11. Status / Work

REPAIRED

043H00000446

Workshop Station FRA025

Resp. Workshop 33512012

Pack Code 00

MK-No. 20

TP R
AMD. A,B

A.J. Walter (Aviation) Ltd. T41917

Return to Service in Accordance with 14 CFR part 43

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under

FAA Certificate No.: DLAY225D

TCCA Approval No.: 897-08

☒ Further details of work performed are attached either in a Workshop Report reference number see blocks 3 and 5 or in other applicable documents

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in a condition for safe operation

14a. ☒ Part-145.A.50 Release to Service

☒ Other Regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature

13c. Approval / Authorisation Number

14b. Authorised Signature

14c. Certificate / Approval Ref. Number

DE.145.0001

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

14e. Date (dd mmm yyyy)
25 Sep 2023

Heinz Heller

EASA FORM 1 - Issue 3


USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

LHT Form 30800 I-23 (HAM TQ A)




61995495

1. Approving Competent Authority / Country CAA UK		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number 21994902 00000001																
4. Organisation Name and Address  Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany				5. Work Order / Contract / Invoice 61995495																
6. Item 01	7. Description DECODER ENCODER UNIT B	8. Part No. Z043H000050A	9. Qty. 1	10. Serial No. 043H00000446	11. Status / Work REPAIRED															
12. Remarks ATA 2300 TP R MK-No. 20 Pack Code 00 AMD. A,B A.J. Walter (Aviation) Ltd. T41917 <table><tr><td>Opr. Hours</td><td>Cycle</td><td>Opr. Day</td></tr><tr><td>UNKNOWN</td><td>UNKNOWN</td><td>UNKNOWN</td></tr><tr><td>UNKNOWN</td><td>UNKNOWN</td><td>UNKNOWN</td></tr><tr><td>UNKNOWN</td><td>UNKNOWN</td><td>UNKNOWN</td></tr><tr><td>0</td><td>0</td><td>0</td></tr></table> TASK PERFORMED IN ACCORDANCE WITH CMM 23-77-47 REV. 11 / CMDS 23-77-47 ISSUE 012 Resp. Workshop 33512012 Workshop Station FRA025						Opr. Hours	Cycle	Opr. Day	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	UNKNOWN	0	0	0
Opr. Hours	Cycle	Opr. Day																		
UNKNOWN	UNKNOWN	UNKNOWN																		
UNKNOWN	UNKNOWN	UNKNOWN																		
UNKNOWN	UNKNOWN	UNKNOWN																		
0	0	0																		
☒ Further details of work performed are attached either in a Workshop Report reference number, see block 3 and 5 or in other applicable documents.																				
13a. Certifies that the items identified above were manufactured in conformity to: <table><tr><td>☐ approved design data and are in a condition for safe operation</td><td>☐ non-approved design data specified in block 12</td></tr></table>						☐ approved design data and are in a condition for safe operation	☐ non-approved design data specified in block 12													
☐ approved design data and are in a condition for safe operation	☐ non-approved design data specified in block 12																			
13b. Authorised Signature		13c. Approval / Authorisation Number		14a. ☒ Part -145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.																
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature 434171																
				14c. Certificate / Approval Ref. Number UK.145.01408																
				14d. Name Heinz Heller																
				14e. Date (dd mmm yyyy) 25 Sep 2023																

Note: This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report



Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Customer Order No. T41917	61995495 Certificate Ref. No. 21994902 00000001	
Part No. as received Z043H0000050A	Serial No. as received 043H000000446	Work Order/Contract/Invoice 61995495
Part No. as dispatched Z043H0000050A	Serial No. as dispatched 043H000000446	Description DECODER ENCODER UNIT B
Reason for removal PLEASE QUOTE TO TEST AND RECERTIFY. PLEASE QUOTE TO REPAIR IF IT FAILS TEST REMOVED IN SERVICEABLE CONDITION FROM A/C REGN: A6-ERE		Responsible Workshop 33512012
Findings FOUND UNIT WITH TWO BROKEN FASTENERS ON DUE-B HOUSING. NO FURTHER ERRORS DETECTED DURING TEST RUN.		Modification Status according to Mod-Label See Unit Mod-Label if equipped
Action REPLACED BROKEN FASTENERS ON DUE-B HOUSING. SEVERAL TESTS PERFORMED IN COLD AND WARM CONDITION. UNIT PASSED ALL TESTS IN ACCORDANCE TO CMM.		
The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.		Name 434171, Heinz Heller
LHT Form 30992 H-19) (HAM T/CE-Q)		Date (dd mm yyyy) 25 Sep 2023

RFID-Smartlabel

61995495



Ident-Tag Barcode

Ident-Tag



Lufthansa Technik

Form Tracking Number
21994902 00000001

Work Order / Contract / Invoice

Description
DECODER ENCODER UNIT B

Part. No.
Z043H000050A

Eligibility

Quantity
1

Status / Work
REPAIRED

Serial-/Batch No.
043H00000446

Remarks

TP R MK-No. 20
FSCM C6253 ATA 2300

Resp. Workshop 33512012 Workshop Station FRA025

AMD. A,B

Packaging Code: 00

Installed on (Information is only required in case of installation only)

PNR NHA

SNR NHA

Position/FIN No. NHA

Station

A/C-Registration

Removed

PNR¹

SNR¹

Position/FIN No.¹

Station¹

A/C-Registration¹

Unit Barcode No.

Removed from NHA (Information is only required in case of part change on next higher assy)

PNR NHA

SNR NHA

Position/FIN No. NHA

Reason for Removal¹

☐ 22 Unscheduled

Complaint No.¹ or WO-Reference¹

☐ 11 Scheduled

Failure Description¹ (Please write in capital letters only)

CCI-ID²

Stamp or ID Number + Signature^{1/2}

Date¹

Special Investigation Tag exists ☐ Yes

Please send back to:(unless other return location is agreed)

LUFTHANSA TECHNIK AG
c/o Lufthansa Technik Logistik Services GmbH
Warenannahme / Goods Receiving
RHEIN-MAIN FLUGHAFEN
60549 FRANKFURT
Deutschland

(LTLS-Information: Use this box for ZID)

¹ Mandatory entries without using CCI-Mask

² Mandatory entries using CCI-Mask