

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES	2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIR WORTHINESS APPROVAL TAG	3. Form Tracking Number: 356834-22A			
4. Organization Name and Address: Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300		5. Work Order/Contract/Invoice Number: 356834 / 86491			
6.Item:	7. Description:	8. Part Number:	9. Quantity:	10.Serial Number:	11.Status/Work:
1	VBV ACTUATOR	1211318-006	1	APMPF094	OVERHAULED
12.Remarks:OVERHAULED IAW CMM ATA 75-32-02 REV: 08 DATE: 08/16/2019 C/W FED-EX POSH M-75-32-01 REV 00 DATED 05/17/2010 TSO-0 CSO-0 ESN:706242 THIS FAA FORM 8130-3 CORRECTS THE ERROR(S) IN BLOCK(S) 12 OF THE FAA FORM 8130-3 # 356834-22 DATED 5 MAY 2022 AND DOES NOT COVER CONFORMITY/CONDITION/RELEASE TO SERVICE. Certifies that the work specified in block 11/12 was carried out in accordance with EASA part 145 and, with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number: EASA 145.5893					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in Block 12.					
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12	
13d. Name (Typed or Printed)		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: 	
13c. Approval/Authorization No.:		14c. Approval/Certificate No.:		14d. Name: (Typed or Printed) Randy Jaskolski	
13d. Name (Typed or Printed)		13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 10 MAY 2022	
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.					
FAA Form 8130-3 (02-14)				NSN: 0052-00-012-9005	

1. 国家 CHINA		2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness		3. 证书编号 Certificate Ref. No. 356834-22A	
4. 单位 Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300		5. 工作单/合同单/货单 Work Order/Contract/Invoice Number: 356834 / 86491			
6. 序号 Item:	7. 内容 Description:	8. 件号 Part Number:	9. 适用性 Eligibility:*	10. 数量 Quantity:	11. 系列号/批号 Serial/Batch Number:
1	VBV ACTUATOR	1211318-006	NOT KNOWN	1	APMPF094
13. 备注 OVERHAULED IAW CMM ATA 75-32-02 REV: 08 DATE: 08/16/2019 C/W FED-EX POSH M-75-32-01 REV 00 DATED 05/17/2010 Remarks: TSO:0 CSO:0 ESN:706242					
14. 新产品 New Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例进行制造/检查, 并且该产品 (出口产品) 符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the Parts(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.			15. 使用过的产品 Used Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例和特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in Block 13, the work was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the parts(s) is (are) in condition of safe operation and considered ready for release to service. (over)		
16. 批准人 Signature:		18. 批准日期 Date		19. 中国民航总局授权 Issued by or on behalf of the CAAC F00100391	
17. 批准人姓名 (打印的) Name (Printed)		Randy Jaskolowski			

AAC-038(12/94)

*参阅产品目录详细查找

*Cross-check eligibility for more details with parts catalogue

批准放行证书/适航批准标签

AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG

使用者/安装者职责

USER/INSTALLER RESPONSIBILITIES

- (1) 必须明确：本文件并不批准零件/组件可以装到有关产品上。
- (2) 当使用者/安装者使用的是所在国适航当局的条例，而不是本表第 1 项中所指国家适航当局的条例时，使用者/安装者必须保证所在国的适航当局能接受所指国家适航当局批准出口的零件/组件/部件。
- (3) 表中第 14 项、第 15 项的陈述，并不说明本表是安装批准。在所有情况下，航空器使用前，航空器使用者/安装者应把按本国适航条例颁发的安装批准放入维修记录中。

- (1) It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.
- (2) Where the user/installer works in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1 it is essential that the user/installer ensure that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.
- (3) Statements 14 and 15 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.

WORK ORDER FORM 100

Page No. 1



Work Order: 356834-22

Triumph Accessory Services -Grand Prairie

1038 Santerre Drive
Grand Prairie, TX 75050-1937
972/623-9300 FAX (972) 660-1580
FAA CRS No: GPYR474X

CAAC CRS No: F00100391

Customer: 070443 / GA TELESIS, LLC

Dept#: FVA

Cust RO#: 86491

Step: INVOICED

Warranty Code: NW Qty: 1

Work Req: OH

P/N: 1211318-006 / VBV ACTUATOR

S/N: APMPF094

Mfg: ARKWIN

Manual#: 1211218 RevDate: 08/16/2019 Rev#: 08 ATA: 75-32-02

OH , COMPLY W/ FEDEX POSH M-75-32-01

***** COMPLY WITH CUSTOMER P.O. REQUIREMENTS *****

Date Recvd: 03/31/2022 Date Reqr'd: / / Date Estmtd: 04/29/2022

PRELIMINARY INSPECTION: DATE: 04/01/2022 TECH: Leonardo Saldivar (esign)
NO VISIBLE ISSUES NOTED PRIOR TO CLEANING
NO A.D.'S

TEARDOWN FINDINGS:

100% KIT REQUIRED

ID PLATE WORN REQUIRES REPLACEMENT

O/H IAW ATA:75-32-02 REV.08 DTD:08/16/19

C/W FED-EX POSH M75-32-01 REV.00 DTD:05/17/10

TECHNICIAN: Brian Hall (esign) DATE: 04/08/2022

CORRECTIVE ACTION:

UNIT OVERHAULED IAW ATA 75-32-02 REV 08 DATED 08/16/2019

C/W FED-EX POSH M-75-32-01 REV 00 DATED 05/17/2010

100% KIT INSTALLED

ID PLATE INSTALLED

* OVERHAULED IAW CMM ATA 75-32-02 REV: 08 DATE: 08/16/2019

*C/W FED-EX POSH M-75-32-01 REV 00 DATED 05/17/2010

*TSO:0 CSO:0 ESN:706242

*THIS FAA FORM 8130-3 CORRECTS THE ERROR(S) IN BLOCK(S) 12 OF THE

*FAA FORM 8130-3 # 356834-22 DATED 5 MAY 2022 AND DOES NOT COVER CONFO
RMITY/CONDITION/RELEASE TO SERVICE.

TECHNICIAN: Austin Barnett (esign) DATE: 04/27/2022

Test Technician: Bradley A. Barker (esign) DATE: 05/03/2022

Supervisor: Chris Gist (esign) DATE: 05/04/2022

Final Inspection: Randy Jaskolowski (esign) DATE: 05/05/2022



1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 356834-22	
4. Organization Name and Address: Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300				5. Work Order/Contract/Invoice Number: 356834 / 86491	
6.Item:		7. Description:		8. Part Number:	
1		VBV ACTUATOR		1211318-006	
9. Quantity:		10.Serial Number:		11.Status/Work:	
1		APMPF094		OVERHAULED	
12.Remarks:OVERHAULED IAW CMM ATA 75-32-02 REV: 08 DATE: 08/16/2019 C/W FED-EX POSH M-75-32-01 REV 00 DATED 05/17/2010 TSO:0 CSO:0 ESN:V98391					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA part 145 and, with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number: EASA 145.5893					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in Block 12.					
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☐ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12	
13d. Name (Typed or Printed)		13e. Date (dd/mm/yyyy):		14b.. Authorized Signature: 	
				14c. Approval/Certificate No.: GPYR474X	
				14d. Name: (Typed or Printed) Randy Jaskolowski	
				14e. Date (dd/mm/yyyy): 05 MAY 2022	

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.

Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.

1. 国家 CHINA		2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness		3. 证书编号 Certificate Ref. No. 356834-22	
4. 单位 Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300		5. 工作单/合同单/货单 Work Order/Contract/Invoice Number: 356834 / 86491		6. 序号 Item:	
7. 内容 Description:		8. 件号 Part Number:		9. 数量 Quantity:	
10. 适用性 Eligibility: *		11. 系列号/批号 Serial/Batch Number:		12. 产品状态 Status/Work:	
13. 备注 OVERHAULED IAW CMM ATA 75-32-02 REV: 08 DATE: 08/16/2019 C/W FED-EX POSH M-75-32-01 REV 00 DATED 05/17/2010 Remarks: TSO-9 CSO-9 ESN: V98391		14. 新产品 New Parts		15. 使用过的产品 Used Parts	
16. 批准人 Signature:		17. 批准日期 Date		18. 中国民航总局授权 Issued by or on behalf of the CAAC F00100391	
17. 批准人姓名 (打印的) Name (Printed)		Randy Jaskolowski			

AAC-038(12/94)

*参阅产品目录详细查找记录

*Cross-check eligibility for more details with parts catalogue

批准放行证书/适航批准标签

AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG

使用者/安装者职责

USER/INSTALLER RESPONSIBILITIES

- (1) 必须明确：本文件并不批准零件/组件/部件可以装到有关产品上。
 - (2) 当使用者/安装者使用的是所在国适航当局的条例，而不是本表第 1 项中所指国家适航当局的条例时，使用者/安装者必须保证所在国的适航当局能接受所指国家适航当局批准出口的零件/组件/部件。
 - (3) 表中第 14 项、第 15 项的陈述，并不说明本表是安装批准。在所有情况下，航空器使用前，航空器使用者/安装者应把按本国适航条例颁发的安装批准放入维修记录中。
- (1) It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly.
 - (2) Where the user/installer works in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1 it is essential that the user/installer ensure that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.
 - (3) Statements 14 and 15 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.

WORK ORDER FORM 100

Triumph Accessory Services -Grand Prairie
1038 Santerre Drive
Grand Prairie, TX 75050-1937
972/623-9300 FAX (972) 660-1580
FAA CRS No: GPYR474X

Page No. 1



Work Order: 356834-22

Customer: 070443 / GA TELESIS, LLC

Cust RO#: 86491

Work Req: OH

Step: SHOP COMPLETE

CAAC CRS No: F00100391

Dept#: FVA

Warranty Code: NW Qty: 1

P/N: 1211318-006 / VBV ACTUATOR

S/N: APMPF094

Manual#: 1211218 RevDate: 08/16/2019 Rev#: 08

OH , COMPLY W/ FEDEX POSH M-75-32-01

ATA: 75-32-02

***** COMPLY WITH CUSTOMER P.O. REQUIREMENTS *****

Date Recvd: 03/31/2022 Date Reqr: / /

Date Estmtd: 04/29/2022

PRELIMINARY INSPECTION:

DATE: 04/01/2022

TECH: Leonardo Saldivar (esign)

NO VISIBLE ISSUES NOTED PRIOR TO CLEANING

NO A.D.'S

TEARDOWN FINDINGS:

100% KIT REQUIRED

ID PLATE WORN REQUIRES REPLACEMENT

O/H IAW ATA:75-32-02 REV.08 DTD:08/16/19

C/W FED-EX POSH M75-32-01 REV.00 DTD:05/17/10

TECHNICIAN: Brian Hall (esign) DATE: 04/08/2022

CORRECTIVE ACTION:

UNIT OVERHAULED IAW ATA 75-32-02 REV 08 DATED 08/16/2019

C/W FED-EX POSH M-75-32-01 REV 00 DATED 05/17/2010

100% KIT INSTALLED

ID PLATE INSTALLED

* OVERHAULED IAW CMM ATA 75-32-02 REV: 08 DATE: 08/16/2019

*C/W FED-EX POSH M-75-32-01 REV 00 DATED 05/17/2010

*TSO:0 CSO:0

*ESN:V98391

TECHNICIAN: Austin Barnett (esign) DATE: 04/27/2022

Test Technician: Bradley A. Barker (esign)

DATE: 05/03/2022

Supervisor: Chris Gist (esign)

DATE: 05/04/2022

Final Inspection: Randy Jaskolowski (esign)

DATE: 05/05/2022

Printed 05/05/2022 05:20:55 TASGP-55QB Rev IR Dated: 03/09/2011

Labor Task Control#

