


1. Approving Competent Authority/Country LUFTFAHRT-BUNDESAMT Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 30010334673	
4. Organisation Name and Address DIEHL Aerospace GmbH Alte Nußdorfer Straße 23 88662 Überlingen - Germany		Telephone : +49 7551 891 0 Telefax : +49 7551 891 4001 Mail address : Alte Nussdorfer Str. 23, 88662 Überlingen		5. Work Order / Contract / Invoice (Delivery Note No. / Order No. / Customer PO No.) 410423562 / 320187229 / R381802	
6. Item 000010	7. Description ELECTRONIC CONTROL BOX	8. Part No. 3888394 - 221205	9. Quantity 1	10. Serial No. 1588	11. Status/Work REPAIRED
12. Remarks This Certificate is issued by DAs location 6 Impasse AliceGuy, 31300 Toulouse - France Work performed according to CMM 49-63-70 REV.06 dated MAY 14/18 Customer Part No. 6900821300 Technical action report 50280652 describing the actual work performed is attached "ECB IS NOT A SHELF LIFE ITEM" The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under certificate no. B2WY697J					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part-145.A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		☒ Other regulation specified in block 12	
13b. Authorised Signature / Electronic Signature on File		13c. Approval/Authorisation Number		14b. Authorised Signature / Electronic Signature on File  Nadège Amri	
13d. Name		13e. Date (DD MMM YYYY)		14c. Certificate/Approval Ref. No. DE-145.0041	
				14d. Name Nadège Amri	
				14e. Date (DD MMM YYYY) 27 MAY 2021	

USER / INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

DIEHL Aerospace	TECHNICAL ACTION REPORT		Rep.-No. : 50280652 / 0 Page : 1 / 1									
	ELECTRONIC CONTROL BOX		Sales Order : 320187229-10000									
Customer : A.J.Walter Aviation Ltd Cust.Order : R381802 Failure Report : Comp. Date in : 29.03.2021	In PN : 3888394-221205 Amdt : SN : 1588 Customer PN: 6900821300	Out PN : 3888394-221205 Amdt : SN : 1588 Customer PN: 6900821300										
Maintenance requirement : CMM 49-63-70 REV.06 MAY 14/18												
Complaint confirmed: NO		Work Type: Repair										
Warranty accepted: NO		Special Investigation: NO										
Removal Date:	A/C SN: 9H-AMD	A/C Pos: NA										
TSN:												
Equipment: 		MFG : 09/2004										
Customer Complaint: INOP MON TO PN 3888394-221205												
Shop finding/actions: Defects/replacements: <table border="0" style="width: 100%;"> <tr> <td style="width: 30%;"> LABEL 284742000000509 MISUSE </td> <td style="width: 30%;"> LABEL AMENDMENT </td> <td style="width: 40%;"> identification wrong or missing Replaced with new part </td> </tr> <tr> <td> LABEL 084748000000508 MISUSE </td> <td> LABEL IDENTIFICATION </td> <td> identification wrong or missing Replaced with new part </td> </tr> <tr> <td> LABEL 0001033351 MISUSE </td> <td> BAR CODE LABEL </td> <td> identification wrong or missing Replaced with new part </td> </tr> </table>				LABEL 284742000000509 MISUSE	LABEL AMENDMENT	identification wrong or missing Replaced with new part	LABEL 084748000000508 MISUSE	LABEL IDENTIFICATION	identification wrong or missing Replaced with new part	LABEL 0001033351 MISUSE	BAR CODE LABEL	identification wrong or missing Replaced with new part
LABEL 284742000000509 MISUSE	LABEL AMENDMENT	identification wrong or missing Replaced with new part										
LABEL 084748000000508 MISUSE	LABEL IDENTIFICATION	identification wrong or missing Replaced with new part										
LABEL 0001033351 MISUSE	BAR CODE LABEL	identification wrong or missing Replaced with new part										
Comment:												
Date: 27.05.2021	Author: ALEXANDRES		 									

DIEHL
Aerospace GmbH

ATLAS TEST RECORD

PP847.44-09-03/01 Rev. D
Pub. No. D0001127

PROJECT	: VECB A319/320/321 (131-9)	
UUT	: ELECTRONIC CONTROL BOX (ECB)	
DAS NO	: 15A847.44	
P/N	: 3888394-221205	
TEST	: FINAL ACCEPTANCE TEST	
ATLAS TEST SPEC NO	: Pub. No. D0001187	ISSUE T
ATLAS PROGRAM	: 16B847.44-09-03-95-000	
TEST INSTRUCTION	: PA700.14-02/01 GATE1000	ISSUE B
TEST UNIT ADAPTER	: see release certificate	
TEST SOFTWARE	: TSW847.44-09-03/02	ISSUE T
OPERATOR ID	: rbo	
DATE	: Wed May 26 10:39:14 2021	
UUT SERIAL NUMBER	: 01588	

Selected Output mode	: +1
Selected Ratio	: +1.000

VECB Test Program finished at Wed May 26 11:08:42 2021
---- VECB Test Program passed ----

87409