

1. Approving National Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 064374	
4. Organization Name and Address: Aircraft Instrument & Radio Services, Inc., 1851 S. Eisenhower Ct. Wichita KS 67209		5. Work Order/Contract/Invoice Number: Same as Block #3			
6. Item: 7. Description: 1 ENGINE ACCESSORY UNIT		8. Part Number: 65-73606-151		9. Eligibility: * N/A	
10. Quantity: 1		11. Serial/Batch Number: D01357		12. Status/Work: REPAIRED	
13. Remarks: REFERENCE WORK ORDER REPORT FOR WORK PERFORMED. ALL WORK PERFORMED i/a/w CMM NO. 77-09-09 REV:25 DE:03/04/10					
MODS INSTALLED: NONE					
Certifies that the work specified in blocks 12/13 was carried out in accordance with EASA Part 145, and with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA 145-4100.					
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 13.		19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
15. Authorized Signature:		16. Approval/Authorization No.:		21. Approval/Certificate No: TI2R188L	
17. Name (Typed or Printed):		18. Date (m/d/y):		22. Name (Typed or Printed): ADAM HOLSTINE	
				23. Date (m/d/y): Jul/11/2013	

User/Installer Responsibilities

It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



AIRCO
GROUP

Aircraft Instrument & Radio Services
1851 S. Eisenhower Ct. Wichita, KS 67209
PH: (316) 945-9820 (800) 972-7626
FAX: (316) 945-8014
FAA REPAIR STATION #T12R188L

WORK ORDER TEARDOWN

Work Order No. 064374


ORIGINAL PN:	65-73606-151
REVISED PN:	65-73606-151
DESC:	ENGINE ACCESSORY UNIT
SN:	D01357
MODEL:	
TECH:	BOB
INSP:	ADAM

BILL TO:

A J WALTERS AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 OSH
ENGLAND

SHIP TO:

B & H SPEEDMAIL
ATTN: AJW AVIATION
2284-86 NW 82 AVE
MIAMI, FL 33122
USA

Date	Cust No.	Terms	Customer Contact	Cust PO	
07/11/13	01489	NET 45 DAYS BY W/T	PROGRESSING	209047	
F.O.B.	Ship Via	Manual	Rev	Rev Dt	Box #
3rd PTY BILL	FED EX NEXT DAY BY 10:30 AM	77-09-09	25	03/04/10	
Description	Qty				
Action Requested: LIGHT REVERSE SLACON ALL TIME. ADVISE COST TO REPAIR IAW MFG SPECS.					
Preliminary Inspection/Defects Found: PERFORMED PRELIMINARY INSPECTION AND TESTING. UNIT IS VERY DIRTY. LAMP DS 6 IS DEFECTIVE. NEED TO DISASSEMBLE, CLEAN AND INSPECT ALL SUB ASSEMBLIES, CIRCUIT BOARDS, CONNECTORS AND CHASSIS. NEED TO CALIBRATE ALL SENSOR CARDS WITH ASSOCIATED RESISTOR KIT, ALIGN IAW MFG SPECS, REASSEMBLE AND FUNCTIONAL TEST IAW MFG SPECS.					
Parts Required:					
LABOR	12.0				
737	1.0				
KIT	1.0				
SS	1.0				
Action Taken: REPAIRED IAW MFG SPECS. REPLACED DEFECTIVE LAMP. CLEANED AND INSPECTED ALL SUB-ASSEMBLIES, CIRCUIT BOARDS, CONNECTORS AND CHASSIS. RESEALED BOARDS AS REQUIRED. RE-ALIGNED UNIT TO MFG SPECS. PAINTED COVER. PERFORMED FULL FUNCTIONAL TEST. TAGGED REPAIRED. TESTED AND CERTIFIED AIRWORTHY IAW CMM 77-09-09, REV 25, 03/04/10.					
By 	Date 07/11/2013				
TARIFF: 9801					