

1. Approving Civil Aviation
Authority/Country:

FAA/United States

2.

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

4. Organization Name and Address:

Honeywell International Inc.
23500 W 105th Street
Olathe KS 66061

Repair Station
PR2R093L

3. Form Tracking Number:
20200008841524Y15
340758818

5. Work Order/Contract/Invoice Number:
R379015
340731200
Page 1 of 1

6. Item:

7. Description:

001

DA-1B ANTENNA DRIVE - DUAL

8. Part Number:

930-3001-001

9. Quantity:

1

10. Serial Number:

DA02367

11. Status / Work:

REPAIRED

12. Remarks:

THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH:

CMM 34-41-70 Rev 5, OCT/12/2019

MM 34-41-80 Rev 3, SEP/21/2020

SB 330-3001-34-001 Rev 1, DEC/06/2019

MODS: 23-28

SW /ERS: N/A

SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED

CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NO. EASA 145.4140

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12.

14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval/Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

Walter Walters

PR2R093L

13d. Name (Typed or Printed):

13e. Date(dd/mm/yyyy):

14d. Name (Typed or Printed):

28/DEC/2020

User / Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA FORM 8130 - 3 (02-14)

NSN : 0052 - 00 - 012 - 9005



1. 国家 Country 中国	2. 中国民用航空总局 CAAC	☐ 符合性 Conformity	☒ 适航性 Airworthiness	3. 证书编号 20200008841527Y05 340758818	Certificate Ref. No.	
批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG						
4. 单位 Organization Honeywell International Inc. 23500 W. 105th Street Olathe KS 66061	5. 工作单/合同单/货单 Work Order/Contract/Invoice R379015 340731200 Page 1 of 1					
6. 序号 Item	7. 内容 Description	8. 件号 Part No.	9. 适用性 Eligibility	10. 数量 Qty	11. 系列号/批号 Serial/Batch No.	12. 产品状态 Status/Work
001	DA-1B ANTENNA DRIVE - DUAL	930-3001-001	NOT KNOWN	1	DA02367	REPAIRED
13 备注 Remarks THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH: MM 34-41-70 Rev 5, OCT/12/2019 MM 34-41-80 Rev 3, SEP/21/2020 SB 930-3001-34-001 Rev 1, DEC/06/2019 MODS: 23-28 SW VERS: N/A						
SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED						
14. 新产品 New Parts 兹声明上述产品除第13项的其它规定以外， 已按照上述国家适航条例进行制造/检查， 并且该产品(出口产品)符合经批准的型号设计和进口国提出的专用要求。 Certifies that the part(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and / or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		15. 使用过的产品 Used Parts 兹声明上述产品除第13项的其它规定以外， 已按照上述国家适航条例和进口国通知的特殊要求进行了工作， 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is(are) in condition for safe operation and considered ready for release to service. (over)				
16. 批准人签名 Signature 		18. 批准日期 Date DEC/28/2020		19. 中国民航总局授权 Issued by or on behalf of the CAAC F00100519		
17. 批准人姓名 (打印的) Name (Printed) Walter Walters						

AAC - 038(12/94)

* 参阅产品目录详细查找适用性

Cross - check eligibility for more details with parts catalogue

SERVICE REPORT

AJW AVIATION LTD

SR NUMBER: 5015243479		340758818	FAA: PR2R093L	EASA: EASA.145.4140
-----------------------	--	-----------	---------------	---------------------

PO: R379015		CUSTOMER PART NUMBER:		CONTRACT NUMBER:
DATE REJECTED: 16 NOV 2020	DATE RECEIVED: 19 NOV 2020	DATE COMPLETED: 28 DEC 2020		
A/C TYPE: A320-214	A/C TAIL NUMBER: AP-BMX	A/C SERIAL NUMBER: D4392		
PACKING STATUS: No		SEALS INTACT: Seals Intact	PHYSICAL DAMAGE: No	

REASON FOR REMOVAL: WX RADAR ANT FAULT PFR SHOWS ANT DRIVE UNIT

AS RECEIVED: 930-3001-001		AS RELEASED: 930-3001-001	
DESCRIPTION: DA-1B ANTENNA DRIVE - DUAL		DA-1B ANTENNA DRIVE - DUAL	
SERIAL NUMBER: DA02367		DA02367	
UID(MFR/SPL PNO SER/UCN): 97896 DA02367		97896 DA02367	
HW MOD STATUS: 23-27		23-28	
SW MOD STATUS: N/A		N/A	
SOFTWARE LOAD: N/A		N/A	
REASON FOR REMOVAL CONFIRMED: Rejection Confirmed		ESTIMATE SUPPLIED: Yes	
PRIMARY SHOP FINDING: Hardware Fault Found		WARRANTY: Warranty Denied	
TYPE OF SERVICE: REPAIRED		TECHNICIAN: German Gallegos	

MAINTENANCE STATEMENT: PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.

SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____

SIGNATURE OF AUTHORIZED PERSON: _____

Complied With

CMM/Eng Documentation: 34-41-70/Rev 5/Rev Date 12 OCT 2019; 34-41-80/Rev 3/Rev Date 21 SEP 2020;
Service Bulletins: 930-3001-34-001/Rev 1/Rev Date 06 DEC 2019;
Customer Manuals/Documentation:

SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN INQUIRY.

SERVICE REPORT
AJW AVIATION LTD

SR NUMBER: 5015243479	
PO: R379015	CUSTOMER PART NUMBER:
FAA: PR2R093L	EASA: EASA.145.4140
CONTRACT NUMBER:	

Previously Complied With		CMM/Eng Documentation:		Service Bulletins:		Customer Manuals/Documentation:			
Evaluation Findings		PASSED VSWR TEST, NEEDS MOD 28 INSTALLED. NO OBVIOUS EXTERNAL DAMAGE.							
Work performed / Comments to Customer		Replaced GDM CCA system 2. Unit modified by installing mod 28 per SB 930-3001-34-001. Unit passed final test per CMM 012-0748-001(34-41-70). Test equipment cal dates checked. Tested by German Gallegos on 12/24/20. This component is airworthy with respect to the work performed.							
DISPOSITION	REF DSG	P/N	S/N	Installed	Removed	S/N	Qty	Primary Failure	SB
Replace		131-00223-	0013	131-00223-	0013		1		
NEEDS MOD 28									
Replace		722-4458-	PLR2020119	722-4458-	PLP141900289		1		
FAILED									