

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 330175-20	
4. Organization Name and Address: Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300				5. Work Order/Contract/Invoice Number: 330175 / R376426	
6.Item: 7. Description:		8. Part Number:		9. Quantity:	
1		N2 SPEED SENSOR		3218KGB01	
10.Serial Number:		11.Status/Work:			
EM170169-B		OVERHAULED			
12.Remarks: OVERHAULED IAW CMM ATA 77-11-15 REV: 13 DATE: 10/31/2007 TSO: 0 CSO: 0					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA part 145 and, with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number: EASA 145.5893					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in Block 12.					
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12	
13d. Name (Typed or Printed)		13e. Date (dd/mm/yyyy):		14b.. Authorized Signature: 	
				14c. Approval/Certificate No.: GPYR474X	
				14d. Name: (Typed or Printed) Leonardo Saldivar	
				14e. Date (dd/mm/yyyy): 10 NOV 2020	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1.					
Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.					

NSN: 0052-00-012-9005

FAA authorized authority per Op Specs A025 for electronic signatures IAW AC 120-78.

FAA Form 8130-3 (02-14)

WORK ORDER FORM 100

Page No. 1



Work Order: 330175-20

Triumph Accessory Services -Grand Prairie

1038 Santerre Drive
Grand Prairie, TX 75050-1937
972/623-9300 FAX (972) 660-1580
FAA CRS No: GPYR474X

CAAC CRS No: F00100391

Customer: 012424 / AJ WALTER AVIATION LTD

Cust RO#: R376426

Step: SHOP COMPLETE

Dept#: EL2

Work Req: OH

Warranty Code: NW Qty: 1

P/N: 3218KGB01 / N2 SPEED SENSOR

S/N: EM170169-B

Mfg: CFMI

Manual#: 77-11-15 RevDate: 10/31/2007 Rev#: 13 ATA: 77-11-15

OH

***** COMPLY WITH CUSTOMER P.O. REQUIREMENTS *****

Date Recvd: 06/25/2020 Date Reqr'd: / / Date Estmtd: 11/17/2020

PRELIMINARY INSPECTION: DATE: 06/25/2020 TECH: Leonardo Saldivar (esign)
NO VISIBLE ISSUES NOTED PRIOR TO CLEANING
NO A.D.'S

TEARDOWN FINDINGS:

CLEANED AND INSPECTED FOR TEST IAW ATA: 77-11-15 REV. 13,
DATED: 10/31/2007.

UNIT REQUIRES O/H.

TECHNICIAN: Vernon C. Manka (esign) DATE: 07/01/2020

FAILED RESISTANCE AND POLARITY ON CH A/C PER
ATA 77-11-15 REV.13 DTD. 10/31/07

TECHNICIAN: STEVE HARKINS (esign) DATE: 07/01/2020

DISASSEMBLED CLEANED AND INSPECTED FOR O/H.
IAW ATA: 77-11-15 REV. 13, DATED; 10/31/2007.

A/C CONNECTOR PIN #1 WIRE BROKEN AT CONTACT,
REQUIRES REPLACEMENT OF CONTACTS.

100% KIT REQUIRED FOR O/H.

TECHNICIAN: Vernon C. Manka (esign) DATE: 07/07/2020

CORRECTIVE ACTION:

REPLACED "A/C" CONNECTOR CONTACTS.

INSTALLED 100% KIT FOR O/H.

ASSEMBLED IAW ATA: 77-11-15 REV. 13, DATED: 10/31/2007.

*

*OVERHAULED IAW CMM ATA 77-11-15 REV: 13 DATE: 10/31/2007

*TSO: 0 CSO: 0

TECHNICIAN: Vernon C. Manka (esign) DATE: 11/06/2020

Test Technician: Michael C. Jenkins (esign) DATE: 11/09/2020

Supervisor: Cheyenne Hargon (esign) DATE: 11/10/2020

Final Inspection: Leonardo Saldivar (esign) DATE: 11/10/2020



1. 国家 Country: CHINA		2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness			3. 证书编号 Certificate Ref. No. 330175-20	
		授权发布证书/航空认证标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG				
4. 单位 Organization: Triumph Accessory Services - Grand Prairie 1038 Santerre Drive, Grand Prairie, TX 75050-1937, 972/623-9300		Repair Station# F00100391			5. 工作单/合同单/货单 Work Order/Contract/Invoice Number: 330175 / R376426	
6. 序号 Item:	7. 内容 Description:	8. 件号 Part Number:	9. 适用性 Eligibility:*	10. 数量 Quantity:	11. 系列号/批号 Serial/Batch Number:	12. 产品状态 Status/Work:
1	N2 SPEED SENSOR	3218KGB01	NOT KNOWN	1	EM170169-B	OVERHAULED
13. 备注 OVERHAULED IAW CMM ATA 77-11-15 REV: 13 DATE: 10/31/2007 Remarks: TSO: 0 CSO: 0						
14. 新产品 New Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例进行制造/检查, 并且该产品 (出口产品) 符合经批准的型号设计资料和进口国提出的专用要求。 Certifies that the Parts(s) identified above except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.			15. 使用过的产品 Used Parts 兹声明上述产品除第 13 项的其它规定以外, 已按照上述国家适航条例和特殊要求进行了工作, 该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in Block 13, the work was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the parts(s) is (are) in condition of safe operation and considered ready for release to service. (over)			
16. 批准人 Signature: 		18. 批准日期 Date 10 Nov, 2020		19. 中国民航总局授权 Issued by or on behalf of the CAAC F00100391		
17. 批准人姓名 (打印的) Name (Printed) Leonardo Saldivar						

AAC-038(12/94)

*参阅产品目录详细查找

*Cross-check eligibility for more details with parts catalogue