CHANGE OF STREET STREET	AND DESCRIPTION OF THE PERSON NAMED IN PARTY	THE RESERVED THE PROPERTY OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN THE PERSON NAMED	では 日本の	SECURE SECURITIES SECURI	THE REAL PROPERTY AND PERSONS ASSESSMENT OF THE PERSON OF	一日の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本の日本
<del>. 1</del>	Approving Civil Aviation Authority Country:	2 AUTH	AUTHORIZED RELEASE CERTIFICATE	E CERTIFICATE	3 Form Tracking Number:	er:
	FAA/UNITED STATES	AI	FAA Form 8130-3 AIRWORTHINESS APPROVAL TAG	30-3 POVAL TAG	N-176420	20
4. Organiz	Organization Name and Address	Aviation Technical Services, Inc. 3121 109th St.SW Everett, WA 98204		FAA Approved Repair Station No. HN6R593N	5. Work Order/Contract/Invoice Number:  Work Order: 559568  Customer PO: T41192	voice Number: 68 92
6. Item:	7. Description		8. Part Number	9. Quantity 1	10. Serial Number	11. Status/Work
<u> </u>	AILERON TAB		113A7200-3	1	HDH0548	Repaired
12. Remarks: Documents des approved data	12. Remarks:  Documents describing the actual work performed on work order #559568 are provided. Note: See attached parts usage list for all replacement approved data for return to service by personnel who were part of a current drug and alcohol testing program as required by 14CFR120.	ere part of a current drug an	d alcohol testing program as required	ement	nufactured by: d work was performed	BOEING I in accordance with FAA accepted /
Certifies that	Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the article is considered ready for release to service under EASA Part 145 approval no. EASA 145-4942	ied out in accordance with E	ASA Part 145 and in respect to that w	vork the article is considered ready f	or release to service under EASA Par	† 145 approval no. EASA 145-4942
13a. Certific	<ul> <li>13a. Certifies the items identified above were manufactured in conformity to:</li> <li>☐ Approved design data and are in a condition for safe operation.</li> <li>☐ Non-approved design data specified in Block 12.</li> </ul>	nufactured in conformity idition for safe operation. Block 12.	. to:	14a. 🗵 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in the described in Block 12 was accomplished in Regulations, Part 43 and in respect to that	Block accor work,	☑ Other regulation specified in Block 12 12, the work identified in Block 11 and dance with Title 14, Code of Federal the items are approved for return to service.
13b. Author	13b. Authorized Signature: -N/A-	13c.	13c. Approval/Authorization No.: -N/A-	14b. Authorized Signature:	Jeste	14c. Approval/Certificate No.: HN6R593N
13d. Name	13d. Name (Typed or printed): -N/A-	13e.	13e. Date (dd/mmm/yyyy): -N/A-	14d. Name (Typed or Printed): Sala, Robert E		14e. Date (dd/mmm/yyyy): 12/MAY/2023

## User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



<b>Customer Name</b>	A.J. WALTER AVIATION	
Customer RO No	T41192	
Manufacturer	BOEING	
Job Number	559568	

**WORK ORDER** 

Page 1 of 1

Unit P/N (in) **Part Number** 

113A7200-3

Serial Number HDH0548

Unit P/N (out)

113A7200-3 **Part Number** 

Serial Number HDH0548

**Cust Part Num** 

**FCS REQ** 

No **Warranty REQ** No

Workscope Repaired

**AILERON TAB** 

Workscope

Repaired

RII REQ Quantity N/A 1

Description

REMOVED IN SERVICEABLE CONDITION FROM AJW STOCK

**Comments** 

Reason for Removal Customer Instructions PLEASE QUOTE TO TEST AND RECERTIFY, PLEASE QUOTE TO REPAIR IF IT FAILS TEST. PLEASE TEST

UNDER T&M - QUOTE AND HOLD. (THIS IS AN RO FOR AN ADDITIONAL PIECE AJW HAD ATTACHED TO

THE UNIT ON JOB 558793)

			Manual Reference				
Type	Number	Rev	Date	Location	Notes		
CMM	57-50-26	26	01-NOV-20	MBF			
SRM	51-60-03	79	10-MAR-23	MBF			

**Preliminary Inspection** 

P/N Verified Yes S/N Verified Yes Repairs Required Yes

Life Limited No.

**AD Required No** 

Uncert

Mechanic 001161 09-MAY-23

**Preliminary Functional Testing** 

Test N/A

Comments

Uncert

Mechanic 001161 09-MAY-23

**Issues and Resolutions** 

\* Issue

Unit requires weight verification Enter By 001161 09-MAY-23

Resolution

Weighed unit IAW SRM 51-60-03 para 5, new tab weight is 4.85 lbs with 3 adjust weights required upon installation of tab to aileron assembly.

Uncert

Mechanic 001161 12-MAY-23

Inspector 020292 12-MAY-23

Cleaned per

CMM 57-50-26 page 401.

**Work Order Final Inspection** 

Uncert

Inspected per

CMM 57-50-26 page 501 para 2.A (1), (4), and (5).

Uncert

Passed Final Test per NA

**Mechanic** 001161 09–MAY–23 Uncert

Mechanic 001161 09-MAY-23

Mechanic 001161 09-MAY-23

Validated that all replacement parts conform to the Manual Reference listed. See attached Components Parts Usage List for discrepancy and parts being replaced. **Cal Tools ID** 

This Unit Has Been Repaired

**Other Comments** 

The work identified on this work order was accomplished in accordance with Title 14. Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

Mechanic

001161 12-MAY-23

**Work Order Final Inspection Signoff** AD Requirement Verified By QC 020292 12-MAY-23

Supervisor Inspector

001161 12-MAY-23 020292 12-MAY-23

CSD-E01 (04/08/2016) Rev 1

## Parts Usage List

JOB: 559568 CREW: (all) DASH: (all)

							<b>5</b> Return Parts		Deficiency/Identif		tifier	
Item	Cond.	Description	on	Qty	UOM	SN/	/Lot	Minimum Returnable Qt	у	Cond.Code	Deficiency	Fig./Item
BACM10L1CVR	NEW	PLACARD	(24 MO SHF LF)	2	EA	1521300-1		1		PREQ	ОТИ	
BACM10L1CVR	NEW	PLACARD	(24 MO SHF LF)		EA	1527156-1		1		PREQ	OTU	
BACR15DR3PA2	NEW	RIVETS	8 EA		EA	1273618-6 1		1		PREQ	ОТИ	
Deficiency Code Description				Condition Code		De	Description					
OTU One Time Use				PREQ		Par	Parts Required For Assembly					



Standard replacement and consumable items may not be identified with a deficiency identifier.



**PACKING SLIP** 

PACKING SLIP #

P - 171973

2600 West Casino Rd Everett, WA, 98204

Phone: 425-347-3030 Fax: 425-423-6065

Ship To:

A.J. WALTER AVIATION

THE HEADQUARTERS MAYDWELL AVENUE

WEST SUSSEX, RH13 OAS

GΒ

DATE PACKI	ED SHI	P VIA	F.O.B.	TERMS	
07-JUN-23 FEDEX INTL PRIORITY		Destination			
	PART NUMBER SERIAL NUMBER	DESERMPTION	CUSTOMER PO	CRATE LOCATION	JOB#
1	113A7200-3 HDH0548	AILERON TAB	T41192	Nonusable	559568 -1

**GOLDEN GLOBE** 

RECEIVED BY:

DATE: