

1. Approving Competent Authority / Country		2.		3. Form Tracking Number	
CAA / UNITED KINGDOM		AUTHORISED RELEASE CERTIFICATE		0001003545	
4. Organisation Name and Address:		SAFRAN AEROSYSTEMS SERVICES UK Ltd UNIT 610, AVENUE WEST, SKYLINE 120 BRAINTREE, ESSEX, CM77 7AA, ENGLAND UNITED KINGDOM		5. Work Order / Contract / Invoice 0051139238 R419318	
6. Item	7. Description	8. Part No	9. Qty.	10. Serial No.	11. Status / Work
1	EVACUATION SYSTEM,SLIDE/RAFT	66673-201	1	66673-M9391	OVERHAULED
12. Remarks Overhauled and tested IAW CMM: 25-61-51 Rev 11, Dated 16/Sep/2022 No applicable AD Parts Replaced: All MSO spares IAW CMM's, Powerpack, Age limited kit, Locator light X2, Overlaminiate Cylinder total life expiry: 05-2033, Powerpack total life expiry: 08-2030, Survival kit total life expiry: 07-2028 Previous Overhaul: New SEE REPAIR REPORT No: 0001000760					
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under FAA certificate no Z5KY074B					
13a. Certifies that the repair identified in the work performed in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under FAA certificate no Z5KY074B					
<input type="checkbox"/> approved design data and are in accordance with the applicable AD					
<input type="checkbox"/> non-approved design data specified in block 12					
13b. Authorised Signature		13c. Approval / Authorisation Number		14a. <input checked="" type="checkbox"/> Part-145, A-50 Release to Service <input type="checkbox"/> Other regulation specified in block 12	
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature	
				14c. Certificate / Approval Ref No. UK. 145.01053	
14d. Name		14e. Date (dd mmm yyyy)		14f. Date (dd mmm yyyy)	
Matthew West		17 Nov 2023			
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



1. Approving Competent Authority / Country		2.		3. Form Tracking Number	
EASA		AUTHORISED RELEASE CERTIFICATE		0001000760	
4. Organisation Name and Address:		EASA FORM 1		5. Work Order / Contract / Invoice	
SAFRAN AEROSYSTEMS SERVICES UK LTD UNIT 610, AVENUE WEST, SKYLINE 120 BRAINTREE, ESSEX, CM77 7AA, ENGLAND UNITED KINGDOM				0051139238 R419318	
6. Item	7. Description	8. Part No	9. Qty.	10. Serial No.	11. Status / Work
1	EVACUATION SYSTEM,SLIDE/RAFT	66673-201	1	66673-M9391	OVERHAULED
12. Remarks					
Overhauled and tested IAW CMM: 25-61-51 Rev 11, Dated 16/Sep/2022 No applicable AD Parts Replaced: All MSO spares IAW CMM's, Powerpack, Age limited kit, Locator light X2, Overlamine Cylinder total life expiry: 05-2033, Powerpack total life expiry: 08-2030, Survival kit total life expiry: 07-2028 Previous Overhaul: New SEE REPAIR REPORT No: 0001000760					
13a. Certifies that the items identified above were manufactured in accordance to: <input type="checkbox"/> approved design data and are in a condition for safe operation. <input checked="" type="checkbox"/> non approved design data specified in block 12		14a. <input checked="" type="checkbox"/> Part-145 A.50 Release to Service <input type="checkbox"/> Other regulation specified in block 12		14b. Authorised Signature	
13b. Authorised Signature		13c. Approval / Approval Ref. Number		14c. Certificate / Approval Ref. No.	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name	
				Matthew West	
USER/INSTALLER RESPONSIBILITIES		14e. Date (dd mmm yyyy)		EASA.UK.145.01053	
This certificate does not automatically constitute authority to install the item(s)		14f. Date (dd mmm yyyy)		17 Nov 2023	
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.					
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



SAFRAN AEROSYSTEMS SERVICES UK LTD  
**REPAIR REPORT**



No 0001000760

**OVERHAULED**

CUSTOMER: AJ WALTER AVIATION LTD

ORDER No: 1117554 / 0051139238

CUSTOMER ORDER: R419318

RECEIVED DATE: 02-11-23

CUSTOMER INSTRUCTION: CUSTOMER REQUEST

**RECEIVING**

DESCRIPTION: EVACUATION SYSTEM, SLIDE/RAFT

REF AIRCRAFT MANUFACTURER:

RECEIVED PART NUMBER: 66673-201

MANUFACTURER:

SERIAL NUMBER: 66673-M9391

CAGE CODE: 70167

AMENDMENT: N/A

MANUFACTURING DATE: 01-10-18

QUANTITY: 1.00

REMOVAL DATE: 05-10-2023

LAST OHL DATE New

TSN: 20965.00 , TSO:

TSR:

AIRCRAFT:

REGISTRATION NUMBER:

A/C DELIVERY DATE:

B787

TC-LLA

N/K

Maintenance Documentation Reference

25-61-51 REV 11 DATED 16-SEP-2022

Reason for Removal

OVERHAUL

Findings

Overhaul requested.

Overhaul due.

Received packed.

Good overall condition.

Failed inspection as per CMM: Power unit short expiry date

Failed inspection as per CMM: Age limited kit short expiry date

Failed inspection as per CMM: Locator light distorted x2

Failed inspection as per CMM: Overlamine peel out on girt

Failed inspection as per CMM: Locator light pocket peel out, need to repair.

Cylinder requires Hydrostatic Test

SB 108-25-11 ALREADY EMBODIED

SB 108-25-15/16/17 / SIL 25-420 CHECKED N/A

**SHIPPING**

SHIPPED PART NUMBER: 66673-201

REF AIRCRAFT MANUFACTURER: 66673-201

SERIAL NUMBER: 66673-M9391

AMENDMENT : N/A

DATE: 17-11-23  
(DD-MM-YY)

TECHNICIAN:

INSPECTOR: Matthew West

Signature

Signature



Page : 1 / 2

**SAFRAN AEROSYSTEMS SERVICES UK LTD**  
**REPAIR REPORT**



No 0001000760

**OVERHAULED**

CUSTOMER: AJ WALTER AVIATION LTD

ORDER No: 1117554 / 0051139238

CUSTOMER ORDER: R419318

RECEIVED DATE: 02-11-23

CUSTOMER INSTRUCTION: CUSTOMER REQUEST

Work performed & replaced parts /Travaux réalisés & pièces remplacées

Overhauled and tested IAW CMM: 25-61-51 Rev 11, Dated

16/Sep/2022

No applicable AD

Inflation hose tested.

Parts Replaced:

All MSO spares IAW CMM's,

Powerpack,

Age limited kit,

Locator light X2,

Overlamine

Remarks

Cylinder total life expiry: 05-2033

Cylinder assembly P/N: 66752-103

Cylinder assembly S/N: 8106-1-2601

Cylinder DOM: 05-2018

Cylinder HST date: 11-2023

Reservoir P/N: 66554-1

Valve assy P/N: 66556-3

Valve assy S/N: R149-004238

Valve MFD: 3Q/18

Hose P/N: 66859-7

Hose S/N: 1826002

Hose MFD: 17-09-2018

Powerpack total life expiry: 08-2030

Powerpack P/N: 66874-1

Powerpack LOT: 0003/22023

Powerpack MFD: 08-2023

Age limited survival kit total life expiry: 07-2028

Customer liability

Yes

**SHIPPING**

SHIPPED PART NUMBER: 66673-201

REF AIRCRAFT MANUFACTURER: 66673-201

SERIAL NUMBER: 66673-M9391

AMENDMENT : N/A

DATE: 17-11-23  
(DD-MM-YY)

TECHNICIAN:

Signature

INSPECTOR: Matthew West

Signature

SAK  
13