

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number. WO83991	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number. R360812-1	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	ELAC B (ELEVATOR AILERON COMPUTEF	3945128216	1.00	ELACVB015402	INSPECTED/TESTED
12. REMARKS INSPECTED/TESTED SERVICEABLE PER CMM 27-93-35A REV.18 DATED APRIL 20, 2018 AND ATEC6 TEST PROGRAM 6-H7FG REL.01. FOR MORE INFORMATION REFER TO THE TEAR DOWN REPORT.					
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Signature:		13c. Approved Organization Number		14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12	
13d. Name (Typed or Printed):		13e. Date		14b. Signature <i>Stephane Hervieux</i> 14c. Approval Organization Number 33-12	
13d. Name (Typed or Printed):		13e. Date		14d. Name (Typed or Printed) Stephane Hervieux 14e. Date (dd/mm/yyyy) 08/Jul/2019	
Installer Responsibilities					
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					



technique

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO83991

Date Printed: 7/8/2019

Customer RO: R360812-1

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: ELAC B (ELEVATOR AILERON COMPUTER)

Phone:

P/N: 3945128216

Qty: 1

Email:

S/N: ELACVB015402

Mfg: THALES AVIONICS SAS

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: 3945128216

Serial Out: ELACVB015402

Symptoms:

CODE: REASON FOR REMOVAL

DETAILS: FÉCTR ELAC 1 PITCH FAULT

Faults:

CODE: INITIAL TEST FAILURE

DETAILS: On test on ATEC6 test station, unable to reproduce the failure in shop.

CODE: TEST AND RECERTIFY

DETAILS: Unit tested 2X without failure.
Test & re-certification.

Corrective Actions:

CODE: INSPECTED/ TESTED

DETAILS: INSPECTED/TESTED SERVICEABLE PER CMM 27-93-35A REV.18 DATED APRIL 20, 2018 AND ATEC6 TEST PROGRAM 6-H7FG REL.01.