

ORIGIN ID:YULA (514) 339-5247 MARY SCOTT AJW TECHNIQUE INC 7055 RUE ALEXANDER-FLEMING.


SAINT-LAURENT, PQ H4S287 CANADA CA

SHIP DATE: 15NDV23 ACTWGT: 7.00 KG MAN CAD: 0846545/CAFE3513 DIMS: 70x43x38 CM

B AND H WORLDWIDE SG PTE LTD 70 ALPS AVENUE UNITS 01-03 & 02-0

SINGAPORE 498801 (656)842-4113 FOLLO 1NU: 9419259

(SG)



FedEx

TRK# 6354 6972 6221

V6 SINA

A1 IP EOD **ETD** 498801 SIN



x 49 x 39



ACI -635469726221

Commercial Invoice Ult Dest. Air Waybill Nbr. SG 635469726221 Bill T/C Bill D/T/F ivoice Number Purpose of Shipment Curr Repair and Return USD Pkgs 2481-8526-0 2481-8526-0 ĺ i pper: Consignee: iry Scott W TECHNI QUE I NC B AND H WORLDWIDE SG PTE LTD)55 RUE ALEXANDER-FLEMING 70 ALPS AVENUE UNITS 01-03 & 02-0 AI NT-LAURENT SINGAPORE) H4S2B7 CA (514) 339-5247 498801 SG (656) 842-4113 D/ELN: ID/EIN: oker: lmporter: B AND H WORLDWIDE SG PTE LTD 70 ALPS AVENUE UNITS 01-03 & 02-0 SI NGAPORE 498801 SG (656) 842-4113 I D/EI N: Marks/Nbrs: R419269 Cntry Mru. Us Net Ngt. 3.00.00 5 Code: 9014.20.0099 Unit Qty: 1.00 EA Unit Value: Commodity Value: 3,000.00 3,000.000000 esc: FLIGHT MANAGEMENT COMPUTER - CIVIL AIRCRAFT PARTS irt Nbr: REPALR COST Marks/Nbrs: Cntry MFG: CA Net Wgt: 0.00 kgs R417488 5 Code: 9802.00.0000 Unit Qty: 1.00 DS Unit Value: Commodity Value: 2,892.75 2, 892. 750000 25 C: REPAIR COST of lowing Repair/Processing Total Shipment 7 kgs Total Commodity 5892.75 Weight: Val ue: Terms of Sale: Freight: 0.00 Insurance: 0.00 Ot hers: 0.00 Total Invoice Value: 5,892,7

omments:

declare all information in this invoice to be true and correct. gnature of shipper: Mary Scott 11/15/2023



PERMIT NO : IM3K863387G

CARGO CLEARANCE PERMIT PG :1 OF 2

7.000/KGM

0.00

0.00

0.00

648.95 0.00

1/PKG

MESSAGE TYPE : IN NON-PAYMENT DECLARATION TYPE :STORAGE IN FTZ

IMPORTER:

B & H WORLDWIDE (SG) PTE LTD

198701661N

EXPORTER:

HANDLING AGENT:

PORT OF LOADING/NEXT PORT OF CALL:

O P CANADA

PORT OF DISCHARGE/FINAL PORT OF CALL

COUNTRY OF FINAL DESTINATION:

INWARD CARRIER AGENT:

SATS LTD.

OUTWARD CARRIER AGENT:

PLACE OF RELEASE: CHANGI FTZ, SG.

LICENCE NO:

CZ

VALIDITY PERIOD

:17/11/2023 -30/11/2023

TOTAL GROSS WT/UNIT TOTAL OUTER PACK/UNIT :

TOT EXCISE DUT PAYABLE : S\$ TOT CUSTOMS DUT PAYABLE: S\$

TOT OTHER TAX PAYABLE : S\$ TOTAL GST AMT : S\$
TOTAL AMOUNT PAYABLE : S\$

CARGO PACKING TYPE : OTHER NON-CONTAINERIZED IN TRANSPORT IDENTIFIER :

CONVEYANCE REFERENCE NO :FX 5311

OBL/MAWB NO :

0BC

ARRIVAL DATE : 18/11/2023 OU TRANSPORT IDENTIFIER :

CONVEYANCE REFERENCE NO :

OBL/MAWB/UCR NO :

DEPARTURE DATE :

CERTIFICATE NO:

PLACE OF RECEIPT: CHANGI FTZ, SG.

CZ

CUSTOMS PROCEDURE CODE (CPC):

UNIOUE REF : 198402740W 20231117 6747

PG : 2 OF 2

PERMIT NO : IM3K863387G

(CONTINUATION PAGE)

CONSIGNMENT DETAILS

PREVIOUS LOT NO

S/NO HS CODE CURRENT LOT NO MARKING CTY OF ORIGIN BRAND NAME

MODEL

IN HAWBNO/HUCR/HBL PACKING/GOODS DESCRIPTION

OUT HAWB/HUCR/OBL HS QUANTITY & UNIT CIF/FOB VALUE (S\$) GST AMOUNT (S\$)

01 88073000

US NA

635469726221

AIRCRAFT PARTS

4.0000 KGM

4129.80

330.38

88073000

CA NA

635469726221

AIRCRAFT PARTS

3.0000 KGM

3982.16

NO UNAUTHORISED ADDITION/AMENDMENT TO THIS PERMIT MAY BE MADE AFTER APPROVAL

NAME OF COMPANY: FEDERAL EXPRESS (S) PTE LTD

DECLARANT NAME : NAVINKUMAR PATHMANABAN DECLARANT CODE : XXXX81168 : 90808835

CONTROLLING AGENCY/CUSTOMS CONDITIONS

Z01 - APPROVED BY SINGAPORE CUSTOMS. 209 - AFTER GOODS WERE BROUGHT INTO SINGAPORE VIA LAND/SEA CHECKPOINTS TO

CHANGI FREE TRADE ZONE, SUBSEQUENT MOVEMENT MUST BE COVERED BY:

(I) THE RELEVANT IMPORT PERMITS REGARDLESS OF THEIR VALUE, WHEN THE GOODS ARE RELEASED INTO CUSTOMS TERRITORY FROM CHANGI FREE TRADE ZONE; OR

(II) THE RELEVANT EXPORT PERMITS SUBJECT TO PREVAILING PERMIT REQUIREMENTS WHEN THE GOODS ARE EXPORTED FROM CHANGI FREE TRADE ZONE.

- THIS PERMIT IS NOT TO BE USED FOR CARGO CLEARANCE.

EEE - END OF CARGO CLEARANCE PERMIT.

UNIQUE REF : 198402740W 20231117 6747

Combined Inventory Receipt & Dispatch Check Sheet

THIS DOCUMENT MAY <u>ONLY</u> BE COMPLETED BY A PERSON THAT HAS RECEIVED TRAINING AND BEEN ISSUED WITH AN INSPECTORS STAMP



B&H Warehouse Reference	Job Number	Date Received
AW590585		21.11.2023

A visual inspection has been performed on this unit and the following information checked:

		RECEIPT			DISPATCH	
	Yes	No	N/A	Yes	No	N/A
EASA Form (8130) / Authorised Release Certificate	V					
Trace Documentation	V					
OEM Certification			•			
DG Declaration			•			
MSDS (Material Safety Data Sheet)						
Shelf Life Applicable			•			
Material Certification / ATA 106			•			
US (unserviceable) Tag			•			
Reason for Removal Stated on Tag			•			
Packing Slip	V					
Original Certificates Returned			•			
Unused Statement			•			
Physical Checks to be completed		RECEIPT	- · · · · · · ·		DISPATCH	
	Yes	No	N/A	Yes	No	N/A
Part Number on Unit Matches Paperwork	✓					
Serial Number on Unit Matches Paperwork	<u> </u>					
Description on Unit Matches Paperwork	<u> </u>					🖳
All Paperwork carries the same part & serial number	V					
Blanks fitted to ALL ports			•			
FOD evident in ports / connectors			•			
Static Sensitive	<u> </u>					
Warranty labels INTACT			•			
Following tasks MUST be completed on Receipt AND		RECEIPT			DISPATCH	
Dispatch	Yes	No	N/A	Yes	No	N/A
Interior packaging sufficient to secure unit and weight of unit	√					
Component wrapped in static sensitive bubble/pouch	✓					
Exterior packing condition acceptable for weight of unit	√					
External Damage customer to inspect photo's			•			
Photos Taken – Package Exterior	✓					
Photos Taken – Item and packaging	✓					
Photos Taken – Component(s)	√					
Photos Taken - Data Plates and Connectors	✓					
FirstTrac Updated	√					
Other (Specify)			•			
Customer advised / Pre alert sent			•			
Completed by (Trained Inspector Stamp)	√					

UK-OPS-FM-29

Uncontrolled Document When Printed

Flq-69x39x39

14 THE SIN THE

Version: 6-23/01/2023

3. Form Tracking Number.

1. Approving Civil Aviation Authority/Country Transport Canada	AUTHORIZED RELEASE CERTIFICATE FORM ONE	WO150287 5. Work Order, Contract or
AJW Technique Inc 7055, rue Alexander Fieming Saint-Laurent QC H4S-2B7	AJW technique	R419269
Canada	9. Quantity: 10. Serial/Batch Number:	11. Status. Vork:
6. Item: 7. Description: 1 FL:GHT MANAGEMENT COMPUTER	176200-01-01 1.00 001017	RETURNE
12. REMARKS UNIT REPAIRED AND TESTED SERVICEABLE AS PER CMM 34-61-15 FOR ADDITIONAL INFORMATION REFER TO TEAR DOWN REPORT.	ABLE AS PER CMM 34-61-15 REV:25 MAY 27/2022. R TO TEAR DOWN REPORT.	
		EASA Approval №.: EASA.145.7260
ા ૄેં	14a. Certifies that, except where 11 and described in Block 1 Regulations.	n Block 12, the work identified in Block coordance with Canadian Aviation
Non-approved design data specified in Block 12.	×	
	Other regulation specified in Block 12	
13b Signature:	14b. Signature	14c. Approval Organization Number 33-12
	14d. Name (Typed or Printed)	14e. Date (dd/mmm²yyyy)
13d. Name (Typed or Printed):	Jae Daie Aili Abdeljalii	15/Nov/2023
	Installer Responsibilities	
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of country specified. Statements in blocks 13a or 14a do not constitute installation of applicable national regulations before the aircraft may be flown.	of a country other than certification. In all case	fications from the ication issued in accordance with the

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO150287 Date Printed: 11/15/2023 Customer RO: R419269

Page: 1

To:

A J Walter Aviation Ltd. THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM

Code: AJW01

Fax:

Descr: FLIGHT MANAGEMENT COMPUTER

Phone:

P/N: 176200-01-01

Email:

S/N: 001017

Mfg: GE AVIATION SYS LLC

TSN: UNK

TSO: 0

TSR: 0

CSN: UNK

CSO: 0

CSR:

P/N Out: 176200-01-01

S/N Out: 001017

Symptoms:

CODE:

HARD FAILURE IN CRUISE. **DETAILS:**

Faults:

CODE:

INITIAL TEST FAILURE

DETAILS:

UNIT FAIL THE ACCEPTANCE TEST:

FAIL RETRIEVE MAINTENANCE RECORDS

A1 BOARD FAIL

CODE:

REPAIR

DETAILS:

The following repair(s) will be performed: UNIT NEEDS TO BE REPAIRED:

A1 BOARD NEEDS TO BE REPROGRAMED NEW SOFTWARE TO BE INSTALED

Corrective Actions:

CODE:

REPAIRED

DETAILS:

UNIT REPAIRED AND TESTED SERVICEABLE AS PER CMM 34-61-15 REV:25 MAY 27/2022.

FOR ADDITIONAL INFORMATION REFER TO TEAR DOWN REPORT.