

1. Approving Civil Aviation
Authority/Country:

2

FAA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

33899

CTID 1

4. Organization Name and Address:

BP Aero Services
4965 HANSON DR.
IRVING, TX 75038
USA
Ph: 972-252-2800, Fax: 972-252-2009

5. Work Order/Contract/Invoice
Number:

15401

FAA Approval Holder: 442R874B

6. Item

7. Description:

8. Part Number:

9. Quantity:

10. Serial Number:

11. Status/Work:

1. MANIFOLD-FUEL RIGHT SIDE

2420M73G01

1

N/A

OVERHAULED

12. Remarks:

ATA: 72-09-03
E.S.N. 704152
Repair Order: 31996
Customer: TES PARTS LTD
See Workscope Report: 15401

All work performed in accordance with CF6-80C2 ENGINE MANUAL Manual ID: GEK92451, Revision # 83, Revision Date: 12/1/2015

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the aircraft component is considered ready for release to Service under EASA Acceptance Certificate Number: EASA.145.6427

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14b. Authorized Signature:

14c. Name (Typed or Printed):



14c. Approval/Certificate No.:

442R874B

14e. Date (dd/mm/yyyy):

19-Mar-2016

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



BPAERO SERVICES, LLC

4965 Hanson Drive Irving, TX 75038
972.252.2800 www.bpaeroservices.com
FAA Repair Station # 442R874B

Workscope Report

Work Order #: **15401**

Date Printed: 3/19/2016

Time: 11:13:57 AM

Page: 1

To: ATTN: MICHAEL SHEEHAN TES PARTS LTD AVIATION HOUSE BROCASTLE AVENUE WATERTON INDUSTRIAL ESTATE BRIGEND, CF31 3XR		Ship To: Repairs Group AVIATION HOUSE BROCASTLE AVENUE WATERTON INDUSTRIAL ESTATE BRIGEND, CF31 3XR UNITED KINGDOM	
Ref #: 31996	Phone #: 44-0-1656-765200	Fax #:	Email:
Code: TES	Site:	PN: 2420M73G01	Descr: MANIFOLD-FUEL RIGHT SIDE
Qty: 1	Station:	Make:	Model: Mfg: GE
GEK92451 CF6-80C2 ENGINE MANUAL			
ESN 704152	Warranty Request N/A		TSN
CSN	Complies With		REF6
Entry Date: 3/10/2016	Need Date: 3/20/2016	Compl. Date: 3/19/2016 11:	Warranty: No Container:

Serial Numbers:

Customer Workscope:

Customer requests O/H IAW ESM, CMM or AMM

Per Customer Purchase/Repair Order Work Scope Instructions

Inspection Findings:

Visual Inspection - Existing Repairs

Qty: 1 Repair Required:

Replacement of PTFE (Teflon) Tape

Corrective Actions:

Overhauled - 8130 Issued

Qty: 1 Performed Replacement of PTFE (Teflon) Tape

	Status	Seq
RECEIVING INSPECTION	Complete	0
PRELIMINARY INSPECTION	Complete	10
CF6-80C2-ESM-TASK-72-09-03-6 - CLEANING	Complete	100
CF6-80C2-ESM-TASK-72-09-03-8 - INSPECTION	Complete	200
CF6-80C2-ESM-TASK-72-09-03-8 - PRESSURE TEST	Complete	200
CF6-80C2-SPM-TASK-70-16-04 - MISC REPR	Complete	350
72-09-03 - Replacement of PTFE Tape	Complete	360
PHASE II FINAL INSPECTION	Complete	399
FINAL CLEANING AND CONDITIONING	Complete	00000
FINAL INSPECTION	Complete	00000



BENJAMIN OKOH

Page: 1