

1. Approving Competent Authority / Country CIVIL AVIATION AUTHORITY United Kingdom		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number BA31266242	
4. Organisation Name and Address BRITISH AIRWAYS British Airways Avionics Engineering. Ely Meadow, Talbot Green, Pontyclun, Cardiff CF72 8XL					
6. Item	7. Description	8. Part number	9. Qty	10. Serial No.	11. Status/Work
1.	MODULE STAB TRIM/AIL LOCKOUT	285T0015-113	1	000299	Repaired
12. REMARKS : Batch No 0005396358 Unit Pretested with multiple failures. Light repair to A8 card. Unit Passed full Test to ATA 27-41-51rev41 (BA ATP 07622). Released under TCCA approval 808-04. U723797 19.09.2016 Original Manufacturer : BOEING-BOEING COMMERCIAL AIRPLANE C CMM:27-41-51-41 The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. BT7Y404J					
13a. Certifies that the items identified above were manufactured in conformity to:		14a. ☒ PART-145.A.50 Release to service ☒ Other Regulation specified in block 12			
☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12		Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with PART 145 and in respect to that work the items are considered ready for release to service.			
13b. Authorised Signature		14b. Authorised Signature 		14c. Certificate/Approval Ref. no. UK.145.00142	
13d. Name		14d. Name U723797 Gareth Kembery. Baae 107 CRS		14e. Date (dd/mm/yyyy) 19.Sep.2016	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

British Airways Avionics Eng

Ely Meadow, Talbot Green,
Pontyclun, Cardiff
CF72 8XL
GB

BRITISH AIRWAYS
ENGINEERING

Component Strip Report

Customer: AJW AVIATION

The Headquarters, Maydwell Avenue
Slinfold, West Sussex
RH13 0AS

Part Number: 285T0015-113:81205

Serial Number: 000299

Description: MODULE STAB TRIM/AIL LOCKOUT

Repair Order Number: R300970

Order Number: 4400855

Equipment Number: 42058116

Batch Number: 0005396358

Warranty Requested:

Customer WORK REQUIRED :

Date of Receipt: 09.09.2016

Reason for Removal:

Removal Code: W465 FE

Reason for removal: AILERON LOCKOUT

Date Serviceable: 19.09.2016

Unit Pretested with multiple failures.

Light repair to A8 card.

Unit Passed full Test to ATA 27-41-51rev41 (BA ATP 07622).

Released under TCCA approval 808-04.

Warranty Decision:

Tested ☐

Repaired ☒

Overhauled ☐

Inspected ☐

Re-manufactured ☐

New ☐

Modified ☐

Certification Number: BA000031266242