

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2.		3. Form Tracking Number: 54900	
4. Organization Name and Address: FAA Approval Holder: J0JR961Y				5. Work Order/Contract/Invoice Number: J16090128000 RO: ERO14413	
6. Item 7. Description: 1 Tube, Oil Return Forward Sump				11. Status/Work: OVERHAULED	
8. Part Number: 338-023-803-0				9. Quantitv: 1	
10. Serial Number: N/A					
12. Remarks:					

Jet Airwerks, LLC
3015 N. Summit Street
Arkansas City, KS 67005
USA
Ph: 620-307-6322, Fax: 888-887-2629
EMAIL: SERVICE@JETAIRWERKS.COM
WEB: WWW.JETAIRWERKS.COM

Customer: AJ Walter Aviation Ltd
Inspection(s) : PER ATA 72-09-03
Repair(s) : 001
Service Bulletin(s) : N/A
Airworthiness Directive(s) : N/A
Per : CFMI CFM56-5B ENGINE MANUAL NO. CFMI-TP-SM.9 REFERENCE 72-09-03 REVISION 67, DATE: 15 MAR 2016
REMOVED FROM ESN: 577858 TSN: N/A CSN: N/A

Additional Information:

"Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.6130"

13a. Certifies the items identified above were manufactured in conformity to: ☒ Approved design data and are in a condition for safe operation. ☒ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
14b. Authorized Signature: 		14c. Approval/Certificate No: J0JR961Y	
14d. Name (Typed or Printed): Joshua Davidson		14e. Date (dd/mm/yyyy): 28/Sep/2016	
User/Installer Responsibilities			

It is important to understand that the existence of this document alone does not automatically constitute authority to install the engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1 國家 Country P.R. CHINA	2 中國民用航空局 CAAAC ☐ 符合性 Conformity	3 證書編號 Certificate Ref. No. 54900
批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG		
4 單位 Jet Airwerks, LLC Repair Station # J0JR961Y 3015 N. Summit Street Arkansas City, KS 67005 USA		
5 工作單 / 合同 / 發票 Work Order / Contract / Invoice J16090128000 ERO14413	6 項目 Item 1	7 描述 Description Tube, Oil Return Forward Sump
8 零件號 Part No. 338-023-803-0	9 適航性 Eligibility CFM56-5B	10 數量 Qty 1
11 序列號 / 批號 Serial/Batch No. N/A	12 狀態 Status/Work OVERHAULED	
13 備註 Remarks Customer: AJ Walter Aviation Ltd Additional Information: Inspection(s) : PER ATA 72-09-03 Repair(s) : 001 Service Bulletin(s) : N/A Airworthiness Directives(s) : N/A Per : CFMI CFM56-5B ENGINE MANUAL NO. CFMI-TP-SM-9 REFERENCE 72-09-03 REVISION 67, DATE: 15 MAR 2016 REMOVED FROM ESN: 577858 TSN: N/A CSN: N/A		
14 新零件 New Parts 此項修理工作係根據CFR 25.1333(a)之規定，在修理工作完成後，應將所有新零件之清單，填入此表，並附上零件之適航批准標籤，以證明其符合適航要求。此項修理工作，應在適航局之監督下進行，並應在修理工作完成後，將此項修理工作之報告，送交適航局備查。		
15 使用說明書 Used Parts 此項修理工作係根據CFR 25.1333(a)之規定，在修理工作完成後，應將所有使用零件之清單，填入此表，並附上零件之適航批准標籤，以證明其符合適航要求。此項修理工作，應在適航局之監督下進行，並應在修理工作完成後，將此項修理工作之報告，送交適航局備查。		
16 批准人簽名 Signature 17 批准人姓名 (Printed) Name (Printed) Joshua Davidson		
18 批准日期 Date Sep/28/2016		
19 中國民用航空局 Issued by or on behalf of the CAAC F00100660		