

1. Approving National Aviation
Authority/Country:

FAA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

4. Organization Name and Address:

The Boeing Company
1901 Oakesdale Ave SW, M/C 34-02 Renton, WA 98057-2623 P.C. #700

3. Form Tracking Number:

07069663

5. Work Order/Contract/Invoice
Number:

YD5376

6. Item:	7. Description:	8. Part Number:	9. Eligibility:	10. Quantity:	11. Serial/Batch Number:	12. Status/Work:
0001	TOP KIT	E1M06T	N/A	1 EA	N/A	NEW
0002	TOP KIT	M1M06U	N/A	1 EA	N/A	NEW
0003	TOP KIT	Q1M06U	N/A	1 EA	N/A	NEW
0004	TOP KIT	R1M06T	N/A	1 EA	N/A	NEW
0005	TOP KIT	U1M06T	N/A	1 EA	N/A	NEW
0006	TOP KIT	W1M06Z	N/A	1 EA	N/A	NEW

13. Remarks

EXPORT AIRWORTHINESS APPROVAL THIS ARTICLE(S) MEETS THE SPECIAL REQUIREMENTS OF UNITED KINGDOM

14. Certifies the items identified above were manufactured in conformity to:

- ☒ Approved design data and are in a condition for safe operation.
☐ Non-approved design data specified in Block 13.

19.

☐ 14-CFR 43.9 Return to Service ☐ Other regulation specified in Block 13

Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and 14, respect to that work, the items are approved for return to service.

15. Authorized Signature:



16. Approval/Authorization No.:

ODA-300064-NM

20. Authorized Signature:

22. Name (Typed or Printed):
STEVEN D. TRUETT18. Date (m/d/y):
Jun 20 2013

21. Approval/Certificate No.:

23. Date (m/d/y):

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA Form 8130-3 (06-01)

*Installer must cross-check eligibility with applicable technical data

NSN: 0052-00-012-9005

Boeing Packing Slip
279149

Ship From:
SDC Receiving Address
Draft
Boeing Spares Kitting
2201 South 142nd Street
22-01 Door W10
Sea-Tac, WA 98168-3713, United States

Ship To:
Customer Services Division
SSA108
2201 South 142nd Street
Sea-Tac, WA 98168, United States

Date: 10-JUN-13 07:18 PM

S/O: 188631
SIS:
Cust Code:
W/O: M79602016



Delivery Name: 279149



Way Bill:

Line	Item No.	Description	Qty Shipped	Qty B/O	UOM	Lot Number
2.1	005W3505-1	TOPKIT - APU POWER FEEDER CLAMP REPLAC	11.00	0.00	EA	379142



Total Qty: 11.00

TEAM CONTRIBUTORS
STDS PICKER



HIGHBAY PICKER *NONE*

FLOOR PICKER *NONE*

PACKER



Boeing Packing Slip

279149

S/O: 188631

/2.1

Kit Lot: 379142

Total Overboxes: 0

Item: 005W3505-1

Qty: 1

Kit Description: TOPKIT - APU POWER FEEDER CLAMP

W/O: M79602016

Engrg Rev:

Ref	Section Level	Item No.	Description	Per Ay Qty	Reqd Qty	Issued Qty	UM	Ctry Mfg B	Sched	Lot Number	Engrg Rev/ Box
+ 0		005W3505-1	TOPKIT - APU POWER FEEDER CLAMP RE		1	1	EA			379142	PDM/A
1		TA027063-22P	CLAMP	25	25	25	EA				
1		TA027063-24P	CLAMP	25	25	25	EA				

EA 2nd Shift
0089534
R

Ref. Section 1