

1. Approving Civil Aviation  
Authority/Country  
**Transport Canada**

**AUTHORIZED RELEASE CERTIFICATE  
FORM ONE**

3. Form Tracking Number.

**WO8456**

4. Organization Name and Address.

**AJW Technique Inc**  
7055, rue Alexander Fleming  
Saint-Laurent QC H4S-2B7  
Canada

5. Work Order, Contract or  
Invoice Number:

**T18286-1**

| 6. Item | 7. Description:           | 8. Part Number: | 9. Quantity: | 10. Serial/Batch Number: | 11. Status/Work: |
|---------|---------------------------|-----------------|--------------|--------------------------|------------------|
| 1       | Ground Power Control Unit | 740121A         | 1.00         | 0529                     | REPAIRED         |

**12. REMARKS**

UNIT REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 24-41-07 REV. 22 DATED 25SEP2012.  
SEE TEAR DOWN REPORT FOR ADDITIONAL INFO.

PRINTED FROM ELECTRONIC FILE

13a. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.  
☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

- ☒ CAR 571.10 Maintenance Release  
☒ Other regulation specified in Block 12

|                               |                                   |                                               |                                                   |
|-------------------------------|-----------------------------------|-----------------------------------------------|---------------------------------------------------|
| 13b. Signature:               | 13c. Approved Organization Number | 14b. Signature<br><i>Daniel Hebert</i><br>021 | 14c. Approval Organization Number<br><b>33-12</b> |
| 13d. Name (Typed or Printed): | 13e. Date                         | 14d. Name (Typed or Printed)<br>Daniel Hebert | 14e. Date (dd/mm/yyyy)<br>18/Sep/2014             |

**Installer Responsibilities**

This certificate does not constitute authority to install the part.  
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.  
Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

106 2240431





Tear Down/Inspection Report

Work Order #: W08456  
Date Printed: 18/09/2014  
Customer RO: T18286-1

Page: 2

technique



7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7  
www.ajw-aviation.com

PAINTING NO  
PCBR NO  
REPAIR YES  
REWORK NO  
TIME CONTROLLED/TX NO  
RE-QUOTE: NO

CODE: DISASSEMBLY / INSPECTION FINDINGS  
DETAILS: During disassembly and inspection of the unit the following anomalies were found:  
CODE: CLEANING  
DETAILS: Cleaning is required due to...  
CODE: REPAIR  
DETAILS: Observation during disassembly found, the inside very dirty and require cleaning, using neutral cleaning agent.  
CODE: REPAIR  
DETAILS: The following repair(s) will be performed:  
Initial test validated the operation and performance of the equipment and was found satisfactory.  
A visual inspection in needed on all the cards. Unit Need cleaning.  
Also a final test will be performed, to keep the functionality, after opening the unit.

Corrective Actions:

CODE: REPAIRED  
DETAILS: Inspected, Unit cleaned and also a final test performed per CMM.