

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 212587	
4. Organization Name and Address:  900 N. Fiesta Blvd. Gilbert, AZ 85233 480-831-1268 FAX 480-831-1314		5. Work Order/Contract/Invoice Number: W0078679			
6. Item: 1	7. Description: GIMBAL ASSY	8. Part Number: 65B08413-1	9. Quantity: 1	10. Serial Number: FC10	11. Status/Work: OVERHAULED
12. Remarks: OVERHAULED UNIT IAW BOEING CMM 57-52-35, REV #90 DATED NOV 01/13. C/W AD 2005-20-18 & SB 747-57A2316 REV #0 DATED DEC 19/02. TSO:00.00,CSO:00.00					
"AIR TRANSPORT COMPONENTS CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH PART-145 AND IN RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA APPROVAL CERTIFICATE NO: EASA.145.5116." 13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation ☐ Non-approved design data specified in Block 12 13b. Authorized Signature: 13c. Approval/Authorization No: 13d. Name (Typed or Printed): 13e. Date (dd/mm/yyyy):					
14a. ☒ 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. 14b. Authorized Signature:  14c. Approval/Certificate No: Z6AR209Y 14d. Name (Typed or Printed): TRENT DAWKINS 14e. Date (dd/mm/yyyy): 04/MAR/2014					
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engines/propellers/articles from the airworthiness authority of the country specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



900 N. Fiesta Blvd.
Gilbert, AZ 85233
Ph: 480-831-1268

FAA Repair Station #
Z6AR209Y
Fx: 480-831-1314

COMPONENT TEARDOWN/CONDITION REPORT

Customer 10109 AJ WALTER AVIATION LTD. WORK ORDER# W0078679
Nomenclature GIMBAL ASSY MFG CUST-PO# 212587
Part Number 65B08413-1 S/N FC10 A/C

Reason For Removal/Customer Instructions Modifications/S.B/A.D Compliance
OVERHAUL AS REQUIRED IAW MFG SPECS.
DUAL RELEASE REQUIRED.
C/W AD 2005-20-18 & SB 747-57A2316 REV #0 DATED DEC 19/02.

Visual Inspection Prior To Teardown:
UNIT DIRTY. PAINT CHIPPED / WORN.

Preliminary Test Results:
NOT REQUIRED.

Teardown And Inspection Findings:
SLEEVES WORN, ALMEN STRIP WORN, PLATING WORN, REFINISH REQUIRED.
PERFORMED NDT INSPECTION WITH NO DEFECTS FOUND.

Corrective Action Taken:
OVERHAULED UNIT IAW BOEING CMM 57-52-35, REV #90 DATED NOV 01/13.
C/W AD 2005-20-18 & SB 747-57A2316 REV #0 DATED DEC 19/02.
TSO:00.00,CSO:00.00

Final Disposition: OVERHAULED

TECH JDA JEFF ADAMS INSPECTOR TD TRENT DAWKINS DATE MAR/04/2014
For further info contact Roy Hyde at 480-831-1268 FAX 480-831-1314

ATC009



900 N. Fiesta Blvd.
Gilbert, AZ 85233
Ph: 480-831-1268

FAA Repair Station #
Z6AR209Y
Fx: 480-831-1314

COMPONENT TEARDOWN/CONDITION REPORT

Customer 10109 AJ WALTER AVIATION LTD.
Nomenclature GIMBAL ASSY MFG

WORK ORDER# W0078679
CUST-PO# 212587

=====
**** PARTS REPLACEMENT RECORD **** Page 1 of 1
=====

QTY	Item #	Part Number	Nomenclature
1		65B02051-8FAB	SLEEVE
1		65B02051-7FAB	SLEEVE
1		65B02051-8FAB	SLEEVE

ATC009