ation	2.		3. Form Tracking Number.
Authority/Country:	AUTHORIZED RELEASE CERTIFICATE	ASE CERTIFICATE	171040-2
FAA/UNITED STATES	FAA FORM 8130-3, AIRWORTHINESS APPROVAL	THINESS APPROVAL TAG	
4. Organization Name and Address.	SOUTHERN AEROPARTNERS, INC. D/B/A/		
1 4	TULSA, OK. 74107		5. Work Order, Contract or Invoice Number:
	US		Work Order No.: SHY107082
n			Customer RO.: R408375
6. Item 7. Description:	Repair Station No.: QAXX523X	40 Corial	A Station AMOSIC
\top		s. Quantity: 10. Serial Number:	TT. Status/vvork:
1 NON-LOCKING ACTUATOR ASSY	ASSY 1U1524-6	1.00 1429	REPAIRED
12. REMARKS IN ACCORDANCE WITH CMM: 78-30-04 REV: 9 DATE:	DATE: 16-OCT-2019		
NO APPLICABLE A/D'S NOTED ON THIS UNIT AT THIS TIME Certifies that the work specified in Block 11/12 was carried out in for release to service under EASA Part-145 Approval Number 1	NO APPLICABLE A/D'S NOTED ON THIS UNIT AT THIS TIME. Certifies that the work specified in Block 11/12 was carried out in accordance with EA for release to service under EASA Part-145 Approval Number 145.5539	NO APPLICABLE A/D'S NOTED ON THIS UNIT AT THIS TIME. Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number 145.5539	is considered ready
13a. Certifies the items identified above were manufactured in conformity to	were manufactured in conformity to:	14a X 14 CFR 43.9 Return to Service	X Other regulation specified in Block 12
Approved design data and are in a condition for safe operation Non-approved design data specified in Block 12	a condition for safe operation. fied in Block 12	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to se	rwise specified in Block 12, the work identified in Block 11 and s accomplished in accordance with Title 14, Code of Federal in respect to that work, the items are approved for return to service.
13b. Authorized Signature:	13c. Approval Authorization No:	14b. Authorized Signature:	14c. Approval/Certificate No: QAKR523K
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mmm/yyyy):
		JASON SANDERS	28/Apr/2023
	User/Inst	User/Installer Responsibilities	
t is important to understand that the exi	t is important to understand that the existence of this document alone does not automatically constitute authority to install the	ly constitute authority to install the aircraft engine/propeller/article	ler/article.
Where the user/installer performs work is sential that the user/installer ensures	in accordance with the national regulations of an ain that his/her airworthiness authority accepts aircraft t	Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is assential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.	ority of the country specified in Block 1, it is athority of the country specified in Block 1.
Statement in Blocks 13a and 14a do not constitute installation co egulations by the user/installer before the aircraft may be flown.	t constitute installation certification. In all cases aircr he aircraft may be flown.	Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national egulations by the user/installer before the aircraft may be flown.	rtification issued in accordance with the national

EROPARTS

Southern Aeropartners, Inc. D/B/A Tear Down/Inspection 4157 Southwest Blvd

Tulsa, OK. 74107

Work Order #: SHY107082

Date Printed: 28-Apr-23

Page: 1 of 1

AJ WALTER *** THE HEADQUARTERS MAYDWELL AVENUE, SLINFOLD **WEST SUSSEX RH13 0AS UNITED KINGDOM**

Ship To: AJ WALTER *** LOGISTICS CENTRE THE BUSINESS PARK **MAYDWELL AVENUE** SLINFOLD, RH13 UNITED KINGDOM

Cust.PO Ref.: R408375

Cust.Phone: 44 1 40 371 1777

Cust.Email: projectsgroup@ajw-aviation.com

Cust.Code: 310222

Cust.Fax: 1-441403710936

Station: SAI

IN. PN: 1U1524-6

Descr: NON-LOCKING ACTUATOR ASSY

Qty: 1

OUT PN: 1U1524-6

Serial Numbers:

1429

Faults:

*********SHOP REPORT*******

TECHNICIAN / NUMBER / DATE: J McGrail 109953 03-31-2023

P/N & SN ON DATA PLATE MATCHES PO/RO/WO: yes

REASON FOR REMOVAL: leaking

TEAR DOWN FINDINGS: Leaking from gland. Found gland seals and piston bearing worn due to normal operation.

NOTES:

RECOMMENDED WORK SCOPE: "REPAIR"

Corrective Actions:

Replaced gland seals and piston bearing. "REPAIRED" J McGrail 04-26-2023

CMM: 78-30-04 Rev: 9 Date: 16-Oct-2019