

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE			3. Form Tracking Number. WO149825	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada					5. Work Order, Contract or Invoice Number: T42409	
6. Item:		7. Description:		8. Part Number:	9. Quantity:	10. Serial/Batch Number:
1		AUDIO CONTROL PANEL		ACP2788AF01	1.00	1318
11. Status/Work: REPAIRED						
12. REMARKS UNIT INSPECTED,REPAIR AND TESTED PER CMM 23-51-01 REV.10 DATED JAN15/19. FOR FURTHER INFORMATION REFER TEAR DOWN INSPECTION REPORT.						
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12				14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12		
13b. Signature:		13c. Approved Organization Number		14b. Signature 		14c. Approval Organization Number 33-12
13d. Name (Typed or Printed):		13e. Date		14d. Name (Typed or Printed) Sarbjit Toor		14e. Date (dd/mm/yyyy) 03/Nov/2023
Installer Responsibilities						
This certificate does not constitute authority to install the part.						
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.						

Work Order: WO149825

Date Printed: 11/3/2023

Customer RO: T42409

Page: 1

To:

**A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM**

Code: AJW01

Fax:

Descr: AUDIO CONTROL PANEL

Phone:

P/N: ACP2788AF01

Qty: 1

Email:

S/N: 1318

Mfg: TEAM-COBHAM AVIONICS

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: ACP2788AF01

Serial Out: 1318

Symptoms:

CODE: REASON FOR REMOVAL

DETAILS: removed serviceable condition for test inspect and repair has require and certification

Faults:

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS: Reason for removal is unknown.

CODE: INITIAL TEST FAILURE

DETAILS: No Fault Found.

CODE: DISASSEMBLY / INSPECTION FINDINGS

DETAILS: During disassembly and inspection of the unit the following anomalies were found:
unit opened for inspection and cleaning.

CODE: CLEANING

DETAILS: Cleaning is required due to dirty.

CODE: PAINTING

DETAILS: Painting is required due to knobs paint yellowish due to lamp heat.

CODE: REPAIR

DETAILS: Unit need to be clean, repair and test per CMM23-51-01.

Corrective Actions:

CODE: REPAIRED

DETAILS: Unit cleaned, repaired and tested serviceable per CMM 23-51-01.