

1. Approving Civil Aviation Authority/Country FAA/United States		2.		3. Form Tracking Number: W49250	
4. Organization Name and Address: Icon Aerospace, LLC 2617 Executive Point Dr Monroe, NC 28110		5. Work Order/Contract/Invoice Number: W160342		6. Item	
7. Description: SWITCH, SPEED		8. Part Number: 307130-1-1		9. Quantity: 1	
10. Serial Number: P-836		11. Status/Work: INSPECTED/TESTED		12. Remarks: INSPECTED/TESTED in Accordance with HONEYWELL CMM 49-60-49 Rev.:3 Date:22/Dec/2000	
FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W160342					
COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADs): N/A					
COMPLIANCE WITH SERVICE BULLETINS (SBs/EOs): N/A					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.					
14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
13b. Authorized Signature:		13c. Approval/Authorization No.: 68IR700B		14c. Approval/Authorization No.: 68IR700B	
13d. Name (Typed or Printed): Agustin Garcia		13e. Date (dd/mm/yyyy): 17/Nov/2021		14e. Date (dd/mm/yyyy): 17/Nov/2021	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



FAA REPAIR STATION 68IR700B
EASA REFERENCE 145.6295
2617 Executive Point Dr
Monroe, NC 28110
Ph: 704.821.4266 Fax:
Email: quotes@iconaerospace.com

Page 1

WORK ORDER

W160342

Date Released: 17/Nov/2021

TEARDOWN REPORT

AJW AVIATION, LTD.
THE HEADQUARTERS

SLINFOLD, Sussex

Contact: CLARE MARKS

Contact Ph: 44 1403 798000

Contact Fax: 44 1403 710 936

Cust RO#: W49250

P/N: 307130-1-1

S/N: P-836

Desc: SWITCH, SPEED

Mfrgr: HONEYWELL.

Manuals

Loc	ATA	Revision
HW-163	49-60-49	3 22/Dec/2000

Work Requested UNIT RECEIVED FOR BENCH CHECK AS PER O.E.M SPECS

FINDINGS

RECEIVING INSPECTION:
VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND.

PRELIMINARY INSPECTION:
PASSED

HIDDEN DAMAGE:
NONE

CONTINUED INSPECTION:
TESTED. UNIT PASSED FUNCTIONAL TEST. NO FAULT FOUND

CORRECTIVE ACTION: UNIT CONDITION INSPECTED/TESTED
CLEANED UNIT. TESTED AS PER O.E.M SPEC'S.

SB'S, AD'S AND RMK'S:
NONE

CERTIFICATION

SERVICE PERFORMED: ☒ INSPECTED/TESTED

PARTS AND MATERIALS

QTY	PART NUMBER	DESCRIPTION	COND
-----	-------------	-------------	------

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY:

Agustin Garcia

DATE: 17/Nov/2021