		Dis Ca	930
1. Approving Civil Aviation 2. Authority/Country	AUTHORIZED RELEASE	ECERTIFICATE	WO42782
Transport Canada	FORM ONE	IE .	
4. Organization Name and Address.			Work Order, Contract or Invoice Number:
AJW Technique Inc		1 fechnique	W36441-1
Saint-Laurent QC H4S-2B7			
Canada		10 Serial/Batch Number:	mber: 11. Status/Work:
6. Item: 7. Description:	8. Part Number:	9. Quantity: 10. Serial Page 1700	
1 ELAC Elevator and Aileron Computer	3945122506		
12. REMARKS UNIT TESTED SERVICEABLE AS PER CMM 27-93-34C DOWN REPORT.		REV N: 19 DATED APR 23/15 USING TEST PROGRAM 6-H7AD REL.03. FOR MORI	EL.03. FOR MORE INFORMATION REFER TO TEAR
A CONTROL OF THE PARTY OF THE P	つること	Maintenance p	EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17
13a. Certifies the items identified above were manufactured in conformity to:	tured in conformity to:	14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation	fied in Block 12, the work identified in Block d in accordance with Canadian Aviation
Approved design data and are in a condition for safe operation	safe operation	Regulations.	
Non-approved design data specified in Block 12		X CAR 571.10 Maintenance Release	
		Other regulation specified in Block 12	
13b. Signature: 13c. A	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number 33-12
13d. Name (Typed or Printed): 13e. Date	ate	14d. Name (Typed or Printed) EI Bachir Rabet	14e. Date (dd/mmm/yyyy) 11/Nov/2016
	installer F	Installer Responsibilities	
This certficate does not constitute authority to install the part Installers working in accordance with the national regulations	ne part. Jations of a country other than specified i	This certficate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Biock 1, must ensure that their regulations recognize certifications from the	certifications from the
country specified. Statements in blocks 13a or 14a do not constitute installation conspicable national regulations before the aircraft may be flown.	allation certification. In all cases,the techrobe flown.	country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft may be flown.	certification issued in accordance with the



7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7 www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO42782 Date Printed: 11/11/2016 Customer RO: W36441-1

Page: 1

To:

A J WALTER AVIATION LIMITED THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM

Phone #:

Fax #:

PN: 3945122506

Serial #: 1787

Email:

Qty: 1

Mfg: THALES

TSN: N/A

Code: AJW01

TSO: 0

Descr: ELAC Elevator and Aileron Computer

TSR: 0

CSN: N/A CSO: 0

CSR: 0

P/N Out: 3945122506

Serial # out: 1787

Symptoms:

CODE: DETAILS:

REPAIR

PFR MSG: F/CTL ELAC 2 FAULT.

PLEASE CONSIDER FOR WARRANTY AGAINST PREVIOUS RO W30240 (WO25780)

Faults:

CODE:

QUOTE

DETAILS:

PRELIMINARY INSPECTION (VISUAL):

PART MISSING:

NO NO

DAMAGE FOUND (CID): HRS/CYCLE RECEIVED:

N/A

ADDITIONAL REQUIREMENT:

WARRANTY REQUESTED?

AD, SB, MOD, SIL

NO NO

ADD.CUST. REQUEST

YES

TEST ARRIVAL:

INITIAL TEST FAIL? NO

REASON FOR REMOVAL CONFIRMED: NO

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION:

NO

WORK TYPE:

TEST

WORKSCOPE:

CALIBRATION CLEANING

NO NO

OUT OF SCOPE OVERHAUL

NO NO



7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7 www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO42782 Date Printed: 11/11/2016 Customer RO: W36441-1

Page: 2

NO PAINTING NO **PCBR** NO REPAIR NO REWORK TIME CONTROLLED/TX NO

NO

RE-QUOTE:

WARRANTY REQUESTED CODE:

Warranty expired on Oct 04th 2016. Also, last visit was covered under warranty so, in fact, the FOC warranty truly ended on July DETAILS:

15th 2016. Also the unit did not fail after being tested two times under normal temperature and one time under hot temperature.

NO FAULT FOUND

CODE:

UNIT PASSED THE TEST ARRIVAL ON ATEC 6 WITHOUT FAILURE. THE UNIT WAS TESTED TWO MORE TIMES UNDER DETAILS:

NORMAL AND HOT TEMPERATURE AND IT DID NOT FAIL. NO FAULT FOUND.

Corrective Actions:

INSPECTED/ TESTED

UNIT TESTED SERVICEABLE AS PER CMM 27-93-34C REV N: 19 DATED APR 23/15 USING TEST PROGRAM 6-H7AD CODE: DETAILS:

REL.03.