

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: WO1064348	
4. Organization Name and Address: Barfield, Inc. 4101 NW 29th Street MIAMI, FL, 33142 Repair Station No: XBIR995K				5. Work Order/Contract/Invoice Number: U16373	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	UPLOCK	C24730100	1.00	H2889	OVERHAULED
12. Remarks: UNIT OVERHAULED I/AW TECHNICAL DATA LISTED BELOW: CMM 32-37-09 REV: 11 DATE: 8/28/2019 AD & S/B: N/A TSN: UNK TSR: UNK TSO: 0 CSN: UNK CSR: UNK CSO: 0 Incoming Amdt/Mod Level: NONE Outgoing Amdt/Mod Level: NONE Refer to teardown report for details of work accomplished Barfield Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 Approval Number: EASA.145.4239 13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12 13b. Authorized Signature: 13c. Approval Authorization No.: 13d. Name (Typed or Printed): 13e. Date (dd/mm/yyyy): 14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. 14b. Authorized Signature: <i>Robert Rosello</i> 14c. Approval/Certificate No.: XBIR995K 14d. Name (Typed or Printed): ROBERT ROSELLO 14e. Date (dd/mm/yyyy): 04/Nov/2019 User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Barfield, Inc.
4101 NW 29th Street
MIAMI, FL, 33142

Teardown

WO: WO1064348

RO: U16373

FAA CRS #: XBIR995K

To:

AJ WALTER AVIATION LTD.
MAYDWELL AVENUE,
SLINFOLD, WEST SUSSEX
UNITED KINGDOM RH13 0AS

AJ WALTER AVIATION LTD.
B AND H WOLDWIDE INC DORAL
1523 NW 82ND AVENUE
DORAL, FL 33126
UNITED STATES OF AMERICA

Incoming PN: C24730100

Descr: UPLOCK

S/N: H2889

Incoming Work Req: OVERHAUL

Outgoing PN: C24730100

Mfg: F6137

Warranty: No

Outgoing Work Req: OVERHAULED

Removal Date:

Tail Number:

Station:

Position:

Manuals: TYPE: CMM PUB: 32-37-09 REV: 11 DATE: 8/28/2019

Tools:

SYMPTOMS:

REASON FOR REMOVAL

OVERHAUL

FAULTS:

FAULT

UNIT RECEIVED FOR OVERHAUL. FAILS PRETEST DUE TO WORN SEALS.

CORRECTIVE ACTIONS:

Overhauled

ALL DEFECTIVE AND REQUIRED PARTS WERE REPLACED. CLEANED OVERHAULED AND TESTED UNIT IAW CMM 32-37-09 REV 11.

Technician: CHRISTOPHER ANTUNEZ RAMOS

Date: 11/4/2019

Inspector:

ROBERT ROSELLO

Signature:



Barfield, Inc.
4101 NW 29th Street
MIAMI, FL, 33142

Teardown

WO: WO1064348

RO: U16373

FAA CRS #: XBIR995K

To:

AJ WALTER AVIATION LTD.
MAYDWELL AVENUE,
SLINFOLD, WEST SUSSEX
UNITED KINGDOM RH13 0AS

AJ WALTER AVIATION LTD.
B AND H WOLDWIDE INC DORAL
1523 NW 82ND AVENUE
DORAL, FL 33126
UNITED STATES OF AMERICA

Incoming PN: C24730100

Descr: UPLOCK

S/N: H2889

Incoming Work Req: OVERHAUL

Outgoing PN: C24730100

Mfg: F6137

Warranty: No

Outgoing Work Req: OVERHAUL

Removal Date:

Tail Number:

Station:

Position:

Manuals: TYPE: CMM PUB: 32-37-09 REV: 11 DATE: 8/28/2019

Tools:

Fig-Item	PN	Description	CD	Qty
	282101	WASHER, MARKING	SV	4.00
	A88915	STOP	SV	1.00
	A88916	STOP	SV	1.00
	C95-54001	SCRAPER	SV	1.00
	C95-54001	SCRAPER	SV	1.00
	M8791-1-012	RETAINER, PACKING, BACK-UP, TEFLON .373	SV	1.00
	M8791-1-021	SEAL	SV	1.00
	M8791-1-022	RETAINER	SV	2.00
	M8791-1-022	RETAINER	SV	1.00
	M8791-1-115	RING BACK UP	SV	2.00
	MS21914-4W	PROTECTIVE CAP	SV	2.00
	MS24665-151	PIN COTTER	SV	5.00
	MS24665-86	PIN COTTER	SV	4.00
	NAS1611-012A	PACKING, PREFORM, HYDRAULIC .364X.070	SV	1.00
	NAS1611-012A	PACKING, PREFORM, HYDRAULIC .364X.070	SV	1.00
	NAS1611-021A	PACKING	SV	1.00
	NAS1611-022A	PACKING, PREFORM, HYDRAULIC .989X.070	SV	1.00
	NAS1611-022A	PACKING, PREFORM, HYDRAULIC .989X.070	SV	1.00
	NAS1611-115A	PACKING, PREFORM, HYDRAULIC .674X.103	SV	1.00
	NAS1612-4A	O-RING	SV	4.00

Technician: CHRISTOPHER ANTUNEZ RAMOS

Date: 11/4/2019

Inspector: ROBERT ROSELLO

Signature: