

1. Approving Civil Aviation Authority/Country: FAA/United States	2.	Authorized Release Certificate FAA Form 8130-3, Airworthiness Approval Tag		3. Form Tracking Number: R405703	
4. Organization Name and Address: AOG ACCESSORIES 2549 NW 74th Avenue, Miami, FL 33122 USA Phone: 305-591-1899 Fax: 305-489-0176 FAA APPROVED REPAIR STATION NO. XB4R642M * EASA 145.5924				5. Work Order/Contract/ Invoice Number: 28123	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	WASTE DRAIN VALVE	14320-020	1ea.	488	REPAIRED
12. Remarks: REPAIRED in accordance with CMM 38-34-25, Revision 06, Dated Dec 02, 2021. Full details of work carried out per work order no. 28123 FAA A.D: Not Applicable EASA A.D: Not Applicable SB: Not Applicable A/C REG: XA-CBV Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work, the WASTE DRAIN VALVE is considered ready for release to service under EASA Part 145 approval no. EASA 145.5924					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14.a ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		14c. Approval/Certificate No.: XB4R642M	
13b. Authorized Signature: Not Applicable		14b. Authorized Signature: 		14e. Date (dd/mm/yyyy): 26/Apr/2023	
13d. Name (Typed or Printed): Not Applicable		14d. Name (Typed or Printed): ALFONSO OJEDA			
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

TearDown/Inspection Form

AOG ACCESSORIES

2549 NW 74th Avenue,
Miami, FL 33122

USA

Phone: 305-591-1899 Fax: 305-489-0176

C.R.S. No.: XB4R642M

Work Order: 28123

Date: Jan/30/2023

Page 1 of 1

Sold to:

AJ WALTER AVIATION, LTD
THE HEADQUARTERS MAYDELL AVE SLINFOLD RH13OAS
WEST SUSSEX
WEST SUSSEX, RH13OAS
United Kingdom

Ship to:

AJ WALTER AVIATION, LTD
THE HEADQUARTERS MAYDELL AVE
SLINFOLD RH13OAS WEST SUSSEX
WEST SUSSEX, SUSSEX RH13OAS
United Kingdom

Part Number: 14320-020

Serial: 488

Manufacturer: SAFRAN

Description: WASTE DRAIN VALVE

Model:

Purchase Order: R405703

Service Performed: REPAIR

Data used:

Manual Number: 38-34-25

Revision: 06

Date: 12/02/2021

Teardown/Inspection Data

1.- Trouble Reported

DEFECTIVE - INOP

Appearance: Normal

Loose or Missing Parts: No Loose or Missing Parts

Corrosion: No Corrosion Noted.

Physical Damage: No Damage Found

2.- Teardown

Disassembly: Only as Required for Repair

Painting: None Performed

Cleaning: Performed cleaning as required.

Assembly: As Required

3.- Test

Operation: Tested I/A/W Mfg. Specs.

Modifications: None

Was Complaint Verified: Yes

Others problems found: None

4.- Final Inspection

Warranty Accepted: N/A

FAA A.D : No AD required.

EASA A.D : No AD required.

Final Test and Inspection : Final Inspection Normal.

FAA S.B: No SB required

EASA S.B : No SB required.

5.- Work Performed

P/N and S/N verified. Unit received in poor condition and failed preliminary functional test due to being inoperative. Unit was disassembled, cleaned, and inspected in accordance with CMM 38-34-25. Inspection revealed damaged pivot ring, worn packings and seals, defective self-locking nut, pin spring, shoulder washer and thrust washer. Unit was Repaired and Tested IAW OEM CMM 38-34-25 Rev. No. 06 dated 12/02/2021. Performed replacement of defective and sealing components, cleaning and sanitizing. A/C REG: XA-VBV.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Order no.: 28123

Inspector's Name: ALFONSO OJEDA

Technician: Carlos Telleria

Signature:



Date: Apr/26/2023

Inspector

Form: AOG 103 Original 03/17/2014