

1. Approving Civil Aviation  
Authority/Country  
**Transport Canada**

2. **AUTHORIZED RELEASE CERTIFICATE  
FORM ONE**

3. Form Tracking Number.  
**WO126869**

4. Organization Name and Address:

**AJW Technique Inc**  
7055, rue Alexander Fleming  
Saint-Laurent QC H4S-2B7  
Canada



5. Work Order, Contract or  
Invoice Number:  
**R397455-1**

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Battery Charger	4-254-04	1.00	C5012	REPAIRED

12. REMARKS

REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 24-31-04 REV 17 DATED JUL 14, 2022.  
FOR ADDITIONAL INFORMATION SEE TEAR DOWN/INSPECTION REPORT.



EASA Approval No.: EASA.145.7260  
Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.  
☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

- ☒ CAR 571.10 Maintenance Release  
☒ Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature  	14c. Approval Organization Number <b>33-12</b>
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed) Eloi Dion	14e. Date (dd/mm/yyyy) 06-Oct-2022

Installer Responsibilities

This certificate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.  
Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

# AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada  
www.ajw-group.com

## Tear Down/Inspection Report

Work Order: WO126869

Date Printed: 2022-10-06

Customer RO: R397455-1

Page: 1

### To:

A J Walter Aviation Ltd.  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD, WEST SUSSEX RH13 0AS  
UNITED KINGDOM

Code: AJW01

Fax:

Descr: Battery Charger

Phone:

P/N: 4-254-04

Qty: 1

Email:

S/N: C5012

Mfg: ELDEC CORPORATION

TSN: N/A

TSO: N/A

TSR: N/A

CSN: N/A

CSO: N/A

CSR: N/A

P/N Out: 4-254-04

Serial Out: C5012

### Symptoms:

CODE: SCHEDULED MAINTENANCE

DETAILS:

### Faults:

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS: Reason for removal is confirmed.

CODE: INITIAL TEST FAILURE

DETAILS: - Unit passed the test.  
- Will inspect internally as per CMM.

CODE: DISASSEMBLY / INSPECTION FINDINGS

DETAILS: - Unit dirty.

CODE: REPAIR

DETAILS: - Unit will be thoroughly cleaned.  
- Final test required.

### Corrective Actions:

CODE: REPAIRED

DETAILS: - Cleaned unit.  
- Repaired and tested serviceable in accordance with CMM 24-31-04 REV 17 DATED JUL 14, 2022.