

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 921 - 401419	
4. Organization Name and Address:  AERO INSTRUMENTS & AVIONICS, INC. 7290 NASH ROAD NORTH TONAWANDA, NEW YORK 14120-1596 (NCIR343K)		5. Work Order/Contract/Invoice Number: R251467			
6. Item: 1	7. Description: MICROPHONE	8. Part Number: 602-3373	9. Quantity: 1	10. Serial Number: 0918365	11. Status/Work: REPAIRED
12. Remarks: COMPONENT REPORT # 401419 DESCRIBING THE ACTUAL WORK PERFORMED IS ATTACHED. THE DESCRIBED WORK WAS PERFORMED REFERENCING THE CURRENT ELECTRO VOICE ORIGINAL EQUIPMENT SPECIFICATIONS LISTED AND/OR CUSTOMER SPECIFICATIONS. CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART-145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART-145 APPROVAL NUMBER: EASA.145.4037 MANUAL 38110-036 REV # C DATE 01/Jun/2010					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		14b. Authorized Signature: 		14c. Approval/Certificate No.: NCIR343K	
13d. Name (Typed or Printed):		14d. Name (Typed or Printed): WAYNE D SMITH		14e. Date (dd/mm/yyyy): 23/Dec/2014	
13e. Date (dd/mm/yyyy): 					
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

COMPONENT REPORT



AERO INSTRUMENTS & AVIONICS, INC.

7290 NASH ROAD

NORTH TONAWANDA, NY 14120

PHONE: 716-694-7060 FAX: 716-694-7594

www.aeroinst.com

FAA Approved Repair Station # NC1R343K

EASA Approved Maintenance Organisation EASA.145.4037

A. J. WALTER (AVIATION) LTD.
THE HEADQUARTERS, MAYDWELL AVE
SLINFOLD, WEST SUSSEX RH13 0SH
UNITED KINGDOM

Cust #	Work Order #	Date Rec.	Customer PO	Date Comp	Aircraft #
921	401419	12/11/2014	R251467	12/23/2014	XA-VAB

Description	Part Number	Serial #	Mfr. Name
MICROPHONE	602-3373	0918365	ELECTRO VOICE

Removal Reason Was : Not Verified
This Unit Was : Repaired
And Is : Continue Time

Reason For Removal :
INOP

Shop Findings :

BENCH CHECK FOUND UNIT OPERATION NORMAL BUT FOUND FLEX RELIEF ASSEMBLY BROKEN.

Details Of Work Accomplished :

DISASSEMBLED UNIT. INSPECTED ALL PARTS. REPLACED FLEX RELIEF ASSEMBLY. REASSEMBLED UNIT. PERFORMED A COMPLETE FUNCTIONAL TEST IAW MFG'S C.M.M. UNIT OPERATED WITHIN REQUIRED SPECS. UNIT CERTIFIED AIRWORTHY.

Mod Level: NONE

Test Spec: 38110-036

Rev: C

Rev Date: 6/1/2010

Applicable AD's : NO

Completed By :

MINH DANG

Tested By :

MINH DANG

Inspected By :

WAYNE D SMITH

** See Invoice For Full Parts Breakdown **

The purpose of this report is to furnish information only. It is not to be used or accepted as the basis for issuance of a Airworthiness Approval Tag. This report must be retained with component.