

1. Approving Competent Authority / Country

LBA / Germany

61903667

3. Form Tracking Number

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

21592807 00000001

4. Organisation Name and Address:



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

5. Work Order/Contract/Invoice

61903667

6. Item

7. Description

8. Part No.

01 EXCHANGER-PRECOOLER

12. Remarks

3732A010000

9. Qty.

10. Serial No.

1

2307

11. Status / Work

OVERHAULED

APOC Aviation RO220623

ATA 3611

TP O

MK-No. 10

Pack Code 00

Resp. Workshop 33343050

THE DENT ON THE TUBES ARE ACCEPTABLE AS PER LEBHERR SPM 20-00-01
REV.2, DATED FEB/10/2020.

Workshop Station HAM143

TT UNKNOWN Cycle Op. Day
TSO UNKNOWN UNKNOWN
TSC 0 0 0
TSF 0 0 0
TASK PERFORMED IN ACCORDANCE WITH CMM 36-11-19
REV.5 / CMDS 36-11-19 ISSUE 017

Return to Service in Accordance with 14 CFR part 43
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under

FAA Certificate No.: DLAY225D

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in a condition for safe operation

☐ non-approved design data specified in block 12

14a. ☒ Part-145, A-50 Release to Service

Further details of work performed are attached either in a Workshop Report reference number see blocks 3 and 5 or in other applicable documents
☒ Other Regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature

13c. Approval / Authorisation Number

13d. Name

13e. Date (dd mmm yyyy)

14b. Authorised Signature

\$50584

14d. Name

Bryan-Jason Kubeil

14c. Certificate / Approval Ref. Number

DE.145.0001

14e. Date (dd mmm yyyy)
18 Oct 2022

EASA FORM 1 - Issue 3

USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report

61903667



Lufthansa Technik

Lufthansa Technik AG
Weg beim Jäger 193
22335 Hamburg
Germany

Certificate Ref. No.

21592807 00000001

Work Order/Contract/Invoice

61903667

Serial No. as received

2307

Description

EXCHANGER-PRECOOLER

Serial No. as dispatched

2307

Responsible Workshop

33343050

Reason for removal
OH IS REQUESTED

Findings

DIRTY,
LEAKAGE 0 NL/MIN,
HANDLE MISSING,
SCRATCHES,
FLANGE BENT.

Action

CLEANED,
CRACKS WELDED,
HANDLE RENEWED,
FLANGE STRAIGHTENED,
SCRATCHES POLISHED,
LEAKAGE TEST O.K.,
AIR PRESSURE LOSS TEST O.K.,
THE DENT ON THE TUBES ARE ACCEPTABLE AS PER LIEBHERR SPM 20-00-01 REV.2, DATED FEB 10/20.

Modification Status according to Mod-Label

See Unit Mod-Label if equipped

Name

550584, Bryan-Jason Kubeil

Date (dd mm yy)

18 Oct 2022

The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.

LHT Form 30992 H-19) (HAM T/CE-Q)