



1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 1389	
4. Organization Name and Address: 1ST CHOICE AEROSPACE 825 Lindbergh Court, Suite 400, Hebron, KY 41048, Fax: 859/283-0509, 859/283-2264				5. Work Order/Contract/Invoice Number: 1010408 / R29483	
6. Item:		7. Description:		8. Part Number:	
001		SEAT-ATTENDANT		DN01TYT3YS00054	
9. Quantity:		10. Serial Number:		11. Status/Work:	
1		02T1897		REPAIRED	
12. Remarks: The component listed above was maintained in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station and are available upon request. This item was Repaired I/A/W Manual # 25-11-98, Revision # 11 Revision Date 21/Oct/2013 VERIFIED COMPLIANCE WITH EASA AD 2013-0020 R4					
1st Choice Aerospace Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and with respect to that work the aircraft component is considered ready for release to service under EASA Approval Certificate Number Part-145 EASA.145.6132.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in Block 12.					
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12	
				Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13d. Name (Typed or Printed)		13e. Date (dd/mm/yyyy).		14b. Authorized Signature:  1st INSP 09	
DAN RUSH				14c. Approval/Certificate No.: A8QR552Y	
14d. Name: (Typed or Printed) DAN RUSH					
14e. Date (dd/mm/yyyy): 26/Jun/2015					
User/Installer Responsibilities					
It is important to understand that the existence of this Document alone does not automatically constitute authority to install the aircraft/engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts aircraft engine(s)/propeller(s)/article(s) from the Airworthiness Authority of the country specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.					

WORK ORDER FORM 100

Page No. 1



FAA CRS No: A8QR552Y

WORK ORDER: 1010408-15

1ST CHOICE AEROSPACE

325 Lindbergh Court, Suite 400

Hebron, KY 41048

Fax: 859/283-0509

859/283-2264

Customer: AIR008 / AIRLINE SERVICES COMPONENT

Cust RO#: R29483

Mfg: ZODIAC ZODIAC

Outgoing DN01TYT3YS00054 / SEAT-ATTENDA

Step: FINAL ASSEMBLY/TEST/IN

*** NO PMA PARTS ***

S/N: 02T1897

Dept#: INTR

Location:

Warranty Code: 00 / 365

Goodthru AD#:

Incoming P/N: DN01TYT3YS00054

Incoming S/N: 02T1897

Incoming Work Req.: REPAIR

Outgoing Work Req: REPAIR

Manual#: 406

RevDate: 21/Oct/2013 Rev#: 11

ATA: 25-11-98

Reason/Rm:

TEST AND RECERTIFICATION

Date Recvd: 13/May/2015 Date Reqrd: 28/May/2015

Date Estmtd: 11/Jun/2015

PRELIMINARY INSPECTION:

DATE: 18/May/2015

INSPECTOR: DJR 1022

PART NUMBER & SERIAL NUMBER VERIFIED

1st
INSP
09

PRE TEST (Yes/No): Y

DATE: 18/May/2015

INSPECTOR: DJR 1022

PRETEST FAILED

UNIT REQS REPAIR

1st
INSP
09

HIDDEN DAMAGE:

N/A

TEARDOWN FINDINGS:

BOTTOM COVER WORN, BOTTOM CUSHION DETERIORATED, TOUCH UP PAINT, LH ROT
ARY BELT TSO TAG ILLEGIBLE.

EASA AD 2013-0020 R4 INSPECTED, FOUND TO BE IN COMPLIANCE.

TECHNICIAN: BDH 1010

DATE: 18/May/2015 INSPECTOR: DJR 1022

FINAL INSPECTION BEFORE ASSEMBLY:

DATE: 18/May/2015 INSPECTOR: DJR 1022

1st
INSP
09

1st
INSP
09

CORRECTIVE ACTION:

REPLACED DEFECTIVE PARTS, ASSEMBLED AND TESTED.
UNIT REPAIRED AND TESTED AND FOUND TO BE SERVICEABLE
IN ACCORDANCE WITH MANUFACTURERS SPECIFICATIONS.

*VERIFIED COMPLIANCE WITH EASA AD 2013-0020 R4

TECHNICIAN: PXO 1101

DATE: 25/Jun/2015 INSPECTOR: DJR 1022

1st
INSP
09

MODIFICATION/SERVICE BULLETINS:

NONE

Test Data Used: CMM 25-11-98

Test Technician: PXO 1101

Final Inspection: DJR 1022

1st
INSP
09

DATE: 26/Jun/2015

DATE: 26/Jun/2015

Printed 02/Jul/2015

14:55:10

STACY-PC

Labor Task Control#



WORK ORDER FORM 100

Page No. 2



FAA CRS No: A8QR552Y

WORK ORDER: 1010408-15

ST CHOICE AEROSPACE

25 Lindbergh Court, Suite 400

Hebron, KY 41048

Fax: 859/283-0509

859/283-2264

Customer: AIR008 / AIRLINE SERVICES COMPONENT

Cust RO#: R29483

Mfg: ZODIAC ZODIAC

Outgoing DN01TYT3YS00054 / SEAT-ATTENDA

Step: FINAL ASSEMBLY/TEST/IN

* * * NO PMA PARTS * * *

S/N: 02T1897

Dept#: INTR

Location:

Warranty Code: 00 / 365

Goodthru AD#:

ADDITIONAL COMMENTS:

NONE

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by DAN RUSH



Date 26/Jun/2015

