1. Approving Civil Aviation Authority/ Country:	2.	3. Form Tracking Number:
FAA/United States	**Authorized Release Certificate** FAA Form 8130-3, Airworthiness Approval Tag	130979

4. Organization Name and Address:	5.Work Order/Contract/ Invoice Number:
Aviation Instruments Repair Specialists, Inc. VTBR433V A.I.R.S./14316 Commerce Way Miami Lakes, FL 33016 U.S.A. Phone: (305) 887-5600 Fax: (305) 820-0931	T26987

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	CONTROL PANEL ASSY.	233T3216-10	1ea.	D00668	INSPECTED

12. Remarks:

INSPECTED in accordance with CMM: 33-24-02. Revision: 4 Date: 8/26/2010

Full details of work carried out per work order no. 130979

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the CONTROL PANEL ASSY. is condidered ready for release to service under EASA Part 145 approval no. EASA EASA.145.5033 .

No applicable A.D. or S.B. Required.

ECCN #9A991D.

13a. Certifies the items identified above were manufactured in conformity to:	14a. [X] 14 CFR 43.9 Return to Service [X] Other regulation specified in Block 12
☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplish in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
Not Applicable	Not Applicable		VTBR433V
13d. Name (Typed or Printed):	**13e. Date (dd/mmm/yyyy):**	**14d. Name (Typed or Printed)**	**14e Date (dd/mmm/yyyy):**
Not Applicable	Not Applicable	Marshall Garber	03/Nov/2015

User/Installer Responsibilities

It is important to understand that the existance of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block1.

Statements in Block13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

TearDown/Inspection Form

Aviation Instruments Repair Specialists, Inc.

A.I.R.S./14316 Commerce Way
Miami Lakes, FL 33016
U.S.A.
Phone: (305) 887-5600 Fax: (305) 820-0931
C.R.S. No.: VTBR433V

Work Order: 130979
Date: November/3/2015

Phone:(305) 887-5600
Fax: (305) 820-0931

Sold To:
A J WALTER AVIATION
The Headquarters, Maydwell Ave. Slinfold
West Sussex RH13 0SH, UK

Ship To:
A J WALTER AVIATION LIMITED
THE HEADQUARTERS MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 OSH

Part Number: 233T3216-10 **Serial:** D00668 **Manufacturer:** BAE SYSTEMS
Description: CONTROL PANEL ASSY. Model: 233T3216-10
Purchase Order: T26987 **Service Performed:** INSPECTED
Data used: **Manual Number: 33-24-02.** **Revision: 4** **Date: 8/26/2010**

Teardown/Inspection Data

1. Removal: NONE GIVEN
Inst.: BC

2. Initial Inspection Findings
Appearance: Normal on Visual Inspection **Corrosion:** No Corrosion Noted
Loose or Missing Parts: No Loose or Missing Parts **Physical Damage:** No Damage Found
Mod. Level: N/A

3. Teardown
Dissassembly: None **Cleaning:** None
Painting: None **Assembly:** None

4. Test
Operation: Operation I/A/W Mfg. Specs **Was Complaint Verified:** N/A
Mods. Completed: None

5. Final
Warranty Accepted: N/A **Final Test and Inspection:** Final Inspection Normal
T.S.O.: TSO **A.T.A.:** 33-24-02 **A.D. S.B.** NO A.D. / S. B. REQUIRED

Work Done: UNIT WAS INSPECTED, TESTED IN ACCORDANCE WITH MFG. SPECS. ALL WORK PERFORMED WITH FAA APPROVED DATA. ATA 33-24-02. WORK PERFORMED BY MIGUEL TORRES. ECCN #9A991D.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work Order No.: 130979

Inspector's Name: Marshall Garber **Technician:** Miguel Torres
Certificate No. 2506369

Signature: _____ **Date:** **November/03/2015** Form CRS-3