1. Approving Civil Aviation Authority/Country:	2.	3. Form Tracking Number:
FAA/UNITED STATES	**AUTHORIZED RELEASE CERTIFICATE** FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG	**130344**

4. Organization Name and Address:	5. Work Order/Contract/Invoice Number:
Aero Accessories & Repair, Inc. **FAA CERT #77AR783B** **15351 SW 29th ST SUITE 600** **MIRAMAR, FL 33027** **Ph: 954-266-1300,** FAA Approval Holder: 77AR783B	**33726** **R372927**

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	IGV ACTUATOR ASSEMBLY	4504086	1	1977	OVERHAULED

12. Remarks:

The component identified above was OVERHAULED in accordance with Federal Aviation Regulation and is approved for return to service with respect to the work performed. Pertinent details of the work accomplished are on the file at this agency under Form Tracking Number identified above.

AC REG: YL-LCO
TSO: 0.00 FH

FAA & EASA S/B and A/D's: None Applicable.

ORIGINAL

OEM CMM: 49-23-05, Revision#: 10, Revision Date:2/15/2019

Certifies work specified in blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA part 145 Approval Number EASA 145-6467

13a. Certifies the items identified above were manufactured in conformity to:	14a. [X] 14 CFR 43.9 Return to Service [X] Other regulation specified in Block 12
[ ] Approved design data and are in a condition for safe operation. [ ] Non-approved design data specified in Block 12	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.
13b. Authorized Signature: / 13c. Approval Authorization No.:	14b. Authorized Signature: / 14c. Approval/Certificate No.: 77AR783B
13d. Name (Typed or Printed): / 13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed): ALFONSO OJEDA / 14e. Date (dd/mmm/yyyy): 06-Mar-2020

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Aero Accessories & Repair, Inc.
FAA CERT #77AR783B
15351 SW 29th ST SUITE 600
MIRAMAR, FL 33027
Ph: 954-266-1300,

Tear Down/Inspection

Work Order #: 33726

Date Printed: 3/6/2020

Time: 10:32:32 AM

Page: 1

To:
AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, SLI RH13 0AS
UNITED KINGDOM

Ship To:
AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WS RH13 0AS
UNITED KINGDOM

Ref #: R372927	**Phone #:** 305 470 8007	**Fax #:** 441.403.710.936	**Email:** Accounting - sarah.adam@ajw-aviati
Code: 45	**Site:** JL/KM	**PN:** 4504086	**Descr:** IGV ACTUATOR ASSEMBLY
Qty: 1	**Station:** FUEL	**Make:**	**Model:** **Mfg:** _

Serial Numbers: 1977

Symptoms:

RECEIVING INSPECTION

P/N AND S/N WAS VERIFIED ON UNIT AND CUSTOMER RO. NO EXTERNAL DAMAGE NOTED. NO AD APPLICABLE. SEE RO FOR WORKSCOPE. TECH MUST VERIFY.

PRELIMINARY INSPECTION

P/N 4504086 AND S/N 1977 VERIFIED ON UNIT AND CUSTOMER RO. NO OBVIOUS EXTERNAL DMAGE NOTED.

Faults:

HIDDEN DAMAGE

NONE FOUND.

INITIAL FINDINGS

UNIT FAILED PRETEST DUE TO INTERNAL LEAKAGE. REQUIRES TEARDOWN FOR FURTHER EVALUATION.

TEARDOWN INSPECTION

UNIT WAS DISASSEMBLED, CLEANED AND INSPECTED IAW OEM CMM 49-23-05 REV. 10 DATED FEB. 15, 2019 AND FOUND WORN PACKINGS AND SEALS. UNIT REQUIRES 100% KIT FOR OVERHAUL.
OVERHAUL QUOTE. TECH: A.F. # 31.

Corrective Actions:

CORRECTIVE ACTION

UNIT WAS OVERHAULED AND TESTED IAW OEM CMM 49-23-05 REVISION #10 DATED FEB 15, 2019. REPLACED ALL DEFECTIVE AND WORN PARTS. MINOR NICKS AND SCRATCHES DO NOT AFFECT FIT, FORM, OR FUNCTION ON THIS UNIT.
AC REG: YL-LCO
TSO: 0.00 FH
TECH: A.V. #43

Authorized Signature: _____

Name: ALFONSO OJEDA

Date: 3/6/2020

Form created with Quantum Control(tm) technology. Product Licensed to: Aero Accessories & Repair, Inc.