

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number. WO146574	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: T41827	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	TRANSMITTER-LIQUID LEVEL	G540DA74	1.00	07460611	INSPECTED/TESTED
12. REMARKS UNIT HAS BEEN INSPECTED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 38-32-53 REVISION 05 DATED Jan 10/2019. FOR ADDITIONAL INFORMATION REFER TO TEAR DOWN / INSPECTION REPORT.					
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12			
13b. Signature:		13c. Approved Organization Number		14b. Signature  14c. Approval Organization Number 33-12	
13d. Name (Typed or Printed):		13e. Date		14d. Name (Typed or Printed) Vincent Crete 14e. Date (dd/mm/yyyy) 18/Oct/2023	
Installer Responsibilities					
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

Tear Down/Inspection Report

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01 Fax: Descr: TRANSMITTER-LIQUID LEVEL

Phone: P/N: G540DA74 Qty: 1
Email: S/N: 07460611 Mfg: DIEHL

TSN: UNK TSO: UNK TSR: UNK CSN: UNK CSO: UNK CSR: UNK

P/N Out: G540DA74 S/N Out: 07460611

Symptoms:

CODE: REASON FOR REMOVAL
DETAILS: Removed serviceable for test and certification

Fault:

CODE: NO FAULT FOUND
DETAILS: No fault were found during the initial test
The unit was tested multiple times with same results each time.
CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION
DETAILS: Reason for removal is UNKNOWN
CODE: INITIAL TEST FAILURE
DETAILS: Initial test failure is attributed to...NO FAILED detected
CODE: TEST AND RECERTIFY
DETAILS: unit test and certify per CMM spec 38-32-53 latest revision

Corrective Actions:

CODE: INSPECTED/ TESTED
DETAILS: Unit has been inspected and tested serviceable in accordance with CMM 38-32-53 Rev. 05 dated Jan 10/2019.