1. Approving Civil Aviation Authority/Country	2.	3. Form Tracking Number.
Transport Canada	**AUTHORIZED RELEASE CERTIFICATE** *FORM ONE*	**WO30665**

4. Organization Name and Address.

AJW Technique Inc
7055, rue Alexander Fleming
Saint-Laurent QC H4S-2B7
Canada

AJW technique

5. Work Order, Contract or Invoice Number:

U11789-1

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Vacuum System Controller	14404-011-1	1.00	0020117	REPAIRED

12. REMARKS

UNIT CLEANED, REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 38-34-12, REVISION No. 7, DATED MAR 31/1999.
FOR MORE INFORMATION REFER TO MAINTENANCE REPORT.

PRINTED FROM ELECTRONIC FILE

EASA Approval No.: EASA.145.7260
Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

☒ CAR 571.10 Maintenance Release

☒ Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
			33-12
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed)	14e. Date (dd/mmm/yyyy)
		Hassan Boudemlij	26/Jan/2016

Installer Responsibilities

This certficate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
Statements in blocks 13a or 14a do not constitute installation certification. In all cases,the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

AJW technique

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO30665
Date Printed: 26/01/2016
Customer RO: U11789-1
Page: 1

To:
A J WALTER AVIATION LIMITED
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #: **Fax #:** **Email:**

Code: AJW01 **PN:** 14404-011-1 **Serial # :** 0020117 **Qty:** 1

Descr: Vacuum System Controller **Mfg:** APPARATEBAU GAUTING

TSN: N/A **TSO:** N/A **TSR:** N/A **CSN:** N/A **CSO:** N/A **CSR:** N/A

P/N Out: 14404-011-1 **Serial # out:** 0020117

Symptoms:

CODE: TEST AND RECERTIFY

DETAILS: Repair if unit fails.

Faults:

CODE: QUOTE

DETAILS: PRELIMINARY INSPECTION (VISUAL):

PART MISSING:	NO
DAMAGE FOUND (CID):	NO
HRS/CYCLE RECEIVED:	NO

ADDITIONAL REQUIREMENT:

AD, SB, MOD, SIL	NO
ADD.CUST. REQUEST	NO

WARRANTY REQUESTED? NO

TEST ARRIVAL:

INITIAL TEST FAIL? NO

REASON FOR REMOVAL CONFIRMED: UNKNOWN

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION YES

WORK TYPE: REPAIR

WORKSCOPE:

CALIBRATION	NO
CLEANING	YES
OUT OF SCOPE	NO
OVERHAUL	NO
PAINTING	NO

AJW technique
7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO30665
Date Printed: 26/01/2016
Customer RO: U11789-1

PCBR		N/A
REPAIR		YES
REWORK	NO	
TIME CONTROLLED/TX		NO
RE-QUOTE:		NO

CODE: INITIAL TEST FAILURE

DETAILS: Initial test passed, but because unit is dirty, must open unit for inspection.

CODE: CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS: Reason for removal unknown .

CODE: DISASSEMBLY / INSPECTION FINDINGS

DETAILS: During disassembly and inspection of the unit the following anomalies were found:
unit dirty needs cleaning.
and identification labels of EPROM (U203 and U204) are missing.

CODE: CLEANING

DETAILS: Cleaning is required due to external contamination of dirt.

CODE: REPAIR

DETAILS: unit will be repaired in accordance with cmm.

Corrective Actions:

CODE: REPAIRED

DETAILS: UNIT CLEANED, REPAIRED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 38-34-12.