

1. AESA Agencia Estatal de Seguridad Aérea SPAIN / España		2. AUTHORISED RELEASE CERTIFICATE Certificado de Aptitud Autorizado EASA FORM 1		3. FORM TRACKING NUMBER. Num. de seguimiento MI/20650039	
4. ORGANIZATION NAME AND ADDRESS Nombre y Dirección de la Organización IBERIA		ZONAS INDUSTRIALES Nº 1 & 2 BARAJAS 28042 MADRID - SPAIN		5. WORK ORDER / CONTRACT / INVOICE Orden de trabajo / Contrato / Factura 7200617852	
6. ITEM Elemento 1	7. DESCRIPTION Descripción FIRE EXTINGUISHER CONTAINER	8. PART Nº Nº Componente 472931-3	9. QTY Cantidad 1	10. SERIAL No. Nº de serie 0569W	11. STATUS / WORK Estado / Trabajo OVERHAULED
12. REMARKS (Observaciones) WORKS PERFORMED I.A.W. CMM:26-20-84 REV.14 MAY 2019 Customer: SRT RO: 66054609_1 WELDMENT CONTAINER DOM:JAN/06 DOT-SP8495 LAST HTEST (RIN D974):FEB/20 AMDT:NONE. CARTRIDGES P/N:446203 S/N:ADG3472 DOM:JUL/14 EXP. LIFE DATE:JUL/24 P/N:446203 S/N:ADG3455 DOM:JUL/14 EXP. LIFE DATE:JUL/24 COUNTERS ACCORDING TO CUSTOMER R.O. AND WORKS PERFORMED IN IBERIA: TSN:9586 CSN:1217 TSO:0 CSO:0					
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate No. ILAY037F.					
Records of works performed are on file at this Maintenance Organization under Work Order stated in block 5 (Los Registros del trabajo realizado están archivados en esta organización bajo la Orden de Trabajo del bloque 5)					
13a. Certifies that the items identified above were manufactured in conformity to Certifica que los elementos indicados anteriormente se fabricaron de conformidad con: ☐ approved design data and are in condition for safe operation datos de diseño aprobados y están en condiciones de operar con seguridad ☐ non-approved design data specified in block 12 datos de diseño no aprobados especificados en la casilla 12					
13b. AUTHORISED SIGNATURE Firma autorizada		13d. APPROVAL/AUTHORISATION NUMBER Nº de Aprobación/Autorización		14c. CERTIF./APPROV. REF. No. Nº ref. certificado/aprobación ES.145.011	
13c. NAME Nombre		13e. DATE(dd/mm/yyyy) Fecha (dd/mm/yyyy)		14e. DATE (dd/mm/yyyy): Fecha (dd/mm/yyyy)	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs works in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					
RESPONSABILIDADES DEL USUARIO / INSTALADOR Este certificado no autoriza automáticamente a instalar el/los elemento/s. Si el usuario o instalador trabaja con arreglo a la normativa de una autoridad de aeronavegabilidad distinta de la especificada en la casilla 1, es esencial que se asegure de que la autoridad a la cual está sujeta acepta los elementos de la autoridad de aeronavegabilidad especificada en la casilla 1. Las declaraciones 13a y 14a no constituyen certificación de instalación. En todo caso, el registro de mantenimiento de la aeronave debe contener una certificación de instalación expedida por el usuario o instalador en virtud de la normativa nacional antes de poder poner la aeronave en vuelo.					



WORK SHOP REPORT

MAINTENANCE ORGANIZATION EASA PART 145 APPROVAL CERTIFICATE N° ES.145.011		FAA AIR AGENCY CERTIFICATE NUMBER ILAY037F	
IBERIA WORK ORDER	7200617852		
CUSTOMER	SR TECHNICS SWITZERLAND LTD.		
CUSTOMER REPAIR ORDER	66054609_1		
DENOMINATION	FIRE EXTINGUISHER CONTAINER		

INCOMING DATA		OUTGOING DATA	
INCOMING DATE:	11.FEB.2020	OUTGOING DATE:	12.FEB.2020
INCOMING P/N:	472931-3	OUTGOING P/N:	472931-3
INCOMING S/N:	0569W	OUTGOING S/N:	0569W
MOD IN:	NONE	MOD OUT:	NONE
TASK REQUESTED:	Inspected/Tested	STATUS/WORK PERFORMED:	Overhauled
REASON FOR REMOVAL:	Not reported		
CMM NUMBER:	26-20-84 REV.14 MAY 2019		
AIRCRAFT TAIL NUMBER:	OH-LTS		
ENGINE SERIAL NUMBER:	Not reported		
WARRANTY REQUESTED:	NO.	WARRANTY STATUS:	Not applicable
WARRANTY COMMENTS:	Not applicable		

EXTERNAL CONDITION / INCOMING INSPECTION:

Equipment Identification Data	☒ Yes ☐ No
Documentation	☒ Yes ☐ No
Correct config and complete	☒ Yes ☐ No
External misused (Burned, forced,	☐ Yes ☒ No

CORRECTLY PACKED AT INCOMING: YES
TYPICAL SEQUENTIAL TASKS:

Visual Incoming inspection	☒ Yes ☐ No ☐ N/A
Incoming test	☒ Yes ☐ No ☐ N/A
Disassembly	☒ Yes ☐ No ☐ N/A
Cleaning	☒ Yes ☐ No ☐ N/A
NDT Check	☐ Yes ☐ No ☒ N/A
Assembly	☒ Yes ☐ No ☐ N/A
FOD Check inspection	☒ Yes ☐ No ☐ N/A
Final Test	☒ Yes ☐ No ☐ N/A

TYPE OF FAULT:OTHERS - OVERHAUL EXPIRED

<http://www.iberiamaintenance.com>**WORK SHOP REPORT****SHOP FINDINGS AND WORKS PERFORMED:**

SHOP FINDING	WORK PERFORMED
DISASSEMBLY FILL VALVE	IT'S DISASSEMBLED
DISCHARGE	IT'S DISCHARGED
PERFORM HYDROTEST	IT`S PERFORMED HYDROTEST
CHARGE AND VERIFY WEIGHT	IT'S CHARGED
WELD A NEW FILL VALVE	I'TS WELDED
PERFORM FINAL TEST & WEIGHT	FINAL TEST, OK. WEIGHT 118.50 LBS

SERVICE BULLETINS: N/A**PARTS REPLACED:**

QUANTITY	PART NUMBER	MATERIAL DESCRIPTION
2	6355-0906	PACKING
1	446216	FITTING,FILL AND SAFETY
1	262539	GASKET
2	63550024	PACKING

SUBASSYS REPLACED: N/A**REMARKS:**WELDMENT CONTAINER DOM:JAN/06 DOT-SP8495 LAST HTEST (RIN D974):FEB/20
AMDT:NONE.

CARTRIDGES P/N:446203 S/N:ADG3472 DOM:JUL/14 EXP. LIFE DATE:JUL/24

P/N:446203 S/N:ADG3455 DOM:JUL/14 EXP. LIFE DATE:JUL/24

COUNTERS ACCORDING TO CUSTOMER R.O. AND WORKS PERFORMED IN IBERIA:

TSN:9586 CSN:1217 TSO:0 CSO:0

