

1. Approving Competent Authority/Country CAA/UK		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number 0000000000010881668 Page 1 of 1	
4. Organisation Name and Address: UTC Aerospace Systems Wrocław Sp. z o.o. ul. Bierutowska 65-67 51-317 Wrocław				5. Work Order/Contract/Invoice 45903880 R419986	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
01	DF1575 CONVECTION OVEN LH	4315750-00-0000	1	N18080013AA0628	REPAIRED
12. Remarks Work performed in accordance with CMM: 25-35-54 Revision: 09 Date: Sep 12/2023 Sub-component with P/N: 4381500-02-0000 and S/N: P180408140B0379 See attached Teardown Report for more detailed information Excluding SUBTASK 25-35-54-200-003-A01 point 1.g paragraph "Examine the plastic parts for cracks. No cracks on plastic parts are permitted" in agreement with customer					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12			14a. ☒ Part-145 A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service.		
13b. Authorised Signature		13c. Approval / Authorisation Number		14b. Authorised Signature <i>Jakub Radzinski</i> 34/IV	
13d. Name		13e. Date (dd mmm yyyy)		14c. Certificate / Approval Ref. No. UK.145.01524	
				14d. Name JAKUB RADZIMSKI	
				14e. Date (dd mmm yyyy) 22 DEC 2023	
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1. Approving competent Authority/Country Civil Aviation Authority/POLAND		2. AUTHORISED RELEASE CERTIFICATE EASA Form 1		3. Form Tracking Number 000000000010881667 Page 1 of 1	
4. Organisation Name and Address: UTC Aerospace Systems Wrocław Sp. z o.o. ul. Bierutowska 65-67 51-317 Wrocław				5. Work Order/Contract/Invoice 45903880 / R419986	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
01	DF1575 CONVECTION OVEN LH	4315750-00-0000	1	N18080013AA0628	REPAIRED
12. Remarks Work performed in accordance with CMM: 25-35-54 Revision: 09 Date: Sep 12/2023 Sub-component with P/N: 4381500-02-0000 and S/N: P180408140B0379 See attached Teardown Report for more detailed information Excluding SUBTASK 25-35-54-200-003-A01 point 1.g paragraph "Examine the plastic parts for cracks. No cracks on plastic parts are permitted" in agreement with customer					
The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and CAR 573 and in respect to that work, the items are approved for release or return to service under FAA certificate No. 2HWY796C and TCCA Approval No. 815-21.					
13a. Certifies the items identified above were manufactured in conformity to:			14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12		
☐ approved design data and are in a condition for safe operation. ☐ non-approved design data specified in Block 12.			Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part 145 and in respect to that work the items are considered ready to release for service.		
13b. Authorised Signature		13c. Approval / Authorisation Number		14c. Certificate / Approval Ref No. PL.145.010	
					
13d. Name		13e. Date (dd mmm yyyy)		14e. Date (dd mmm yyyy): 22 DEC 2023	
				JAKUB RADZIMSKI	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

TEARDOWN REPORT

UTC Aerospace System Sp. z o.o. – MRO
Customer Service Plant
ul. Kielczowska 74
PL-51-315 WROCLAW



UTC Aerospace Systems

Customer A J WALTER AVIATION		Cust PO	R419986	Operator PO	
Input Part	4315750-00-0000	Input Serial	N18080013AA0628	Qty	1.000
Output Part	4315750-00-0000	Output Serial	N18080013AA0628	Workscope	MNR REPAIR
Cust Part		Cust Serial	N18080013AA0628	Status/Work	REPAIRED
Description	DF1575 CONVECTION OVEN LH	Removal Code	IRAN REPAIR	Failure Date	
Aircraft		Engine Type			
Incoming NSN	N/A	Outgoing NSN	N/A	Tail No	EI-LRC
Date Rec'd	14.11.2023	Quote Date	16.11.2023	Accept Date	01.12.2023
Ship Date		DOM	01.08.2018	Last Order Date	14.09.2023
Sales Order	121104385	Work Order	45903880	Notification	305466363

Evaluation Inspection

REMOVAL REASON: REPAIR
EPAIR FAILURE VERIFIED: YES
FAILURE REASON: CID
TYPE OF WORK: MINOR REPAIR

frame is cracked, will be replaced
Door seal is missing

Cracks on parts mentioned below are not allowed in accordance with CMM,
but does
not affect correct operation of the unit therefore parts are not included
in quotation
and will be added upon customer request:
-OUTER COVER DF1575 PN 431507041

special procedure:
reattach plug

Warranty evaluation process has been completed. Warranty has not been
granted. No failure found in workmanship or materials related to previous
shop visit.

Components :

Order	Material	Description	Req Qty	Issued	Reason Code	Stor Loc
45903880	431509010	SEAL, DOOR	1	1	MISSING/CID	OVBE
45903880	431506022	FRAME, DF15XX LH ASSEMBLY COAT	1	1	CRACKED/CID	OVBE