

1. Approving Competent Authority / Country LUFTFAHRT-BUNDESAMT Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1				3. Form Tracking Number DB 90539484 1/1	
4. Organisation Name and Address:		 AIRBUS Operations GmbH Lüneburger Schanze 30 21614 Buxtehude, Germany				5. Work Order/Contract/Invoice W36851	
6. Item	7. Description	8. Part No.	9. Qty	10. Serial-No.	11. Status/Work		
N/A	CIDS AFT.ATTND.PNL.	Z120H0040110	1	120H00007797	REPAIRED		
12. Remarks:		The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. K30Y905Y.					
13a Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in block 12		14a. ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature:		13c. Approval/Authorisation Number:		14b. Authorised Signature: 		14c. Certificate/Approval Ref.No.: DE.145.0286	
13d. Name:		13e. Date (dd/mm/yyyy):		14d. Name: Zeigermann		14e. Date (dd/mm/yyyy): 05.Dec.2016	
USER / INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

1 国家 Country		2. 中国民用航空总局 CAAC ☐ 符合性 Conformity ☒ 适航性 Airworthiness			3 证书编号 Certificate Ref. No.	
China		批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG			DB 90539483	
4 单位 Organization		AIRBUS Operations GmbH Cabin Electronics Lüneburger Schanze 30 21614 Buxtehude, Germany		Plant Werk	5 工作单/合同单/货单 Work Order/Contract/Invoice W36851	
6 序号 Item		7 内容 Description		8 件号 Part No.	9 适用性 Eligibility	10 数量 Qty
0001		CIDS AFT.ATTND.PNL.		Z120H0040110	A320	1
						11 系列号/批号 Serial/Batch No.
						12 产品状态 Status/Work
						REPAIRED
13 备注 Remarks						
see Maintenance Report No.1033680 Work performed as per: C.M.M. 23-73-13 Rev. 16 JAN-12-2016 work accomplished: DEC-01-2016 Amendment:B						
14 新产品 New Parts						
兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例进行制造/检查，并且该 产品，在出口产品，符合经批准的型号设计资料进口国提出的专用要求。 Certifies that the Part(s) identified above except as otherwise specified in block 13 was(were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.						
15 使用过的产品 Used Parts		兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例和进口国 通知的特殊要求进行了工作，该产品处于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)				
16 批准人签名 Signature		18 批准日期 Date		19 中国民航总局授权 Issued by or on behalf of the CAAC		
Zeigermann DA_K_3		05.Dec.2016		F049000446		
17 批准人姓名 (打印的) Name(Printed)						

*参阅产品目录详细查找适用性
Cross-check eligibility for more details with parts catalogue

MAINTENANCE ORDER		V Activity Category		1033680 Maintenance Number		 AIRBUS FSCM C9072	
Customer AJW	Part Number Z120H0040110			Serial No SPEC2000 120H00007797		Amd. B	
	Description CIDS AFT.ATTND.PNL.			Quantity 1		Repair-Station BUX	
Customer Order W36851		Cust. Order Date 18.11.2016		Work Order 1033680		Work Order Date 28.11.2016	
Required Activities:		Test X	Repair X	Modify	Inspection X	Scrap	Overhaul
						Entry Date 24.11.2016	Redelivery Date 30.11.2016
Reason for Return INTERMITTENT							
Operator UKN	Removal Date	AC-Reg YL-LCR	AC Type A320	Station UKN	Release Certificate AAC038/EDUAL	Warranty X	Chargeable
		Operators Man	OEM-Man O.E.M.-M	Aviation Device YES		Package OK	
Administrator: Seckerdieck		Department: ECYS1			Phone: (0)40 743 54998		

MAINTENANCE REPORT	Preliminary Inspection/HDI	Pre- Strip-Test YES	Cond. elec. BAD	Cond. SW OK	Cond. mech. OK	BITE N/A
	Status of Removal Confirmed Removal		Tech. warranty YES		Missing Part NO	
Findings: The AAP was found sporadically inoperative because the ribbon cable between the Keyboard Z120H2305110 and the connector J2 on the Microcomputer-Board Z120H2200110 C was not properly inserted into the connector J2. Note: We found some scratches on the cover frame but w/o any impacts on the AAPs` functional performance!						
Remarks: Work performed as per: C.M.M. 23-73-13 Rev. 16 JAN-12-2016						
Work performed: Preliminary- and hidden damage inspection performed. Ribbon cable reinserted into connector J2 on the Microcomputer-Board Z120H2200110 C. Acceptance test successfully performed. 						
Final Condition	PN_After Z120H0040110		SN_After 120H00007797		AMD_After B	
	Tested X	Repaired X	Modified	Modified internal	Cond as is	Scrapped
	Warranty_Charge_WC W		NFF		QA-Inspected	
Work performed staff Bredow		Work performed department ECYS3		Work performed date 01.12.2016		05. Dez. 2016 