

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: W518611786031	
4. Organization Name and Address: General MRO Aerospace, Inc. 10990 NW 92nd Terrace MIAMI, FL 33178 Ph: 305-482-9903, Fax: 305-482-9905 sales@generalmroaerospace.com FAA Approval Holder: 19GR994Y				5. Work Order, Contract or Invoice Number: R391499	
16. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	ACTUATOR	764711C	1	0845	OVERHAULED
12. REMARKS: Full details describing the actual work performed are contained and held in W/O # W51861. This unit was Overhauled in accordance with: MFG: UTC AEROSPACE SYSTEM ATA Manual ID: 29-21-03, Revision #: 14, Revision Date: 3/30/2022 Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA.145.6095". Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Authorized Signature:		13c. Approval Authorization No:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: 	
				14c. Approval Certificate No: 19GR994Y	
				14d. Name (Typed or Printed): Eduardo Morales	
				14e. Date (dd/mm/yyyy): 30/Jun/2022	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



General MRO Aerospace
10990 NW 92nd Terrace
MIAMI, FL 33178
Ph: 305-482-9903, Fax: 305-482-9905
sales@generalmroaerospace.com

Teardown

Work Order #: W51861

Date Printed: 6/30/2022

Time: 6:00:01 PM

Page: 1

To:
AJW AVIATION LTD
VISCOUNT HOUSE WEST SUSSEX
Sussex, UK RH13 8RA

Ship To:
AJW AVIATION LTD
AJ WALTER AVIATION LTD
The Headquarters
Maydwell Avenue
West Sussex, Slinfold RH13 0AS
UNITED KINGDOM

Ref #: R391499

Phone #: 441403711777

Fax #: 441403710936

Email: ilsenquiries@ajw-group.com

Code: 165

Site: 2SM

PN: 764711C

Descr: ACTUATOR

Qty: 1

Make:

Model:

Mfg: UTC AEROSPACE S

Serial Number: 0845

Entry Date: 2/16/2022

Need Date:

Compl. Date: 6/30/2022 4:51

Warranty: No

Container:

ATA: 29-21-03 Loc: 3485 Revision: 14 Rev Date: 3/30/2022

REMARKS

SUBCOMPONENT PN AND SN

Deploy Solenoid QTY 2	Switch assy	Pressure Switch	Solenoid
PN 1211523-235	PN 1211523-274	PN 121523-239	PN 1211523-238
SN 23544	SN 2023	SN 2580	SN GI022
SN 23129			

REASON FOR REMOVAL

NONE GIVEN

PRELIMINARY INSPECTION

Verified PN and SN from RO and Unit

PRE TEST

UNIT WAS TESTED AND PASSED ALL FUNCTIONAL TEST.

HIDDEN DAMAGE

No hidden damage reported

TEARDOWN FINDINGS

During inspection the following discrepancies were found:

Maintenance Release Statement (FAR Pars 121, 125 and 135)

The instruments and or Components above was Serviced and Inspected with Pride and in accordance with current F.A.A. Regulations and is
[X] Approved | [] Not approved to Return to Service. Pertinent details of the Services are on files at this Repair Station.

Name:

Authorized Signature:

Date:

6/30/2022

Eduardo Morales

Form created with Quantum Control(tm) technology. Product Licensed to: General MRO Aerospace



General MRO Aerospace
10990 NW 92nd Terrace
MIAMI, FL 33178
Ph: 305-482-9903, Fax: 305-482-9905
sales@generalmroaerospace.com

Teardown

Work Order #: W51861

Date Printed: 6/30/2022

Time: 6:00:02 PM

Page: 2

To:
AJW AVIATION LTD
VISCOUNT HOUSE WEST SUSSEX
Sussex, UK RH13 8RA

Ship To:
AJW AVIATION LTD
AJ WALTER AVIATION LTD
The Headquarters
Maydwell Avenue
West Sussex, Slinfold RH13 0AS
UNITED KINGDOM

Ref #: R391499 Phone #: 441403711777 Fax #: 441403710936 Email: ilsenquiries@ajw-group.com
Code: 165 Site: 2SM PN: 764711C Descr: ACTUATOR
Qty: 1 Make: Model: Mfg: UTC AEROSPACE S

Serial Number: 0845

Entry Date: 2/16/2022 Need Date: Compl. Date: 6/30/2022 4:51 Warranty: No Container:

ATA: 29-21-03 Loc: 3485 Revision: 14 Rev Date: 3/30/2022

Unit was cleaned, tested, and inspected. Unit passed all functional tests. Unit was fully disassembled for further inspection. Upon inspection found damaged toggle retainer. Unit requires all mentioned parts. 100% Kit, deep cleaning, NDT and reconditioning for Overhaul.

Discrepancies Noted:

1. Damaged toggle retainer - Requires replacement.

Rework Required:

1. Deep cleaning.
2. NDT.
3. Reconditioning.

***** Quoted for Overhaul *****

Technician: Javier Martinez Inspector: Jsosa Date: 05/19/2022

AD/SERVICE BULLETINS/MODIFICATIONS

No ADs applicable to this component.

WORK PERFORMED

Performed replacement of all mentioned parts, deep cleaning, NDT, assembly and testing. Unit passed all functional tests. Performed final reconditioning. Unit has been Overhauled IAW HAMILTON SUNDSTRAND CORP CMM ATA 29-21-03 Rev 14 DTD March 30, 2022.

Maintenance Release Statement (FAR Pars 121, 125 and 135)

The instruments and/or Components above was Serviced and Inspected with Pride and in accordance with current F.A.A. Regulations and is
[X] Approved [] Not approved to Return to Service. Pertinent details of the Services are on files at this Repair Station.

Name:

Eduardo Morales

Authorized Signature:

Date: 6/30/2022